

PARAMETER LIST

for

**MAZATROL FUSION 640MT/MT 5X
MAZATROL FUSION 640T/TE
MAZATROL FUSION 640T NEXUS/TN**

MANUAL No. : H734SA0033E

Serial No. :

Before using this machine and equipment, fully understand the contents of this manual to ensure proper operation. Should any questions arise, please ask the nearest Technical/Service Center.

IMPORTANT NOTICE

1. Be sure to observe the safety precautions described in this manual and the contents of the safety plates on the machine and equipment. Failure may cause serious personal injury or material damage. Please replace any missing safety plates as soon as possible.
2. No modifications are to be performed that will affect operation safety. If such modifications are required, please contact the nearest Technical/Service Center.
3. For the purpose of explaining the operation of the machine and equipment, some illustrations may not include safety features such as covers, doors, etc. Before operation, make sure all such items are in place.
4. This manual was considered complete and accurate at the time of publication, however, due to our desire to constantly improve the quality and specification of all our products, it is subject to change or modification. If you have any questions, please contact the nearest Technical/Service Center.
5. Always keep this manual near the machinery for immediate use.
6. If a new manual is required, please order from the nearest Technical/Service Center with the manual No. or the machine name, serial No. and manual name.

Issued by *Manual Publication Section, Yamazaki Mazak Corporation, Japan*

SAFETY PRECAUTIONS

Preface

Safety precautions relating to the CNC unit (in the remainder of this manual, referred to simply as the NC unit) that is provided in this machine are explained below. Not only the persons who create programs, but also those who operate the machine must thoroughly understand the contents of this manual to ensure safe operation of the machine.

Read all these safety precautions, even if your NC model does not have the corresponding functions or optional units and a part of the precautions do not apply.

Rule

1. This section contains the precautions to be observed as to the working methods and states usually expected. Of course, however, unexpected operations and/or unexpected working states may take place at the user site.
During daily operation of the machine, therefore, the user must pay extra careful attention to its own working safety as well as to observe the precautions described below.
2. Although this manual contains as great an amount of information as it can, since it is not rare for the user to perform the operations that overstep the manufacturer-assumed ones, not all of “what the user cannot perform” or “what the user must not perform” can be fully covered in this manual with all such operations taken into consideration beforehand.
It is to be understood, therefore, that functions not clearly written as “executable” are “inexecutable” functions.
3. The meanings of our safety precautions to DANGER, WARNING, and CAUTION are as follows:



DANGER

: Failure to follow these instructions could result in loss of life.



WARNING

: Failure to observe these instructions could result in serious harm to a human life or body.



CAUTION

: Failure to observe these instructions could result in minor injuries or serious machine damage.

Basics



WARNING

- After turning power on, keep hands away from the keys, buttons, or switches of the operating panel until an initial display has been made.
- Before proceeding to the next operations, fully check that correct data has been entered and/or set. If the operator performs operations without being aware of data errors, unexpected operation of the machine will result.
- Before machining workpieces, perform operational tests and make sure that the machine operates correctly. No workpieces must be machined without confirmation of normal operation. Closely check the accuracy of programs by executing override, single-block, and other functions or by operating the machine at no load. Also, fully utilize tool path check, solid check, and other functions, if provided.
- Make sure that the appropriate feed rate and rotational speed are designated for the particular machining requirements. Always understand that since the maximum usable feed rate and rotational speed are determined by the specifications of the tool to be used, those of the workpiece to be machined, and various other factors, actual capabilities differ from the machine specifications listed in this manual. If an inappropriate feed rate or rotational speed is designated, the workpiece or the tool may abruptly move out from the machine.
- Before executing correction functions, fully check that the direction and amount of correction are correct. Unexpected operation of the machine will result if a correction function is executed without its thorough understanding.
- Parameters are set to the optimum standard machining conditions prior to shipping of the machine from the factory. In principle, these settings should not be modified. If it becomes absolutely necessary to modify the settings, perform modifications only after thoroughly understanding the functions of the corresponding parameters. Modifications usually affect any program. Unexpected operation of the machine will result if the settings are modified without a thorough understanding.

Remarks on the cutting conditions recommended by the NC



WARNING

- Before using the following cutting conditions:
 - Cutting conditions that are the result of the MAZATROL Automatic Cutting Conditions Determination Function
 - Cutting conditions suggested by the Machining Navigation Function
 - Cutting conditions for tools that are suggested to be used by the Machining Navigation Function
- Confirm that every necessary precaution in regards to safe machine setup has been taken – especially for workpiece fixturing/clamping and tool setup.
- Confirm that the machine door is securely closed before starting machining. Failure to confirm safe machine setup may result in serious injury or death.

Programming



- Fully check that the settings of the coordinate systems are correct. Even if the designated program data is correct, errors in the system settings may cause the machine to operate in unexpected places and the workpiece to abruptly move out from the machine in the event of contact with the tool.
- During surface velocity hold control, as the current workpiece coordinates of the surface velocity hold control axes approach zeroes, the spindle speed increases significantly. For the lathe, the workpiece may even come off if the chucking force decreases. Safety speed limits must therefore be observed when designating spindle speeds.
- Even after inch/metric system selection, the units of the programs, tool information, or parameters that have been registered until that time are not converted. Fully check these data units before operating the machine. If the machine is operated without checks being performed, even existing correct programs may cause the machine to operate differently from the way it did before.
- If a program is executed that includes the absolute data commands and relative data commands taken in the reverse of their original meaning, totally unexpected operation of the machine will result. Recheck the command scheme before executing programs.
- If an incorrect plane selection command is issued for a machine action such as arc interpolation or fixed-cycle machining, the tool may collide with the workpiece or part of the machine since the motions of the control axes assumed and those of actual ones will be interchanged. (This precaution applies only to NC units provided with EIA functions.)
- The mirror image, if made valid, changes subsequent machine actions significantly. Use the mirror image function only after thoroughly understanding the above. (This precaution applies only to NC units provided with EIA functions.)
- If machine coordinate system commands or reference position returning commands are issued with a correction function remaining made valid, correction may become invalid temporarily. If this is not thoroughly understood, the machine may appear as if it would operate against the expectations of the operator. Execute the above commands only after making the corresponding correction function invalid. (This precaution applies only to NC units provided with EIA functions.)
- The barrier function performs interference checks based on designated tool data. Enter the tool information that matches the tools to be actually used. Otherwise, the barrier function will not work correctly. (This precaution applies only to the M640MT/MT 5X/T/T NEXUS/TN and M640M Pro/MT Pro.)
- The system of G-code and M-code commands differs between the machines equipped with M640M Pro (e-Series such as the INTGEREX e-410, e-650 and e-1060) and the machines equipped with M640MT/MT 5X/T/T NEXUS/TN/MT Pro (such as the INTGEREX non e-Series, the SQT Series, the MPX Series and the QTN Series).
Issuance of the wrong G-code or M-code command results in totally non-intended machine operation. Thoroughly understand the system of G-code and M-code commands before using this system.

Sample program	Machine with M640M Pro	Machine with M640MT/MT 5X/T/T NEXUS/TN/MT Pro
S1000M3	The milling spindle rotates at 1000 min ⁻¹ .	The turning spindle rotates at 1000 min ⁻¹ .
S1000M203	The turning spindle rotates at 1000 min ⁻¹ .	The milling spindle rotates at 1000 min ⁻¹ .

- For the machines equipped with M640M Pro (e-Series such as the INTGEREX e-410, e-650 and e-1060), programmed coordinates can be rotated using an index unit of the MAZATROL program and a G68 command (coordinate rotate command) of the EIA program. However, for example, when the B-axis is rotated through 180 degrees around the Y-axis to implement machining with the turning spindle No. 2, the plus side of the X-axis in the programmed coordinate system faces downward and if the program is created ignoring this fact, the resulting movement of the tool to unexpected positions may incite collisions.

To create the program with the plus side of the X-axis oriented in an upward direction, use the mirror function of the WPC shift unit or the mirror imaging function of G-code command (G50.1, G51.1).

- After modifying the tool data specified in the program, be sure to perform the tool path check function, the solid check function, and other functions, and confirm that the program operates properly. The modification of tool data may cause even a field-proven machining program to change in operational status.

If the user operates the machine without being aware of any changes in program status, interference with the workpiece could arise from unexpected operation.

For example, if the cutting edge of the tool during the start of automatic operation is present inside the clearance-including blank (unmachined workpiece) specified in the common unit of the MAZATROL program, care is required since the tool will directly move from that position to the approach point because of no obstructions being judged to be present on this path.

For this reason, before starting automatic operation, make sure that the cutting edge of the tool during the start of automatic operation is present outside the clearance-including workpiece specified in the common unit of the MAZATROL program.



- If axis-by-axis independent positioning is selected and simultaneously rapid feed selected for each axis, movements to the ending point will not usually become linear. Before using these functions, therefore, make sure that no obstructions are present on the path.
- If the machine employs sliding surface structure, lubrication may prove to be insufficient during continuous microfeed machining (see Note 1 below), and in the worst case, seizure of the sliding surface could result. For these reasons, the sliding surface needs to be maintained in a well-lubricated condition during such machining by, for example, inserting an oil-film forming program (see Note 2 below).

List of applicable models and intended axes (Models that employ sliding surface structure)

Classification	Machine model	Axes with sliding surface structure
Lathes	INTEGREX 50Y	X-axis, Y-axis, Z-axis
	INTEGREX 50YB	X-axis, Y-axis, Z-axis
	INTEGREX 70Y	X-axis, Y-axis, Z-axis
	INTEGREX 70YB	X-axis, Y-axis, Z-axis
	SLANT TURN 450	X-axis, Z-axis
	SLANT TURN 50N	X-axis, Z-axis
	SLANT TURN 60N	X-axis, Z-axis
	SLANT TURN 80N	X-axis, Z-axis
	TURNING CENTER M-4N	X-axis, Z-axis
	TURNING CENTER M-5N	X-axis, Z-axis
	POWER MASTER	X-axis, Z-axis
	QUICK TURN 40	X-axis, Z-axis
	MEGA TURN series	X-axis, Z-axis
	SUPER QUADREX 200/250	Z2-axis
	SUPER QUICK TURN 200/250MY	Y-axis
SUPER QUICK TURN 300MY	Y-axis	
Vertical machining centers	FJV-35/50/60	Z-axis
	MTV-515/655/815	Z-axis
	V-40/60	Z-axis

For further details and more specific examples, refer to the relevant Machine Operating Manual, Part 4, Section 1-2, "Precautions for Microfeed Machining (Models that Employ Sliding Surface Structure)".

- Note 1:** Continuous microfeed machining refers to the operation in which the movement of the intended feed axis through strokes shorter than those required for lubrication is continuously repeated.
- Note 2:** The oil-film forming program refers to a program that creates an oil film on the sliding surface by moving the intended machining axis over a long stroke during machining.

Operations



WARNING

- Single-block, feed hold, and override functions can be made invalid using system variables #3003 and #3004. Execution of this means the important modification that makes the corresponding operations invalid. Before using these variables, therefore, give thorough notification to related persons. Also, the operator must check the settings of the system variables before starting the above operations.
- If manual intervention during automatic operation, machine locking, the mirror image function, or other functions are executed, the workpiece coordinate systems will usually be shifted. When making machine restart after manual intervention, machine locking, the mirror image function, or other functions, consider the resulting amounts of shift and take the appropriate measures. If operation is restarted without any appropriate measures being taken, collision with the tool or workpiece may occur.
- Use the dry run function to check the machine for normal operation at no load. Since the feed rate at this time becomes a dry run rate different from the program-designated feed rate, the axes may move at a feed rate higher than the programmed value.
- After operation has been stopped temporarily and insertion, deletion, updating, or other commands executed for the active program, unexpected operation of the machine may result if that program is restarted. No such commands should, in principle, be issued for the active program.



CAUTION

- During manual operation, fully check the directions and speeds of axial movement.
- For a machine that requires manual homing, perform manual homing operations after turning power on. Since the software-controlled stroke limits will remain ineffective until manual homing is completed, the machine will not stop even if it oversteps the limit area. As a result, serious machine damage will result.
- Do not designate an incorrect pulse multiplier when performing manual pulse handle feed operations. If the multiplier is set to 100 times and the handle operated inadvertently, axial movement will become faster than that expected.

OPERATIONAL WARRANTY FOR THE NC UNIT

The warranty of the manufacturer does not cover any trouble arising if the NC unit is used for its non-intended purpose. Take notice of this when operating the unit.

Examples of the trouble arising if the NC unit is used for its non-intended purpose are listed below.

1. Trouble associated with and caused by the use of any commercially available software products (including user-created ones)
2. Trouble associated with and caused by the use of any Windows operating systems
3. Trouble associated with and caused by the use of any commercially available computer equipment

Operating Environment

1. Ambient temperature

During machine operation: 5° to 40°C (41° to 104°F)

Note: When power is turned on, if the thermal sensor detects an ambient temperature under 5°C, the hard disk warm-up status indicator lamp will light up and the NC unit will not start operating at once. After automatic heating of the hard disk by its internal heater, the lamp will go out and the NC unit will start. It takes about 20 minutes for temperature to increase from 0 to 5°C in order to avoid condensation due to sudden changes in temperature.

2. Relative humidity

During machine operation: 30 to 75 % (without bedewing)

Note: As humidity increases, insulation deteriorates causing electrical component parts to deteriorate quickly.

- NOTE -

CONTENTS

	Page
1 PREFACE	1-1
2 PARAMETER LIST.....	2-1
2-1 USER PARAMETER	2-1
2-2 MACHINE PARAMETER.....	2-23
2-3 DATA INPUT/OUTPUT PARAMETER	2-33
3 PARAMETER	3-1
3-1 How to Use Parameter List.....	3-1
3-2 PARAMETER (USER, CUTTING P).....	3-3
3-3 PARAMETER (USER, CUTTING K).....	3-54
3-4 PARAMETER (USER, CUTTING U)	3-74
3-5 PARAMETER (USER, POINT D)	3-99
3-6 PARAMETER (USER, LINE E)	3-113
3-7 PARAMETER (MACHINE, CONTROL A)	3-121
3-8 PARAMETER (MACHINE, MACHINE B)	3-131
3-9 DATA I/O CMT PARAM.....	3-167
3-10 DATA I/O PARAM.	3-169
3-11 DATA I/O DNC PARAM.....	3-179
3-12 DATA I/O EXTENDED PARAMETER	3-189

- NOTE -

1 PREFACE

1. Scope of this manual

This manual gives the parameters you can change as required. How to read the manual is described in the beginning of the list. Always refer to the manual to change parameters.

2. Precautions on this manual

This manual is written to be adaptable to all the NC units and also gives parameters relating to optional functions. Accordingly, the manual includes parameters which can not be changed. Check the type of NC turning machine purchased by you and its specifications before you read the manual.

* The contents of this manual are subjected to change without notice, for NC unit or machine improvement.

* Any questions about the contents of this manual should be communicated to a nearby TC (technical center) or SC (service center) of YAMAZAKI MAZAK.

- NOTE -

2 PARAMETER LIST

2-1 USER PARAMETER

Note: M: Valid only for MAZATROL Program
E: Valid only for EIA/ISO Program

Address	Outline	Unit	Effective condition	Applicable program (Note)
P1 (bit 0)	Use/disuse of acceleration in up-going slope during rough cutting cycle in bar machining unit	–	Instant	M
P1 (bit 1)	Use/disuse of deceleration in down-going slope during rough cutting cycle in bar machining unit	–	Instant	M
P1 (bit 2)				
P1 (bit 3)	Selection between use/disuse of acceleration distance check at start of thread cutting unit	–	Instant	M
P1 (bit 4)	Selection for thread number offset	–	Instant	M
P1 (bit 5)	Selection between whether or not tool should be returned to tool change position on M code unit end	–	Instant	M
P1 (bit 6)	Selection of whether the spindle is to be stopped following completion of the END unit	–	Instant	M
P1 (bit 7)	Selection between whether or not tool should be returned to tool change position before repetition of same program	–	Instant	M
P2 (bit 0)	Selection for cutting path method in milling line machining unit	–	Instant	M
P2 (bit 1)	Output/no output of spindle rotation command during manual program machining unit	–	Instant	M
P2 (bit 2)	Return/no return to the tool change position upon issuance of T-command with the same TNo. but followed by a different suffix	–	Instant	M
P2 (bit 3)				
P2 (bit 4)	Selection of whether the position of fixed point is to be shifted by an amount of A13	–	Instant	M
P2 (bit 5)	Selection of whether the position of fixed point is to be shifted in the direction of the B-axis by an amount of A13	–	Instant	M
P2 (bit 6)	Selection of an angle margin for nose shape compensation	–	Instant	M
P2 (bit 7)	Selection of an angle margin for nose shape compensation	–	Instant	M
P3 (bit 0)	Use/disuse of Z offset check	–	Instant	M
P3 (bit 1)	Axis designation for TPS operation	–	Instant	M, E
P3 (bit 2)	Return/no return to the tool change position upon issuance of T-command with the same TNo. but followed by a different suffix	–	Instant	M
P3 (bit 3)	Selection of whether the Y-axial return to zero point is to be executed at the start of a MAZATROL program	–	Instant	M
P3 (bit 4)	Selection of the method for approach/escape during mill-line center machining	–	Instant	M
P3 (bit 5)	Data auto-setting method selection for TAP/MTP (pipe tapping)	–	Instant	M

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
P3 (bit 6)				
P3 (bit 7)	Selection of G1 or G0 as the axial relief feed mode for linear machining	–	Instant	M
P4 (bit 0)				
P4 (bit 1)	Selection of display type of tapping tool in solid mode	–	Instant	M
P4 (bit 2)				
P4 (bit 3)				
P4 (bit 4)				
P4 (bit 5)				
P4 (bit 6)				
P4 (bit 7)				
P5 (bit 0)				
P5 (bit 1)				
P5 (bit 2)				
P5 (bit 3)	Spindle synchronizing pattern	–	Instant	M
P5 (bit 4)				
P5 (bit 5)				
P5 (bit 6)				
P5 (bit 7)				
P6 (bit 0)	Selection of whether immediate indexing of the automatically selected spare tool is to be made valid or invalid	–	Instant	M, E
P6 (bit 1)	Selection of the order of spare tool selection	–	Instant	M, E
P6 (bit 2)	Tool offset type selection	–	Power OFF → ON	M, E
P6 (bit 3)				
P6 (bit 4)	Counting all the tools with the same tool number for tool life management on the TOOL DATA display executed/not executed.	–	Instant	M, E
P6 (bit 5)	Name/ID No. selection on the TOOL DATA display	–	Instant	M, E
P6 (bit 6)				
P6 (bit 7)	VISUAL TOOL MANAGER display valid/invalid	–	Instant	M

Address	Outline	Unit	Effective condition	Applicable program (Note)
P7 (bit 0)				
P7 (bit 1)	Selection of a shape-drawing position for milling	–	Instant	M
P7 (bit 2)	Input digit quantity selection of infeed point coordinate	–	Instant	M
P7 (bit 3)	Selection of conditions capable of setting tool data	–	Instant	M, E
P7 (bit 4)	JAW SHAPE display name/code selection	–	Instant	M, E
P7 (bit 5)				
P7 (bit 6)				
P7 (bit 7)				
P8 (bit 0)				
P8 (bit 1)				
P8 (bit 2)				
P8 (bit 3)	Tool nose position storage function valid/invalid on the TOOL OFFSET display	–	Instant	M, E
P8 (bit 4)				
P8 (bit 5)				
P8 (bit 6)				
P8 (bit 7)	Selection of use/disuse of tool identification code skip function	–	Instant	M
P9 (bit 0)	Command data execution as it is/at 10 times	–	Instant	E
P9 (bit 1)				
P9 (bit 2)	Selection of G-code series A	–	Instant	E
P9 (bit 3)	Selection of G-code series B	–	Instant	E
P9 (bit 4)				
P9 (bit 5)	Selection of the command type without decimal point	–	Instant	E
P9 (bit 6)	Selection of rapid traverse interpolation method	–	Instant	E
P9 (bit 7)	Address E specification in precision thread cutting command	–	Instant	E
P10 (bit 0)	Selection of whether short-cutting is to be executed during circular milling (CIR)	–	Instant	M
P10 (bit 1)	Selection of whether short-cutting is to be executed during chamfering	–	Instant	M

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
P10 (bit 2)	Selection of whether or not dwell command should be specified in time	—	Instant	E
P10 (bit 3)	Tool compensation amount selection for EIA/ISO programs	—	Instant	E
P10 (bit 4)	Selection of T command digit length	—	Instant	E
P10 (bit 5)	Use/disuse of interruption prevention function	—	Instant	E
P10 (bit 6)	Selection of return method during deep hole drilling cycle	—	Instant	E
P10 (bit 7)	Selection of tool return position at the end of drilling cycle	—	Instant	E
P11 (bit 0)	Selection of initial G96 (allowed only in G code series A)	—	Instant	E
P11 (bit 1)	Selection of initial G99 (allowed only in G code series A)	—	Instant	E
P11 (bit 2)	Selection of initial G90 (allowed only in G code series B and C)	—	Instant	E
P11 (bit 3)				
P11 (bit 4)	Use/disuse of high speed processing function during machine lock	—	Instant	E
P11 (bit 5)	Selection between whether or not intermediate point should be ignored during execution of reference return command	—	Instant	E
P11 (bit 6)	Selection of whether the machine is to be brought to a macro single-block stop	—	Instant	E
P11 (bit 7)	Absolute/incremental axis name selection	—	Instant	E
P12 (bit 0)	Selection of positioning method during fixed cycle	—	Instant	E
P12 (bit 1)	Selection of whether or not G50 is used during G53 mode	—	Instant	E
P12 (bit 2)	Selection of initial G53	—	Instant	E
P12 (bit 3)	Selection of initial G00	—	Instant	E
P12 (bit 4)				
P12 (bit 5)	Selection of M code output at bottom during tapping cycle	—	Instant	E
P12 (bit 6)	Selection of the operation occurring during the control of the tool tip point when command G49 is issued (when the tool length offset value is canceled)	—	Instant	E
P12 (bit 7)	Selection of coordinate system type for controlling the tool tip point	—	Instant	E
P13 (bit 0)	Use/disuse of compensation movement during T command	—	Instant	E
P13 (bit 1)	Use/disuse of block stop after restart	—	Instant	E
P13 (bit 2)	Use/disuse of automatic return on resuming program	—	Instant	E

Address	Outline	Unit	Effective condition	Applicable program (Note)
P13 (bit 3)	Use/disuse of G00 dry run	–	Instant	M, E
P13 (bit 4)	Use/disuse of dry run during thread cutting	–	Instant	M, E
P13 (bit 5)	Use/disuse of feed hold during thread cutting	–	Instant	E
P13 (bit 6)				
P13 (bit 7)	Use/disuse of reverse rotation error prevention function during G46 mode	–	Instant	E
P14 (bit 0)				
P14 (bit 1)				
P14 (bit 2)				
P14 (bit 3)				
P14 (bit 4)	Whether the workpiece barriers are to be activated	–	Instant	M
P14 (bit 5)	Nose R compensation change-over	–	Instant	E
P14 (bit 6)	Selection as to handling of leading zeros in the DPRNT command mode	–	Instant	E
P14 (bit 7)	Selection of a method of updating data during automatic nose measurement (for EIA)	–	Instant	E
P15 (bit 0)	Overriding valid/invalid of the return speed during a synchronous tapping (parameter K70)	–	Instant	E
P15 (bit 1)	Simplified wear offsetting valid/invalid	–	Instant	M, E
P15 (bit 2)	Method of entering tool position offset data in X-axis direction	–	Instant	E
P15 (bit 3)	Selection of the minimum data unit for secondary auxiliary functions	–	Instant	E
P15 (bit 4)	Address selection for direct input of chamfered corner R curved surface dimensions	–	Instant	E
P15 (bit 5)	Selection of whether tool shape offsetting is to be cancelled with offset number 0	–	Instant	E
P15 (bit 6)	Selection of a tool shape offsetting method	–	Instant	E
P15 (bit 7)				
P16 (bit 0)	Use/disuse of in-position check	–	Instant	M, E
P16 (bit 1)	Automatic setting of target data for nose measurement	–	Instant	E
P16 (bit 2)	Whether reading/writing of system variables is to be executed during tool pass check	–	Instant	E
P16 (bit 3)	EIA format selection	–	Instant	E
P16 (bit 4)	Macro interrupt valid/invalid	–	Instant	E

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
P16 (bit 5)	Selection of the type of interrupt program call for macro interruption	–	Instant	E
P16 (bit 6)	Whether local variables are to be cleared by resetting	–	Instant	E
P16 (bit 7)	Whether common variables are to be cleared by resetting	–	Instant	E
P17	Selection of tool change position specification code	–	Instant	M
P18	Selection of spare tool indexing condition	–	Instant	M, E
P19	Selection of data unit system mm/inch/highly accurate inch	–	Power OFF → ON	M, E
P20	Measurement retry frequency in C offset measurement process	Times	Instant	M
P21	Selection of separating ratio of GRAPHIC display	–	Instant	M, E
P22	Tool command time for tool path	0.05 sec	Instant	M
P23	Auxiliary command time for tool path	0.05 sec	Instant	M
P24	Dwell at groove bottom (number of spindle rotation)	Revolutions	Instant	M
P25				
P26	Selection of escape pattern from wall (90°) in rough cutting cycle	–	Instant	E
P27	Specification of first M code for milling axis gear selection	–	Instant	M
P28	Specification of first M code for spindle gear selection	–	Instant	M
P29	Specification of first M code for parts catcher control	–	Instant	M
P30	Threading chamfering angle	Degree	Instant	E
P31	Simultaneous operation pattern for transfer	–	Instant	M
P32	Threading termination waiting time processing	3.5 msec	Instant	M
P33	Number of times of roughing in the composite-type fixed cycle (G73)	–	Instant	E
P34	Final finishing repeat times in the composite-type fixed cycle (G76)	–	Instant	E
P35	Maximum workpiece length range 1 on the CUT LEARN display	1 mm or 0.1 inches	Instant	M
P36	Maximum workpiece length range 2 on the CUT LEARN display	1 mm or 0.1 inches	Instant	M
P37	Maximum workpiece length range 3 on the CUT LEARN display	1 mm or 0.1 inches	Instant	M
P38	Maximum workpiece outside diameter range 1 on the CUT LEARN display	1 mm or 0.1 inches	Instant	M
P39	Maximum workpiece outside diameter range 2 on the CUT LEARN display	1 mm or 0.1 inches	Instant	M

Address	Outline	Unit	Effective condition	Applicable program (Note)
P40	Maximum workpiece outside diameter range 3 on the CUT LEARN display	1 mm or 0.1 inches	Instant	M
P41	Macro call G code	–	Instant	E
P42	Macro call G code	–	Instant	E
P43	Macro call M code	–	Instant	E
P44	Macro call M code	–	Instant	E
P45	Macro call M code	–	Instant	E
P46	Macro call M code	–	Instant	E
P47	Macro call M code	–	Instant	E
P48				
P49	Macro program number corresponding to P41	–	Instant	E
P50	Macro program number corresponding to P42	–	Instant	E
P51	Macro program number corresponding to P43	–	Instant	E
P52	Macro program number corresponding to P44	–	Instant	E
P53	Macro program number corresponding to P45	–	Instant	E
P54	Macro program number corresponding to P46	–	Instant	E
P55	Macro program number corresponding to P47	–	Instant	E
P56				
P57	Subprogram call M-code	–	Instant	E
P58	Subprogram call M-code	–	Instant	E
P59	Subprogram call M-code	–	Instant	E
P60	Subprogram number corresponding to P57	–	Instant	E
P61	Subprogram number corresponding to P58	–	Instant	E
P62	Subprogram number corresponding to P59	–	Instant	E
P63	Upward cutting speed for inside threading (THR IN)	mm/min 0.1 inches/min	Instant	M
P64				
P65	Selection about tape operation mode data input	–	Instant	E
P66	Method of judging whether the life of the tool is approaching	–	Instant	M
P67	Criteria for judging whether the life of the tool is approaching	% or minute	Instant	M

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
P68 P72				
P73	Number of times of pecking up to the return of the tool to a position near the starting point of the #4 or the #[4] very-deep-hole-drilling cycle of a DRP or MDR unit	Times	Instant	M
P74	Tool drawing accuracy in solid mode	–	Instant	M
P75				
P76	Selection of the shape correction function of the MAZATROL program	–	Instant	M
P77	Selection of whether the C-axis on the WORK OFFSET display for the No. 2 spindle is to be made valid or invalid	–	Instant	E
P78 P94				
P95	Selection of tool change position specification code for FLASH-tool or multi-tool holder	–	Instant	M
P96				
P97	Cutting depth in the composite-type fixed cycle (G71/G72)	0.001 mm or 0.0001 inches	Instant	E
P98	Amount of escape in an X-axial direction during the composite-type fixed cycle (G73)	0.001 mm or 0.0001 inches	Instant	E
P99	Amount of escape in a Z-axial direction during the composite-type fixed cycle (G73)	0.001 mm or 0.0001 inches	Instant	E
P100	Pitch of tapping tool for display in detail in solid mode	0.001 mm or 0.0001 inches	Instant	M
P101	Thread depth of tapping tool for display in detail in solid mode	0.001 mm or 0.0001 inches	Instant	M
P102 P104				
P105 (bit 0)				
P105 (bit 1)	EIA macroprogram call help function valid/invalid in MAZATROL screen mode	–	Instant	M
P105 (bit 2)	Cutting conditions studying function valid or invalid	–	Instant	M
P105 (bit 3)	Fixed-amount offset function valid or invalid	–	Instant	M
P105 (bit 4)	Whether the movable range of the inclined Y-axis is to be drawn on the TRACE display	–	Instant	M, E
P105 (bit 5)				
P105 (bit 6)	Text input/output valid/invalid for data I/O	–	Instant	M, E
P105 (bit 7)				
P106 (bit 0)	Handling when the lives of all the same group number tools are reached in a standard EIA/ISO mode	–	Instant	E
P106 (bit 1)	Method of estimating a residual life in standard EIA/ISO mode	–	Instant	E

Address	Outline	Unit	Effective condition	Applicable program (Note)
P106 (bit 2)	Hard disk, floppy disk, and/or memory card input/output Conditions for loading the machining program of the same work number	–	Instant	M, E
P106 (bit 3)	Selection of the display mode of ID numbers on the TOOL DATA display - Decimal or hexadecimal display	–	Instant	M, E
P106 (bit 4)				
P106 (bit 5)	Tool set data protection in the automatic operation mode	–	Instant	M, E
P106 (bit 6)	Whether the GRAPHIC MAINTEN. display is to be automatically displayed when the specific alarm occurs.	–	Instant	M, E
P106 (bit 7)				
P107 (bit 0)	Whether workpiece and finishing shape data is to be output during EIA conversion output	–	Instant	M
P107 (bit 1)				
P107 (bit 2)	Selection of G0/G1 EIA conversion output during the polar coordinate mode (G12.1)	–	Instant	M
P107 (bit 3)	Selection of the approach operation for machining with the No. 2 spindle	–	Instant	M
P107 (bit 4)	Selection of a FLASH-tool life management method	–	Instant	M, E
P107 (bit 5)	Selection of whether to hold spindle status during transfer (TRS) (machine with sub-spindle)	–	Instant	M
P107 (bit 6)	Selection of whether to execute the G90/G94 turning cycle when its approach point and ending point match	–	Instant	E
P107 (bit 7)	Selection of the Z/C offset to be used for the subprogram when a subprogram call is performed from the MAZATROL program to the EIA program	–	Instant	E
P108 (bit 0)	How to handle EOR (%) - M02 or M30	–	Instant	E
P108 (bit 1)	Execution mode selection for a fixed turning cycle	–	Instant	E
P108 (bit 2)	Form of single-block stop during a fixed turning cycle	–	Instant	E
P108 (bit 3)	T-command compensation	–	Instant	E
P108 (bit 4)	Selection of whether to output M30 for a tool whose life has been reached	–	Instant	M, E
P108 (bit 5)	Use/disuse of the Z-offset existing when a subprogram call is performed from the MAZATROL program to an EIA/ISO program	–	Instant	E
P108 (bit 6)	Selection of modal information reading system variable	–	Instant	E
P108 (bit 7)	Selection of output codes for macro external output instructions	–	Instant	M, E
P109 (bit 0)	Program protect flag (Whether editing of the programs of the order of WNo. 9000 is to be prohibited)	–	Instant	M, E
P109 (bit 1)	Program protect flag (Whether displaying of the programs of the order of WNo. 9000 is to be prohibited)	–	Instant	M, E
P109 (bit 2)	Whether to save the data as an additional one during hard disk/floppy disk input/output	–	Instant	M, E
P109 (bit 3)				

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
P109 (bit 4)	Program protect flag (Whether editing of the programs of the order of WNo. 8000 and WNo. 9000 is to be prohibited.)	–	Instant	M, E
P109 (bit 5)	Program protect flag (Whether displaying of the programs of the order of WNo. 8000 and WNo. 9000 is to be prohibited.)	–	Instant	M, E
P109 (bit 6)	Selection of an alarm checking method for data input/output program saving	–	Instant	M, E
P109 (bit 7)	Selection of the jaw data reference method	–	Instant	M, E
P110 (bit 0)	Power-on display selection	–	Instant	M, E
P110 (bit 1)	Page extension on the MAINTENANCE CHECK display	–	Instant	M, E
P110 (bit 2)	When the visual tool ID/data management functions are valid – Stored tools registration function on the VISUAL TOOL MANAGER display valid/invalid	–	Instant	M, E
P110 (bit 3)				
P110 (bit 4)				
P110 (bit 5)				
P110 (bit 6)	Tool length input valid/invalid	–	Instant	M, E
P110 (bit 7)				
P111 (bit 0)	M-command execution time processing during time study of tool path checking	–	Instant	M, E
P111 (bit 1)	T-command execution time processing during time study of tool path checking	–	Instant	M, E
P111 (bit 2)	Upward cutting speed valid/invalid for inside threading (THR IN)	–	Instant	M
P111 (bit 3)				
P111 (bit 4)				
P111 (bit 5)	Using angle tool holder valid/invalid	–	Instant	M, E
P111 (bit 6)	EIA tool command suffix valid/invalid	–	Instant	E
P111 (bit 7)	Selection of the method of moving axes to the tool change position (P7 and P95)	–	Instant	M
P112 (bit 0)	Selection of measurement data items to be printed out - Work No., process No.	–	Instant	M, E
P112 (bit 1)	Selection of measurement data items to be printed out - Tool No., work counter	–	Instant	M, E
P112 (bit 2)	Selection of measurement data items to be printed out - Measurement mode	–	Instant	M, E
P112 (bit 3)	Selection of measurement data items to be printed out - Target data	–	Instant	M, E
P112 (bit 4)	Selection of measurement data items to be printed out - Measurement data	–	Instant	M, E
P112 (bit 5)	Selection of measurement data items to be printed out - Offset data	–	Instant	M, E

Address	Outline	Unit	Effective condition	Applicable program (Note)
P112 (bit 6)	Selection of measurement data items to be printed out - Tolerance upper/lower	–	Instant	M, E
P112 (bit 7)	Selection of measurement data items to be printed out - Day and time of measurement	–	Instant	M, E

Address	Outline	Unit	Effective condition	Applicable program (Note)
K1	Cut depth reduction rate for rough cutting in bar machining unit	%	Instant	M
K2	Acceleration rate in up - going taper for rough cutting in bar machining unit	%	Instant	M
K3	Acceleration rate in - up-going wall slope (90°) for rough cutting in bar machining unit	%	Instant	M
K4	Deceleration rate in down - going taper for rough cutting in bar machining unit	%	Instant	M
K5	Deceleration rate in down - going wall slope (90°) for rough cutting in bar machining unit	%	Instant	M
K6	Acceleration rate on outside stock contour for rough cutting in copy machining unit	%	Instant	M
K7				
K8	Rough cutting residue ratio in cutting off cycle	%	Instant	M
K9	Deceleration ratio for automatic corner overriding	%	Instant	E
K10	Cut depth allowable incremental rate for rough cutting in groove, edge and copy machining unites	%	Instant	M
K11	Deceleration rate at cutting start time in drilling unit	%	Instant	M
K12	Deceleration rate at cutting end time in drilling unit	%	Instant	M
K13	Deceleration rate at rough cutting start time (BAR, CPY)	%	Instant	M
K14	Maximum permissible rate of increase of the initial cutting depth during BAR roughing	%	Instant	M
K15	Pitch error correction during threading acceleration	0.001 mm	Instant	M
K16				
K17	Drilling cut depth calculation coefficient	%	Instant	M
K18	Reamer return speed calculation coefficient	%	Instant	M
K19	Chamfering data calculation coefficient in thread cutting unit	Lead/10	Instant	M, E
K20	Incomplete threading portion length calculation coefficient for tap tip	Pitch/10	Instant	M
K21	Tapper elongation calculation coefficient	Pitch/10	Instant	M
K22				

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
K23	Calculation coefficient for axial feedrate of milling line machining	%	Instant	M
K24	Thread height calculation coefficient for outside diameter, face/rear thread cutting (metric)	0.01 %	Instant	M
K25	Thread height calculation coefficient for inside diameter thread cutting (metric)	0.01 %	Instant	M
K26	Thread height calculation coefficient for outside diameter, face/rear thread cutting (inch)	0.01 %	Instant	M
K27	Thread height calculation coefficient for inside diameter thread cutting (inch)	0.01 %	Instant	M
K28				
K29	Feedrate calculation reference diameter in mill drilling unit	0.1 mm or 0.01 inches	Instant	M
K30	Feedrate calculation reference diameter in mill boring unit	0.1 mm or 0.01 inches	Instant	M
K31	Radial direction feedrate calculation reference diameter for rough cutting in milling line machining unit	0.1 mm or 0.01 inches	Instant	M
K32	Radial direction feedrate calculation reference diameter for finish cutting in milling line machining unit	0.1 mm or 0.01 inches	Instant	M
K33	Polishing margin width for #1 to #3	0.001 mm or 0.0001 inches	Instant	M
K34	Polishing margin depth for #1 to #3	0.001 mm or 0.0001 inches	Instant	M
K35	Polishing margin width for #4	0.001 mm or 0.0001 inches	Instant	M
K36	Polishing margin depth for #4	0.001 mm or 0.0001 inches	Instant	M
K37	Polishing margin width for #5	0.001 mm or 0.0001 inches	Instant	M
K38	Polishing margin depth for #5	0.001 mm or 0.0001 inches	Instant	M
K39	Polishing margin width for #6	0.001 mm or 0.0001 inches	Instant	M
K40	Polishing margin depth for #6	0.001 mm or 0.0001 inches	Instant	M
K41	Rate of adjustment of the axial cutting/relief feedrate during linear milling	%	Instant	M
K42	Distance from the ending point of a mill-drilling unit (MDR) where the feedrate is to be modified	0.001 mm or 0.0001 inches	Instant	M
K43	Radial clearance for circular milling	0.001 mm or 0.0001 inches	Instant	M
K44				
K45	Reference diameter for calculating the circular milling radial feedrate	0.1 mm or 0.01 inches	Instant	M
K46	Coefficient for calculating the circular milling axial feedrate	%	Instant	M
K47	Selection of position for output of reciprocating rotation M code milling tapping (asynchronous)	-	Instant	M, E
K48				

Address	Outline	Unit	Effective condition	Applicable program (Note)
K49	Selection of manual feed per revolution or per minute	–	Instant	M, E
K50	Direction of rotation of the C-axis during C-axis threading with G01.1	–	Instant	E
K51	Selection of whether to move the tool past a clearance point immediately before executing move command of the turning/milling manual program machining unit that follows I. D. machining	–	Instant	M
K52 K54				
K55	Selection of a shape definition method for the Z-C plane in a linear machining unit	–	Instant	M
K56				
K57	Method of nose R offsetting during finishing with EIA conversion output	–	Instant	E
K58	Language selection	–	Power OFF → ON	M, E
K59				
K60 (bit 0)	Data entry for communication with the magazine-side display unit (Serial port)	–	Power OFF → ON	M, E
K60 (bit 1)	Data entry for communication with the magazine-side display unit (Serial port)	–	Power OFF → ON	M, E
K60 (bit 2)	Data entry for communication with the magazine-side display unit (Communication setting file)	–	Power OFF → ON	M, E
K60 (bit 3)				
K60 (bit 4)	Data entry for communication with the magazine-side display unit (Type of ID amplifier)	–	Power OFF → ON	M, E
K60 (bit 5)	Data entry for communication with the magazine-side display unit (Type of ID amplifier)	–	Power OFF → ON	M, E
K60 (bit 6)	Data entry for communication with the magazine-side display unit (R-register)	–	Power OFF → ON	M, E
K60 (bit 7)	Data entry for communication with the magazine-side display unit (R-register)	–	Power OFF → ON	M, E
K61 K64				
K65	Selection of a cylindrical interpolation rotational axis for cylindrical interpolation plane selection	–	Instant	E
K66				
K67	Angle of the tool nose during the G76 mode	Degree	Instant	E
K68	Number of common variables between turrets (#100 onward)	–	Instant	E
K69	Number of common variables between turrets (#500 onward)	–	Instant	E
K70	Return speed overriding during a synchronous tapping	%	Instant	E
K71				

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
K72	Tool registration quantity pattern on the TOOL LIFE display	—	Instant	E
K73				
K74	Number of cutting edges of a FLASH-tool for milling (Only when using a tool not specified in the TOOL FILE display)	—	Instant	M, E
K75	Selection about planetary tapping chip ejection	—	Instant	M
K76	Reduction ratio for the G00-based relief rate during a very-deep-hole drilling cycle	%	Instant	M
K77	Dwell at the hole bottom during a DRL or MDR unit	Revolutions	Instant	M
K78 K80				
K81	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K82	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K83	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K84	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K85	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K86	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K87	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K88	CODE — Macro call G-code NUM. — Corresponding macroprogram number	—	Instant	E
K89	CODE — Macro call M-code NUM. — Corresponding macroprogram number	—	Instant	E
K90	CODE — Macro call M-code NUM. — Corresponding macroprogram number	—	Instant	E
K91	CODE — Macro call M-code NUM. — Corresponding macroprogram number	—	Instant	E
K92	CODE — Macro call M-code NUM. — Corresponding macroprogram number	—	Instant	E
K93	CODE — Macro call M-code NUM. — Corresponding macroprogram number	—	Instant	E
K94	CODE — Macro call S-code NUM. — Corresponding macroprogram number	—	Instant	E
K95	CODE — Macro call T-code NUM. — Corresponding macroprogram number	—	Instant	E
K96	CODE — Macro call B-code NUM. — Corresponding macroprogram number	—	Instant	E

Address	Outline	Unit	Effective condition	Applicable program (Note)
U1	Tool turning clearance in X-axis	0.001 mm or 0.0001 inches	Instant	M
U2	Tool turning clearance in Z-axis	0.001 mm or 0.0001 inches	Instant	M
U3	Safety contour clearance - Outside diameter clearance	0.001 mm or 0.0001 inches	Instant	M
U4	Safety contour clearance - Inside diameter clearance	0.001 mm or 0.0001 inches	Instant	M
U5	Safety contour clearance - Front clearance	0.001 mm or 0.0001 inches	Instant	M
U6	Safety contour clearance - Back clearance	0.001 mm or 0.0001 inches	Instant	M
U7	Thread cutting clearance	0.001 mm or 0.0001 inches	Instant	M
U8	Groove cutting clearance in X-axis	0.001 mm or 0.0001 inches	Instant	M
U9	Groove cutting clearance in Z-axis	0.001 mm or 0.0001 inches	Instant	M
U10	Milling line right/left cutting clearance	0.001 mm or 0.0001 inches	Instant	M
U11	Workpiece transfer clearance	0.001 mm or 0.0001 inches	Instant	M
U12	Amount of edge clearance after EDG roughing	0.001 mm or 0.0001 inches	Instant	M
U13	Radial finishing allowance for Y-axis mill-grooving unit (MGV)	%	Instant	M
U14	Amount of overlapping for Y-axis mill-grooving unit (MGV)	0.001 mm or 0.0001 inches	Instant	M
U15 U17				
U18	Return speed at pecking portion in groove cutting, drilling unit	0.001 mm/rev or 0.0001 inches/rev	Instant	M
U19	Feedrate specification reference speed for finish cutting in milling line machining unit	0.001 mm/rev or 0.0001 inches/rev	Instant	M
U20				
U21	Measurement skip feedrate (X-axis, Z-axis)	mm/min or 0.1 inches/min	Instant	M
U22	Measurement approach speed (X-axis, Z-axis)	mm/min or 0.1 inches/min	Instant	M
U23	Measurement skip speed (C-axis)	mm/min or 0.1 inches/min	Instant	M
U24	Measurement approach speed (C-axis)	mm/min or 0.1 inches/min	Instant	M
U25	Approaching speed for TPS function	mm/min or 0.1 inches/min	Instant	M
U26	Workpiece pressing speed in workpiece transfer unit (TPS)	mm/min or 0.1 inches/min	Instant	M
U27	Revolution number (min^{-1}) of two spindles in workpiece transfer unit	min^{-1} (rpm)	Instant	M
U28	Feedrate for escape by short distance	mm/min or 0.1 inches/min	Instant	M

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
U29	Maximum angle for automatic corner overriding	Degree	Instant	E
U30 U32				
U33	Return distance in X-axis at wall during rough cutting	0.001 mm or 0.0001 inches	Instant	M
U34	Return distance in Z-axis at wall during rough cutting Return distance after cutting in the rough-cutting cycle (G71, G72)	0.001 mm or 0.0001 inches	Instant	M, E
U35	Cut depth per cycle for machining inside diameter	0.001 mm or 0.0001 inches	Instant	M
U36	Reverse feed tolerance for contour machining	0.001 mm or 0.0001 inches	Instant	M
U37	Overtravelling in X-axis direction in edge machining unit	0.001 mm or 0.0001 inches	Instant	M
U38	Acceleration distance clamp value for thread cutting unit	Lead/10	Instant	M
U39	Cut depth for final cut in thread cutting unit	0.001 mm or 0.0001 inches	Instant	M, E
U40				
U41	Pecking return distance in groove cutting unit	0.001 mm or 0.0001 inches	Instant	M, E
U42	Overlap distance in groove cutting unit	0.001 mm or 0.0001 inches	Instant	M
U43	Escape value after machining in edge machining unit	0.001 mm or 0.0001 inches	Instant	M
U44	Drilling depth decrement	0.001 mm or 0.0001 inches	Instant	M
U45	Pecking return distance in drilling unit	0.001 mm or 0.0001 inches	Instant	M, E
U46	Drilling cut depth clamp value	0.001 mm or 0.0001 inches	Instant	M
U47	Escape value after milling spindle orientating at hole bottom in boring unit	0.001 mm or 0.0001 inches	Instant	M
U48	Distance of deceleration for automatic corner overriding	0.001 mm or 0.0001 inches	Instant	E
U49	Tolerance for radial value difference in arc command	0.001 mm or 0.0001 inches	Instant	E
U50	Workpiece pressing distance in workpiece transfer unit	0.001 mm or 0.0001 inches	Instant	M
U51	Deceleration clearance at start of rough cutting in bar and copy machining unit	0.001 mm or 0.0001 inches	Instant	M
U52	Tolerance for escape in high speed rough cutting cycle in bar machining unit	0.001 mm or 0.0001 inches	Instant	M
U53	Minimum overlap distance in mill-grooving unit (MGV) and circular milling unit (CIR)	0.001 mm or 0.0001 inches	Instant	M
U54	Spindle revolution clamp value in cutting off cycle	min ⁻¹ (rpm)	Instant	M
U55	Number of times of finishing when #0 is selected in threading unit	Times	Instant	M
U56	Number of times that feedrate is to be reduced during the #4 and #5 cutting cycle of a grooving unit	Times	Instant	M

Address	Outline	Unit	Effective condition	Applicable program (Note)
U57	Specification of measuring tolerance (lower limit)	%	Instant	M, E
U58	Specification of measuring tolerance (upper limit)	%	Instant	M, E
U59	Measurement stroke for workpiece measurement	0.001 mm or 0.0001 inches	Instant	M
U60	Measurement stroke for tool nose measurement	0.001 mm or 0.0001 inches	Instant	M
U61	Coefficient to determine rotation angle when retrying measurement in C offset measurement unit	%	Instant	M
U62	Feed override for the section to be chamfered for planetary tapping cycle	%	Instant	M
U63	Amount of escape at hole bottom for planetary tapping cycle	0.1 thread	Instant	M
U64	Specification of automatic pre-holing feed rate value for planetary tapping cycle	0.01 mm/rev or 0.001 inch/rev	Instant	M
U65	Delay timer of M code for the parts catcher (headstock 1)	msec	Instant	M
U66	Delay timer of M code for the parts catcher (headstock 2)	msec	Instant	M
U67	M-code value for making shape correction valid in the MAZATROL program	–	Instant	M
U68	M-code value for making shape correction invalid in the MAZATROL program	–	Instant	M
U69				
U70				
U71	Selection of transfer pattern (TRS)	–	Instant	M
U72 U74				
U75	Timer setting for manual TOOL EYE measurement	7.1 msec	Instant	M, E
U76				
U77				
U78	Selection as to tool life management alarm display	–	Instant	M, E
U79	Setting range of MTP dwell time data	msec	Instant	M
U80				
U81	Raw jaw forming workpiece length	0.001 mm or 0.0001 inches	Instant	M
U82	Specification of automatic feed rate value for planetary tapping cycle	0.01 mm/rev or 0.001 inch/rev	Instant	M
U83	Height of the second referential point during the Tornado cycle	0.001 mm or 0.0001 inches	Instant	M

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
U84 U95				
U96				

According to machine used, parameters D and E are not specified.

Address	Outline	Unit	Effective condition	Applicable program (Note)
D1	Height of the second referential point during point machining	0.001 mm or 0.0001 inches	Instant	M
D2	Nominal diameter of spot-machining tool	1 mm or 0.1 inches	Instant	M
D3	Spot-machining hole bottom dwell time element	Revolution	Instant	M
D4	Maximum allowable spot-chamfering hole diameter element	0.1 mm or 0.01 inches	Instant	M
D5	Prehole through speed during inversed spot-facing	1 mm/min 0.1 inch/min	Instant	M
D6	Drill-machining cycle setting element	–	Instant	M
D7	Drill-machining cycle setting element	–	Instant	M
D8	Maximum diameter of holes machinable on one drill	1 mm or 0.1 inches	Instant	M
D9	Maximum diameter of holes machinable on two drills	1 mm or 0.1 inches	Instant	M
D10	Maximum diameter of holes machinable on three drills	1 mm or 0.1 inches	Instant	M
D11	Through-hole/Tap-prehole machining overshoot	0.1 mm or 0.01 inches	Instant	M
D12	Stop-hole machining hole-bottom clearance	0.1 mm or 0.01 inches	Instant	M
D13	Spot-machining hole diameter (fixed value)	1 mm or 0.1 inches	Instant	M
D14	Depth-of-cut setting element for drilling (ALMINUM)	0.1	Instant	M
D15	Depth-of-cut setting element for drilling (except AL)	0.1	Instant	M
D16	Hole-bottom dwell time for chamfering cutter	Revolution	Instant	M
D17	Interference clearance of chamfering cutter	0.001 mm 0.0001 inches	Instant	M
D18	Return feedrate for reaming or boring (cycle 3)	1 mm/min or 0.1 inch/min	Instant	M
D19	Hole-bottom dwell time for end milling	Revolution	Instant	M
D20	Radial depth-of-cut setting element for end milling	%	Instant	M
D21	Reference bottom-finishing allowance for end milling	0.001 mm or 0.0001 inches	Instant	M

Address	Outline	Unit	Effective condition	Applicable program (Note)
D22	Tapping-cycle dwell time	0.01 sec	Instant	M
D23				
D24	Hole bottom dwell time for boring	Revolution	Instant	M
D25				
D26	Boring or back-boring hole-bottom return	0.001 mm or 0.0001 inch	Instant	M
D27				
D28	Bottom-finishing amount of boring	0.001 mm or 0.0001 inches	Instant	M
D29 D32				
D33	Back-boring tool tip relief	0.001 mm or 0.0001 inches	Instant	M
D34				
D35	Prehole-drilling diameter setting element for reamer (drilling)	0.01 mm or 0.001 inch	Instant	M
D36	Prehole-drilling diameter setting element for reamer (boring)	0.01 mm or 0.001 inches	Instant	M
D37	Prehole-drilling diameter setting element for reamer (end milling)	0.01 mm or 0.001 inches	Instant	M
D38	Machining hole diameter setting element for boring tool or end mill in the reamer unit	0.01 mm or 0.001 inches	Instant	M
D39	Machining hole diameter setting element for end mill in the reamer unit	0.01 mm or 0.001 inches	Instant	M
D40	Spot-faced hole bottom dwell time for inversed spot-facing	Revolution	Instant	M
D41				
D42	Height of the third referential point during point machining	0.001 mm or 0.0001 inches	Instant	M
D43	Number of incomplete threads in tapping cycle	pitch/10	Instant	M
D44	Automatic calculation method for the amount of chamfering using the tapping unit	–	Instant	M
D45	Amount of mill-drilling depth attenuation	0.001 mm or 0.0001 inches	Instant	M
D46	Mill-drilling depth clamping value	0.001 mm or 0.0001 inches	Instant	M
D47	Reamer-prehole machining overshoot	0.01 mm or 0.001 inches	Instant	M
D48 D72				
D73 D77	Learning of cutting conditions (DEP-A range)	–	Instant	M

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
D78 D82	Learning of cutting conditions (WID-R range)	—	Instant	M
D83 D90				
D91 (bit 0)				
D91 (bit 1)				
D91 (bit 2)				
D91 (bit 3)				
D91 (bit 4)				
D91 (bit 5)				
D91 (bit 6)	Set the referential point height of the drill as D1 or D42 if a spot drill/drill is included in the pre-machining tool sequence of the same unit.	—	Instant	M
D91 (bit 7)	Set the referential point height of the chamfering cutter during the cycle 2 as D42 .	—	Instant	M
D92 (bit 0)	Use K41 for axial feed during a true-circle processing (end milling) cycle.	—	Instant	M
D92 (bit 1)	Set the referential point 1 height of the back spot facing as D1 .	—	Instant	M
D92 (bit 2)	Set the referential point height of the reamer as D1 if a chamfering cutter is included in the premachining tool sequence of the same unit.	—	Instant	M
D92 (bit 3)				
D92 (bit 4)				
D92 (bit 5)				
D92 (bit 6)				
D92 (bit 7)				
D93 D94				
D95 (bit 0)	Data auto-setting method selection for pipe tapping	—	Instant	M
D95 (bit 1)	Data auto-setting method selection for unified tapping	—	Instant	M
D95 (bit 2)	Data auto-setting method selection for metric tapping	—	Instant	M
D95 (bit 3)				
D95 (bit 4)				
D95 (bit 5)				

Address	Outline	Unit	Effective condition	Applicable program (Note)
D95 (bit 6)				
D95 (bit 7)				
D95 (bit 8)				
D96 D108				

Address	Outline	Unit	Effective condition	Applicable program (Note)
E1	Closed-pattern cutting start point and escape point setting element	0.001 mm or 0.0001 inches	Instant	M
E2				
E3				
E4	Reference allowance of finishing in radial direction	0.001 mm or 0.0001 inches	Instant	M
E5	Element used to set the cutting start point and escape point (the second clearance)	0.001 mm or 0.0001 inches	Instant	M
E6	Reference allowance of finishing in axial direction	0.001 mm or 0.0001 inches	Instant	M
E7	Allowance of cutting start point in axial direction (the second clearance)	0.001 mm or 0.0001 inches	Instant	M
E8	Radial interference clearance of chamfering cutter	0.001 mm or 0.0001 inches	Instt	M
E9				
E10	Depth-of-cut-R automatic setting element (Face milling, End milling-top, End milling-step)	10%	Instant	M
E11	Axial interference clearance of chamfering cutter	0.001 mm or 0.0001 inches	Instant	M
E12	Radial interference clearance of face milling unit and angular face milling unit	0.001 mm or 0.0001 inches	Instant	M
E13	Tool path setting element for end milling-top unit	10%	Instant	M
E14	Depth-of-cut-R automatic setting element (Pocket milling, Pocket milling-mountain, Pocket milling-valley)	10%	Instant	M
E15	Tool path setting element for face milling-top unit (reciprocating short)	10%	Instant	M
E16				
E17	Axial cutting feed override	10%	Instant	M
E18	Override in case of the overall width cutting for pocket-machining	10%	Instant	M
E19 E20				

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
E21	Overlapping depth during wall cutting in a closed pattern	0.001 mm or 0.0001 inches	Instant	M
E22 E91				
E92	Tool-path pattern selection for pocket milling unit	–	Instant	M
E93				
E94				
E95	Tool-path pattern selection for line-machining unit	–	Instant	M
E96	Tool-path pattern selection for end milling-slot unit	–	Instant	M
E97	Tool-path pattern selection for end milling-top unit	–	Instant	M
E98 E108				

2-2 MACHINE PARAMETER

Note: M: Valid only for MAZATROL Program

E: Valid only for EIA/ISO Program

Address	Outline	Unit	Effective condition	Applicable program (Note)
A1	Maximum rapid traverse speed	mm/min (0.1 inches/min) or deg/min	Instant	M, E
A2	Clamping value for the cutting feedrate during tool tip point control	mm/min (0.1 inches/min) or deg/min	Instant	M, E
A3	Origin return speed	mm/min (0.1 inches/min) or deg/min	Instant	M, E
A4	Cutting feedrate clamp value, thread chamfering feedrate	mm/min (0.1 inches/min) or deg/min	Instant	M, E
A5	Fixed point return position	0.001 mm 0.0001 inches 0.001 deg	Instant	M, E
A6	Tool tip measurement tool change position	0.001 mm or 0.0001 inches	Instant	M, E
A7	Workpiece origin (fixed point) coordinate	0.001 mm or 0.0001 inches	Instant	E
A8	Machine reference position	0.001 mm or 0.0001 inches	Instant	M, E
A9	Soft limit upper end	0.001 mm or 0.0001 inches	Instant	M, E
A10	Soft limit lower end	0.001 mm or 0.0001 inches	Instant	M, E
A11	Single direction positioning shift distance	0.001 mm or 0.0001 inches	Instant	M, E
A12	Handle interruption clamp data	0.001 mm or 0.0001 inches	Instant	M, E
A13	Origin point dog shift distance	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
A14	Machine position shift distance	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
A15	Floating reference point	0.001 mm or 0.0001 inches	Instant	E
A16	Amount of watchdog-less origin shift	0.001 mm 0.0001 inches 0.001 deg	Instant	M, E
A17	Feed forward gain	%	Instant	M, E
A18 (bit 0)	Selection of a linear-type rotational axis	—	Power OFF → ON	M, E
A18 (bit 1)	Selection as to how to determine the rotational direction of the rotational axis	—	Power OFF → ON	M, E
A18 (bit 2)				
A18 (bit 3)				
A18 (bit 4)				

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
A18 (bit 5)				
A18 (bit 6)				
A18 (bit 7)				
A19 A24				
A25	Setting the upper limit data of Stored Stroke Limit II	0.001 mm or 0.0001 inches	After travelling stop	M, E
A26	Setting the lower limit data of Stored Stroke Limit II	0.001 mm or 0.0001 inches	After travelling stop	M, E
A27	Rear-turret machine coordinate origin (Dual-turret specs. only)	0.001 mm or 0.0001 inches	After travelling stop	M, E
A28				
A29	Illegal axis area - Setting the upper limit (Type A), (Type B), (Type C)	0.001 mm or 0.0001 inches	Instant	M, E
A30	Illegal axis area - Setting the lower limit (Type A), (Type B), (Type C)	0.001 mm or 0.0001 inches	Instant	M, E
A31	Reference position of tool offsetting	0.001 mm or 0.0001 inches	Instant	M, E
A32	X-axial distance from the center of the B-axis to that of the C-axis at the time of arrival at the home position	–	Instant	E

- The Machine Parameter is found with each head or tool post.
- Display of the Machine parameter is changed by HEAD SELECT key or TURRET SELECT key on the operation board in case of 4/6 axis type machine.

*H1: No. 1 spindle head

*H2: No. 2 spindle head

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B1	○	○	Tool head No. (#1)	–	Instant	M, E
B2	○	○	Number of tools (#1)	–	Instant	M, E
B3	○	○	Tool head No. (#2)	–	Instant	M, E
B4	○	○	Number of tools (#2)	–	Instant	M, E
B5	○	○	Tool head No. (#3)	–	Instant	M, E
B6	○	○	Number of tools (#3)	–	Instant	M, E
B7	○	○	Tool head No. (#4)	–	Instant	M, E
B8	○	○	Number of tools (#4)	–	Instant	M, E
B9	○	○	Tool head No. (#5)	–	Instant	M, E

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B10	<input type="radio"/>	<input type="radio"/>	Number of tools (#5)	–	Instant	M, E
B11	<input type="radio"/>	<input type="radio"/>	Number of turret pockets	–	Instant	M, E
B12						
B13						
B14	<input type="radio"/>	<input type="radio"/>	Selection of reference tool in updating data method during automatic nose measurement (for EIA)	–	Instant	E
B15	<input type="radio"/>	<input type="radio"/>	Reference tool No.	–	Instant	M, E
B16	<input type="radio"/>	<input type="radio"/>	Reference tool suffix	–	Instant	M, E
B17	<input type="radio"/>	<input type="radio"/>	Direction of N° orientation indexing	–	Instant	M, E
B18	<input type="radio"/>	<input type="radio"/>	Number of pins to be driven for N° orientation	–	Instant	M, E
B19	<input type="radio"/>	<input type="radio"/>	Angular direction of spindle orientation on headstock 1 (Angular direction of spindle orientation on headstock 2)	–	Power OFF → ON	M, E
B20 B28						
B29	<input type="radio"/>	<input type="radio"/>	Selecting Type A/Type B of illegal axis area limits	–	Instant	M, E
B30						
B31	<input type="radio"/>	<input type="radio"/>	Name of the fourth axis	ASCII by decimal digit	Instant	M, E
B32	<input type="radio"/>	<input type="radio"/>	Name of the fifth axis	ASCII by decimal digit	Instant	M, E
B33	<input type="radio"/>	<input type="radio"/>	Chuck outside diameter	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B34	<input type="radio"/>	<input type="radio"/>	Chuck width	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B35	<input type="radio"/>	<input type="radio"/>	Chuck inside diameter	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B36						
B37	<input type="radio"/>	<input type="radio"/>	Tail body outside diameter	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B38	<input type="radio"/>	<input type="radio"/>	Tail body length	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B39	<input type="radio"/>	<input type="radio"/>	Tail spindle outside diameter	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B40	<input type="radio"/>	<input type="radio"/>	Length with tail spindle at back end	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B41	<input type="radio"/>	<input type="radio"/>	Tail head outside diameter	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B42	<input type="radio"/>	<input type="radio"/>	Tail head length	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B43	<input type="radio"/>	<input type="radio"/>	Tail head taper angle	0.001 deg	Power OFF → ON	M, E

2 PARAMETER LIST

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B44	<input type="radio"/>	<input type="radio"/>	Tail head biting diameter	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B45	<input type="radio"/>	<input type="radio"/>	Tool post radius	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B46	<input type="radio"/>	<input type="radio"/>	Tool post width	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B47	<input type="radio"/>	<input type="radio"/>	Tool post reference position in X-axis direction	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B48	<input type="radio"/>	<input type="radio"/>	Tool post reference position in Z-axis direction	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B49	<input type="radio"/>	<input type="radio"/>	Tool holder (type 1) mounting position	0.001 mm or 0.0001 inches	Instant	M
B50	<input type="radio"/>	<input type="radio"/>	Tool holder (type 1) width in X-axis direction	0.001 mm or 0.0001 inches	Instant	M
B51	<input type="radio"/>	<input type="radio"/>	Tool holder (type 1) width in Z-axis direction	0.001 mm or 0.0001 inches	Instant	M
B52	<input type="radio"/>	<input type="radio"/>	Tool holder (type 2) mounting position	0.001 mm or 0.0001 inches	Instant	M
B53	<input type="radio"/>	<input type="radio"/>	Tool holder (type 2) width in X-axis direction	0.001 mm or 0.0001 inches	Instant	M
B54	<input type="radio"/>	<input type="radio"/>	Tool holder (type 2) width in Z-axis direction	0.001 mm or 0.0001 inches	Instant	M
B55	<input type="radio"/>	<input type="radio"/>	Tool holder (type 3) mounting position	0.001 mm or 0.0001 inches	Instant	M
B56	<input type="radio"/>	<input type="radio"/>	Tool holder (type 3) width in X-axis direction	0.001 mm or 0.0001 inches	Instant	M
B57	<input type="radio"/>	<input type="radio"/>	Tool holder (type 3) width in Z-axis direction	0.001 mm or 0.0001 inches	Instant	M
B58	<input type="radio"/>	<input type="radio"/>	Tool holder (type 4) mounting position	0.001 mm or 0.0001 inches	Instant	M
B59	<input type="radio"/>	<input type="radio"/>	Tool holder (type 4) width in X-axis direction	0.001 mm or 0.0001 inches	Instant	M
B60	<input type="radio"/>	<input type="radio"/>	Tool holder (type 4) width in Z-axis direction	0.001 mm or 0.0001 inches	Instant	M
B61	<input type="radio"/>	<input type="radio"/>	Tool nose measurement sensor width in X-axis direction	0.001 mm or 0.0001 inches	Instant	M
B62	<input type="radio"/>	<input type="radio"/>	Tool nose measurement sensor width in Z-axis direction	0.001 mm or 0.0001 inches	Instant	M
B63	<input type="radio"/>	<input type="radio"/>	Tool nose measurement sensor mounting position in X-axis	0.001 mm or 0.0001 inches	Instant	M
B64	<input type="radio"/>	<input type="radio"/>	Tool nose measurement sensor mounting position in Z-axis	0.001 mm or 0.0001 inches	Instant	M
B65						
B66	<input type="radio"/>	<input type="radio"/>	Workpiece measurement sensor diameter compensation data for outside diameter measurement and projection width measurement	0.001 mm or 0.0001 inches	Instant	M
B67	<input type="radio"/>	<input type="radio"/>	Workpiece measurement sensor diameter compensation data for inside diameter measurement and groove width measurement	0.001 mm or 0.0001 inches	Instant	M
B68	<input type="radio"/>	<input type="radio"/>	Position of separating plate	0.001 mm or 0.0001 inches	Instant	M

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B69	○		Chuck outside diameter of No. 2 spindle (twin spindle specs. only)	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B70	○		Chuck width of No. 2 spindle (twin spindle specs. only)	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B71	○		Chuck inside diameter of No. 2 spindle (twin spindle specs. only)	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B72	○	○	Z-coordinate of turret reference position with respect to spindle edge	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B73	○	○	X-coordinate of tool path start point on the TOOL PATH CHECK display	0.001 mm or 0.0001 inches	Instant	M, E
B74	○	○	Z-coordinate of tool path start point on the TOOL PATH CHECK display	0.001 mm or 0.0001 inches	Instant	M, E
B75	○	○	Spindle limit speed 1 selection for spindle position control time constant	Revolution	Power OFF → ON	M, E
B76	○	○	Spindle limit speed 2 selection for spindle position control time constant	Revolution	Power OFF → ON	M, E
B77	○	○	Spindle limit speed 3 selection for spindle position control time constant	Revolution	Power OFF → ON	M, E
B78	○	○	Spindle position control time constant 1	0.001 sec	Power OFF → ON	M, E
B79	○	○	Spindle position control time constant 2	0.001 sec	Power OFF → ON	M, E
B80	○	○	Spindle position control time constant 3	0.001 sec	Power OFF → ON	M, E
B81 (bit 0)	○	○	EIA barrier selection - Tail to be used or not	-	Instant	E
B81 (bit 1)	○	○	EIA barrier selection - Holder present or not	-	Instant	E
B81 (bit 2)	○	○	EIA barrier selection - Main chuck outer or inner jaw	-	Instant	E
B81 (bit 3)	○	○	EIA barrier selection - Sub-chuck outer or inner jaw	-	Instant	E
B82	○	○	M-code for spindle forward rotation during a fixed hole-drilling cycle	-	Power OFF → ON	E
B83	○	○	M-code for spindle reverse rotation during a fixed hole-drilling cycle	-	Power OFF → ON	E
B84	○	○	T-command pre-reading valid/invalid, selection of whether to display tail information, stand by M-code pre-reading valid/invalid, pre-reading the block immediately succeeding the M00/M01 code valid/invalid, bar feeder schedule function valid/invalid, NC powered tailstock valid/invalid, and selection of whether to display tail thrust in pounds (lbs)	-	Power OFF → ON	M, E
B85 (bit 0)	○	○	Selection of the feed unit at block connections	-	Instant	M, E
B86	○		Holder angle of angle tool holder	Degree	Instant	M, E
B87						
B88						
B89	○	○	Selection of the solid-mode threading tool nose position	-	Instant	M

2 PARAMETER LIST

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B90 B106						
B107	○		Angle of pre-interpolation corner deceleration	Degree	Instant	M, E
B108	○	○	Reference axis for polygonal machining	Number of controlled axis	Power OFF → ON	E
B109	○	○	Spindle number for mill spindle synchronous tapping	Number of controlled axis	Power OFF → ON	M, E
B110	○	○	Axis control flag for a machine having a high-speed turret	–	Power OFF → ON	M, E
B111						
B112	○		S-shaped acceleration/deceleration filtering	–	Instant	M, E
B113 B144						
B145	○	○	Dwell time during the C-axis unclamping mode in a fixed hole-drilling cycle	msec	Power OFF → ON	M, E
B146	○		Pre-interpolation acceleration/deceleration: Time constant	msec	Instant	M, E
B147	○		Maximum cutting speed for shape correction mode	mm/min or 0.1 inches/min	Instant	M, E
B148	○	○	Feedrate during measurement for automatic tool offsetting	mm/min	Instant	E
B149	○	○	Rapid feed overriding data	%	Instant	M, E
B150	○	○	Rapid feed overriding data	%	Instant	M, E
B151	○	○	Rapid feed overriding data	%	Instant	M, E
B152	○	○	Minimum index angle of the FLASH-tool	0.1 degrees	Instant	M, E
B153	○	○	Maximum spindle speeds setting for each gear position [1] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B154	○	○	Maximum spindle speeds setting for each gear position [2] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B155	○	○	Maximum spindle speeds setting for each gear position [3] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B156	○	○	Maximum spindle speeds setting for each gear position [4] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B157	○	○	Maximum spindle speeds setting for each gear position [5] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B158	○	○	Maximum spindle speeds setting for each gear position [6] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B159	○	○	Maximum spindle speeds setting for each gear position [7] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B160	○	○	Maximum spindle speeds setting for each gear position [8] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B161	○	○	Critical spindle speeds setting for each gear position [1] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B162	○	○	Critical spindle speeds setting for each gear position [2] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B163	○	○	Critical spindle speeds setting for each gear position [3] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B164	○	○	Critical spindle speeds setting for each gear position [4] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B165	○	○	Critical spindle speeds setting for each gear position [5] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B166	○	○	Critical spindle speeds setting for each gear position [6] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B167	○	○	Critical spindle speeds setting for each gear position [7] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B168	○	○	Critical spindle speeds setting for each gear position [8] during a synchronous tapping cycle	min ⁻¹ (rpm)	Power OFF → ON	M, E
B169	○	○	Maximum permissible speed of the rotational axis for polygonal/hobbing machining	min ⁻¹ (rpm)	Power OFF → ON	E
B170	○	○	Acceleration/deceleration time constant for synchronous tapping	msec	Power OFF → ON	M, E
B171	○	○	Spindle 1/4h (1/2h) rated torque for L coils for auto-pecking of the cutting load detection type	0.1 N·m	Instant	M
B172	○	○	Spindle 1/4h (1/2h) rated torque for H coils for auto-pecking of the cutting load detection type	0.1 N·m	Instant	M
B173	○	○	Cutting force calculation filter for auto-pecking of the cutting load detection type	7.1 msec	Instant	M
B174 B175						
B176	○		Time constant for threading	msec	Instant	M, E
B177	○		Analog output offset adjustment	–	Instant	M, E
B178	○		Analog output offset adjustment	–	Instant	M, E
B179	○		Analog output offset adjustment	–	Instant	M, E
B180	○		Analog output offset adjustment	–	Instant	M, E
B181	○		Analog output offset adjustment	–	Instant	M, E
B182	○		Analog output gain adjustment	–	Instant	M, E
B183	○		Analog output gain adjustment	–	Instant	M, E
B184	○		Analog output gain adjustment	–	Instant	M, E
B185	○		Analog output gain adjustment	–	Instant	M, E
B186	○		Analog output gain adjustment	–	Instant	M, E
B187	○		Analog input gain adjustment	–	Instant	M, E
B188	○		Analog input gain adjustment	–	Instant	M, E

2 PARAMETER LIST

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B189	○		Analog input gain adjustment	–	Instant	M, E
B190	○		Analog input gain adjustment	–	Instant	M, E
B191	○		Analog input gain adjustment	–	Instant	M, E
B192 B199						
B200	○		Correction value for tool-setting data auto-setting functions (for ↓ tool)	0.001 mm or 0.0001 inches	Instant	M
B201	○		Correction value for tool-setting data auto-setting functions (for ↓ tool)	0.001 mm or 0.0001 inches	Instant	M
B202	○		Correction value for tool-setting data auto-setting functions (for ← tool)	0.001 mm or 0.0001 inches	Instant	M
B203	○		Correction value for tool-setting data auto-setting functions (for ← tool)	0.001 mm or 0.0001 inches	Instant	M
B204	○		Turret rotational runout correction value	0.001 mm or 0.0001 inches	Instant	M, E
B205 B208						
B209	○		Radius of the rear turret (Dual turret specs. only)	0.001 mm or 0.0001 inches	Instant	M, E
B210	○		Width of the rear turret (Dual turret specs. only)	0.001 mm or 0.0001 inches	Instant	M, E
B211	○		Rear turret reference position - X-coordinate (Dual turret specs. only)	0.001 mm or 0.0001 inches	Instant	M, E
B212	○		Rear turret reference position - Z-coordinate (Dual turret specs. only)	0.001 mm or 0.0001 inches	Instant	M, E
B213	○		Mounting position of the tool holder (Dual turret specs. only, type 1)	0.001 mm or 0.0001 inches	Instant	M, E
B214	○		X-axial width of the tool holder for the rear turret (Dual turret specs. only, type 1)	0.001 mm or 0.0001 inches	Instant	M, E
B215	○		Z-axial width of the tool holder for the rear turret (Dual turret specs. only, type 1)	0.001 mm or 0.0001 inches	Instant	M, E
B216	○		Mounting position of the tool holder (Dual turret specs. only, type 2)	0.001 mm or 0.0001 inches	Instant	M, E
B217	○		X-axial width of the tool holder for the rear turret (Dual turret specs. only, type 2)	0.001 mm or 0.0001 inches	Instant	M, E
B218	○		Z-axial width of the tool holder for the rear turret (Dual turret specs. only, type 2)	0.001 mm or 0.0001 inches	Instant	M, E
B219	○		Mounting position of the tool holder (Dual turret specs. only, type 3)	0.001 mm or 0.0001 inches	Instant	M, E
B220	○		X-axial width of the tool holder for the rear turret (Dual turret specs. only, type 3)	0.001 mm or 0.0001 inches	Instant	M, E
B221	○		Z-axial width of the tool holder for the rear turret (Dual turret specs. only, type 3)	0.001 mm or 0.0001 inches	Instant	M, E
B222	○		Mounting position of the tool holder (Dual turret specs. only, type 4)	0.001 mm or 0.0001 inches	Instant	M, E
B223	○		X-axial width of the tool holder for the rear turret (Dual turret specs. only, type 4)	0.001 mm or 0.0001 inches	Instant	M, E

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B224	○		Z-axial width of the tool holder for the rear turret (Dual turret specs. only, type 4)	0.001 mm or 0.0001 inches	Instant	M, E
B225 B228	○					
B229	○	○	Opposed-turret mirror image Distance between the turrets	0.001 mm or 0.0001 inches	Instant	E
B230	○	○	Inclined Y-axis offsetting - Virtual Y-axis	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B231	○	○	Inclined Y-axis offsetting - Real X-axis	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B232	○	○	Inclined Y-axis offsetting - Real Y-axis	0.001 mm or 0.0001 inches	Power OFF → ON	M, E
B233	○		Pre-interpolation acceleration/deceleration: Target speed	mm/min or 0.1 inches/min	Instant	M, E
B234	○		Distance from reference workpiece zero point to center of milling rotation	0.001 mm or 0.0001 inches	Instant	M
B235	○		Correction value relating to the workpiece measuring sensor diameter for protrusion width measurement	0.001 mm or 0.0001 inches	Instant	M
B236	○		Correction value relating to the workpiece measuring sensor diameter for groove width measurement	0.001 mm or 0.0001 inches	Instant	M
B237	○	○	Measurement area for automatic tool offsetting X-axial direction	0.001 mm or 0.0001 inches	Instant	E
B238	○	○	Measurement area for automatic tool offsetting Z-axial direction	0.001 mm or 0.0001 inches	Instant	E
B239	○	○	Deceleration area setting for automatic tool offsetting X-axial direction	0.001 mm or 0.0001 inches	Instant	E
B240	○	○	Deceleration area setting for automatic tool offsetting Z-axial direction	0.001 mm or 0.0001 inches	Instant	E
B241	○	○	EIA chuck barrier: Jaw shape dimension A	0.001 mm or 0.0001 inches	Instant	E
B242	○	○	EIA chuck barrier: Jaw shape dimension B	0.001 mm or 0.0001 inches	Instant	E
B243	○	○	EIA chuck barrier: Jaw shape dimension C	0.001 mm or 0.0001 inches	Instant	E
B244	○	○	EIA chuck barrier: Jaw shape dimension D	0.001 mm or 0.0001 inches	Instant	E
B245	○	○	EIA chuck barrier: Jaw shape dimension E	0.001 mm or 0.0001 inches	Instant	E
B246	○	○	EIA chuck barrier: Holder mounting position	0.001 mm or 0.0001 inches	Instant	E
B247	○	○	EIA chuck barrier: X-axial width of the holder	0.001 mm or 0.0001 inches	Instant	E
B248	○	○	EIA chuck barrier: Z-axial width of the holder	0.001 mm or 0.0001 inches	Instant	E
B249	○	○	EIA chuck barrier Z-axial tool nose position	0.001 mm or 0.0001 inches	Instant	E
B250	○	○	EIA chuck barrier X-axial tool nose position	0.001 mm or 0.0001 inches	Instant	E
B251	○	○	EIA chuck barrier: Sub-chuck mounting position	0.001 mm or 0.0001 inches	Instant	E
B252	○	○	EIA tail barrier: Tail extruding length	0.001 mm or 0.0001 inches	Instant	E

2 PARAMETER LIST

Address	H1*	H2*	Outline	Unit	Effective condition	Applicable program (Note)
B253	○	○	EIA tail barrier: Workpiece length	0.001 mm or 0.0001 inches	Instant	E
B254	○	○	EIA tail barrier: Distance from the machine origin position to the leading edge position during tail reversing	0.001 mm or 0.0001 inches	Instant	E
B255	○	○	Spindle viscous friction coefficient "cms" for auto-pecking of the cutting load detection type	–	Instant	M
B256	○	○	Spindle coulombic friction coefficient "fms" for auto-pecking of the cutting load detection type	–	Instant	M
B257	○	○	X-axial tool reference position (For INTEGREG, ↓ turning tool)	0.001 mm or 0.0001 inches	Instant	M, E
B258	○	○	Z-axial tool reference position (For INTEGREG, ↓ turning tool)	0.001 mm or 0.0001 inches	Instant	M, E
B259	○		X-axial tool reference position (Only for INTEGREG, ← turning tool)	0.001 mm or 0.0001 inches	Instant	M, E
B260	○		Z-axial tool reference position (Only for INTEGREG, ← turning tool)	0.001 mm or 0.0001 inches	Instant	M, E
B261	○		X-axial tool reference position (Only for INTEGREG, ↓ milling tool)	0.001 mm or 0.0001 inches	Instant	M, E
B262	○		Z-axial tool reference position (Only for INTEGREG, ↓ milling tool)	0.001 mm or 0.0001 inches	Instant	M, E
B263	○		X-axial tool reference position (Only for INTEGREG, ← milling tool)	0.001 mm or 0.0001 inches	Instant	M, E
B264	○		Z-axial tool reference position (Only for INTEGREG, ← milling tool)	0.001 mm or 0.0001 inches	Instant	M, E
B265	○		Number of jaws to be used for displaying solids (No. 1 spindle)	–	Instant	M
B266	○		Number of jaws to be used for displaying solids (No. 2 spindle)	–	Instant	M
B267	○		Jaws offsets for displaying solids (No. 1 spindle)	0.1 deg	Instant	M
B268	○		Jaws offsets for displaying solids (No. 2 spindle)	0.1 deg	Instant	M
B269	○		X-axial tool reference position (Only for INTEGREG, → turning tool)	0.001 mm or 0.0001 inches	Instant	M, E
B270	○		Z-axial tool reference position (Only for INTEGREG, → turning tool)	0.001 mm or 0.0001 inches	Instant	M, E
B271	○		X-axial tool reference position (Only for INTEGREG, → milling tool)	0.001 mm or 0.0001 inches	Instant	M, E
B272	○		Z-axial tool reference position (Only for INTEGREG, → milling tool)	0.001 mm or 0.0001 inches	Instant	M, E

2-3 DATA INPUT/OUTPUT PARAMETER

Note: M: Valid only for MAZATROL Program
E: Valid only for EIA/ISO Program

Address	Outline	Unit	Effective condition	Applicable program (Note)
CMT1 CMT24				
CMT25 (bit 0)	Selection of loading tool data or tool offset data		I/O start	M, E
CMT25 (bit 1)	Selection of saving program with set up data		I/O start	M, E
CMT25 (bit 2)	Selection of loading tool data number and suffix		I/O start	M, E
CMT25 (bit 3)	Selection of loading pitch error compensation of machining parameter		I/O start	M, E
CMT25 (bit 4)	Selection of loading jaw data		I/O start	M, E
CMT26 CMT32				

Address	Outline	Unit	Effective condition	Applicable program (Note)
TAP1	Terminator type		I/O start	M, E
TAP2	Terminator code 1		I/O start	M, E
TAP3				
TAP4	Use/disuse of CR code output to paper tape punch		I/O start	M, E
TAP5	Selection of DC code parity		I/O start	M, E
TAP6	Feed control flag		I/O start	M, E
TAP7				
TAP8				
TAP9	Perforation pattern for “[“ code for EIA Transmission retry frequency for file transfer	–	I/O start	M, E
TAP10	Perforation pattern for “]“ code for EIA Acceptance retry frequency for file transfer	–	I/O start	M, E
TAP11	Perforation pattern for “#“ code for EIA Transmission retry frequency for command message transfer	–	I/O start	M, E
TAP12	Perforation pattern for “*“ code for EIA @ waiting time for DNC transfer	–	I/O start	M, E
TAP13	Perforation pattern for “=“ code for EIA TEXT, * waiting time for transfer	–	I/O start	M, E
TAP14	Perforation pattern for “:“ code for EIA TEXT, * waiting time for transfer	–	I/O start	M, E

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
TAP15 TAP24				
TAP25	Selection of parity V check		I/O start	M, E
TAP26 (bit 0)	Program name tape input/output valid or invalid		I/O start	M, E
TAP26 (bit 1)	Punching the setup information of PTP program valid or invalid		I/O start	M, E
TAP26 (bit 2)				
TAP26 (bit 3)				
TAP26 (bit 4)				
TAP26 (bit 5)				
TAP26 (bit 6)				
TAP26 (bit 7)	Selection of whether RTS/CTS control is to be conducted when "PTP DC control" is selected		I/O start	M, E
TAP27 (bit 0)	Selection of PTP program end code - O or :		I/O start	M, E
TAP27 (bit 1)				
TAP27 (bit 2)	Selection of PTP program end code - M199		I/O start	M, E
TAP27 (bit 3)	Selection of PTP program end code - M198		I/O start	M, E
TAP27 (bit 4)	Selection of PTP program end code - M99		I/O start	M, E
TAP27 (bit 5)	Selection of PTP program end code - M30		I/O start	M, E
TAP27 (bit 6)	Selection of PTP program end code - M02		I/O start	M, E
TAP27 (bit 7)	Character conversion I/O using an extension tape		I/O start	M, E
TAP28 (bit 0)	Protocol B function - start code		I/O start	E
TAP28 (bit 1)	Protocol B function - start DC3 output on completion		I/O start	E
TAP28 (bit 2)	Protocol B function - start DC1 output after NAK or SYN		I/O start	E
TAP28 (bit 3)	Protocol B function - start NC alarm (NAK) output		I/O start	E
TAP28 (bit 4)	Protocol B function - start NC reset (SYN) output		I/O start	E
TAP28 (bit 5)	Protocol B function - start Data code selection		I/O start	E
TAP28 (bit 6)				
TAP28 (bit 7)				

Address	Outline	Unit	Effective condition	Applicable program (Note)
TAP29	Number of space characters between work No. and data to be punched on paper tape	1 character	I/O start	M, E
TAP30	Number of space characters between programs to be punched on paper tape	1 character	I/O start	M, E
TAP31	Number of leading and tailing feed characters of paper tape	10 character	I/O start	M, E

Address	Outline	Unit	Effective condition	Applicable program (Note)
DNC1 DNC8				
DNC9	Transmission retry frequency for file transfer	Times	I/O start	M, E
DNC10	Acceptance retry frequency for file transfer	Times	I/O start	M, E
DNC11	Transmission retry frequency for command message transfer	Times	I/O start	M, E
DNC12	@ waiting time for transfer	0.1 sec	I/O start	M, E
DNC13	TEXT, * waiting time for transfer	0.1 sec	I/O start	M, E
DNC14	EOT waiting time for transfer	0.1 sec	I/O start	M, E
DNC15	Stop time after acceptance of ! for transfer	0.1 sec	I/O start	M, E
DNC16	Reset time after digital out for transfer	0.1 sec	I/O start	M, E
DNC17	Acceptance → transmission switching time for transfer	0.01 sec	I/O start	M, E
DNC18	Command response message waiting time for transfer	0.1 sec	I/O start	M, E
DNC19	Machine No. for DNC transfer		I/O start	M, E
DNC20				
DNC21	Stop time between EOT acceptance and * transmission for transfer	0.01 sec	I/O start	M, E
DNC22	Stop time between EOT transmission and * transmission for transfer	0.01 sec	I/O start	M, E
DNC23				
DNC24				
DNC25 (bit 0)	Selection of loading tool data or tool offset data		I/O start	M, E
DNC25 (bit 1)	Selection of saving program with set up data		I/O start	M, E
DNC25 (bit 2)	Selection of loading tool data number and suffix		I/O start	M, E
DNC25 (bit 3)	Selection of loading pitch error compensation of machine parameter		I/O start	M, E

2 PARAMETER LIST

Address	Outline	Unit	Effective condition	Applicable program (Note)
DNC25 (bit 4)	Selection of loading jaw data		I/O start	M, E
DNC25 (bit 5)				
DNC25 (bit 6)				
DNC25 (bit 7)	DNC alarm display selection		I/O start	M, E
DNC26 (bit 0)	Selection of work No. search after program reception		I/O start	M, E
DNC26 (bit 1)	Selection of DNC alarm display		I/O start	M, E
DNC26 (bit 2)	Selection of loading programs of stored work No.		I/O start	M, E
DNC26 (bit 3)	Selection of relieving program rewrite switch function		I/O start	M, E
DNC26 (bit 4)				
DNC26 (bit 5)	Selection of outputting data blocks with a data length of 0		I/O start	M, E
DNC26 (bit 6)	Selection of layout data size		I/O start	M, E
DNC26 (bit 7)	Selection of deleting all programs before work No. 9000 at the program reception start		I/O start	M, E
DNC27				
DNC28				
DNC29	DNC physical error detection repeat times	Times	I/O start	M, E
DNC30 DNC32				

Address	Outline	Unit	Effective condition	Applicable program (Note)
DPR1	Baud rate		I/O start	M, E
DPR2	Stop bit		I/O start	M, E
DPR3	Parity bit		I/O start	M, E
DPR4	Data bit		I/O start	M, E
DPR5 DPR8				
DPR10	Method of handshaking		I/O start	M, E
DPR11	Feed section DC code output		I/O start	M, E
DPR12	Waiting time	0.1 sec	I/O start	M, E
DPR13	Output format		I/O start	M, E
DPR14	Port selection		I/O start	M, E
DPR15	Number of characters in feed section	1 character	I/O start	M, E
DPR16				

- NOTE -

3 PARAMETER

Parameters are constants and various data required for setting machine and NC equipment operation modes required for machining.

When machines are delivered, parameters are set at factory. Some of them can be changed by the user.

If wrong values are set as parameter, operation of machines and NC equipment may be hampered. For changing parameters, their meaning and functions must be well understood.

This parameter list shows important parameters for the user. Those which the user hardly need change settings and those not used are omitted from the list. The meaning and functions of parameters are described only important points. If functions of parameters to be changed are not clearly understood, contact our service centers.

3-1 How to Use Parameter List

The parameters are listed in a form as shown below.


Title of display		(1)
(2)	(3)	
	Unit	(4)
	Effective condition	(5)
	Applicable program	(6)
(7)		

(1): Title of display showing required parameter

(2): Address (nomenclature) of required parameter

- Bit input type parameters have the bit No. shown in the parentheses below address.

Example:



(3): Meaning of required parameter

(4): Setting unit for parameter

(5): Conditions on which set value is effective

Example 1: “Instant” designates that new parameter value becomes effective upon parameter change.

Example 2: “Power OFF → ON” designates that new parameter value will become effective after procedure below.

- [1] Change parameter setting value.
↓ (By procedure similar to changing of ordinary data)
- [2] Press power off button on the operation panel.
↓
- [3] Press power on button on the operation panel.

Example 3: In the parameter list, “I/O start” means that the system operates at the parameter data entered before the start of I/O. If the parameter data is modified during I/O operation, the new data will not become valid until the I/O operation has been completed.

(6): Applicable program

M..... Effective only for MAZATROL programs

E Effective for EIA/ISO programs

M, E Effective for MAZATROL programs and EIA/ISO programs





(7): Description of required parameter

Relevant parameters are indicated in the parentheses at bottom.

Precautions

1. The type and setting value for required parameters may vary according to machine types, use/disuse of optional equipment and manufacturing time.
Values set for specific machines and NC equipment must not be used for other machines and NC equipment.
2. The factory set parameters are recorded on separate paper and stored inside the control cabinet. This paper must not be lost.
3. If parameter setting values are changed, values before and after the change must be recorded for storage.
4. If machines are not operated for a long time, battery backup may be lost and data will be destroyed (battery alarm indicated). In this case, confirm parameter setting values by referring to the parameter record paper. If machines are operated with data lost, error will be caused.




3-2 PARAMETER (USER, CUTTING P)



Title of display		PARAMETER (USER, CUTTING)		
Address	Meaning	Description		
P1 (bit 0)	Use/disuse of acceleration in up-going slope during rough cutting cycle in bar machining unit (BAR)	<p>P1 (bit 0) = 0: Disuse</p>  <p>No acceleration</p>		
		<p>P1 (bit 0) = 1: Use</p>  <p>$F_2 > F_1$ F_1: Feedrate for rough cutting cycle F_2: Feedrate after acceleration</p>		
		Unit	—	
		Effective condition	Instant	
Applicable programm	M	(⇒K2, K3)		
P1 (bit 1)	Use/disuse of deceleration in down-going slope during rough cutting cycle in bar machining unit (BAR)	<p>P1 (bit 1) = 0: Disuse</p>  <p>No deceleration</p>		
		<p>P1 (bit 1) = 1: Use</p>  <p>$F_3 < F_1$ F_1: Feedrate for rough cutting cycle F_3: Feedrate after deceleration</p>		
		Unit	—	
		Effective condition	Instant	
Applicable programm	M	(⇒K4, K5)		

NM211-00208

NM211-00209

PARAMETER (USER, CUTTING)

Address	Meaning	Description
P1 (bit 3)	Selection between use/disuse of acceleration distance check at start of thread cutting unit (THR)	<p>P1 (bit 3) = 0: Disuse Alarm not caused even if acceleration distance at start of thread cutting unit exceeds clamp data</p> <p>P1 (bit 3) = 1: Use Alarm caused when acceleration distance at start of thread cutting unit exceeds clamp data</p> <p>Example:</p>  <p style="text-align: right;">L_o : Acceleration distance L_c : Acceleration distance clamp data</p>
	Unit	—
	Effective condition	Instant
	Applicable program	M
		(⇒U38)
P1 (bit 4)	Selection between start position shift/start angle shift for thread number offset in thread cutting unit (THR)	<p>P1 (bit 4) = 0: Start position shift Thread number offset adjusted by moving thread cutting start position</p>  <p>P1 (bit 4) = 1: Start angle shift Thread number offset adjusted according to thread cutting start angle</p> 
	Unit	—
	Effective condition	Instant
	Applicable program	M

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P1 (bit 5)	Selection between whether or not tool should be returned to tool change position on M code unit (M) end		<p>P1 (bit 5) = 0: Not return Tool not moved from the end of the previous unit after completing M code unit (M)</p> <p>P1 (bit 5) = 1: Return Tool returned to tool change position after completing M code unit (M)</p> <p>(⇒P17)</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P1 (bit 6)	Selecting whether the spindle is to be stopped following completion of the END unit in which continuous machining is specified		<p>P1 (bit 6) = 0: The spindle stops.</p> <p>P1 (bit 6) = 1: The spindle does not stop.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P1 (bit 7)	Selection between whether or not tool should be returned to tool change position at program end for cycles except for final repetition of same program		<p>Tool will be moved to the following position after executing 1 to (N-1)th cycles if the program repetition frequency is represented by N ($N \geq 2$).</p> <p>P1 (bit 7) = 0: Return Tool always returned to tool change position for any location specified for program end unit (END)</p> <p>P1 (bit 7) = 1: Not return Tool always returned to position specified for program end unit (END)</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P2 (bit 0)	Selection for cutting path method in milling line machining unit (MGV, LCT, RGT, LFT)		<p>P2 (bit 0) = 0</p>  <p>P2 (bit 0) = 1: High speed mode</p> 
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P2 (bit 1)	Output/no output of spindle rotation command during manual program machining unit (MNP)		<p>P2 (bit 1) = 0: Output Output of M3, M4 or M5 according to tools assigned to manual program machining unit (MNP)</p> <p>P2 (bit 1) = 1: No output No output of spindle rotation command during manual program machining unit (MNP). Specify M3, M4 or M5.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P2 (bit 2)	Selection of whether the return to the tool change position is to be executed upon issuance of T-command with the same TNo. but followed different suffix.		<p>P2 (bit 2) = 0 The tool change position is not reached.</p> <p>P2 (bit 2) = 1 The tool change position is reached.</p> <p>This parameter is effective only for tools with suffix H or V of the V/H turret specifications.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P2 (bit 4)	Selection of whether the position of fixed point is to be shifted by an amount of A13		<p>P2 (bit 4) = 0 A13 is not added</p> <p>P2 (bit 4) = 1 A13 is added.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P2 (bit 5)	Selection of whether the position of the fixed point is to be shifted in the direction of the B-axis by an amount of parameter A13		<p>Select whether the position of fixed point is to be shifted in the direction of the B-axis by an amount of machine parameter A13 (Amount of shifting of the B-axis movement origin from machine home position reference).</p> <p>P2 (bit 5) = 0 Then the position of the fixed point is shifted without machine parameter A13 being added.</p> <p>P2 (bit 5) = 1 Then the position of the fixed point is shifted by an amount of machine parameter A13</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)																		
Address	Meaning		Description																	
P2 (bit 6) (bit 7)	Selecting an angle margin for nose shape compensation		An angle margin for nose shape compensation can be selected by setting data in bits 6 and 7. <table border="1" data-bbox="844 414 1332 613"> <thead> <tr> <th colspan="2">Setting</th> <th rowspan="2">Angle margin for nose shape compensation</th> </tr> <tr> <th>Bit 7</th> <th>Bit 6</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>3.0</td> </tr> <tr> <td>0</td> <td>1</td> <td>2.0</td> </tr> <tr> <td>1</td> <td>0</td> <td>1.0</td> </tr> <tr> <td>1</td> <td>1</td> <td>0.5</td> </tr> </tbody> </table>	Setting		Angle margin for nose shape compensation	Bit 7	Bit 6	0	0	3.0	0	1	2.0	1	0	1.0	1	1	0.5
	Setting			Angle margin for nose shape compensation																
	Bit 7	Bit 6																		
	0	0		3.0																
0	1	2.0																		
1	0	1.0																		
1	1	0.5																		
Unit	—																			
Effective condition	Instant																			
Applicable program	M																			
P3 (bit 0)	Use/disuse of Z offset check		P3 (bit 0) = 0: Disuse Even when Z offset of a program to be executed is not set, the machine can be started. P3 (bit 0) = 1: Use When Z offset of a program to be executed is not set, the machine cannot be started. (Pressing the start button gives an alarm.)																	
	Unit	—																		
	Effective condition	Instant																		
	Applicable program	M																		
P3 (bit 1)	Axis designation for TPS operation		P3 (bit 1) = 0 The X-, Z- and C-axes are designated for the position storage during TPS operation.																	
	Unit	—																		
	Effective condition	Instant																		
	Applicable program	M, E																		
P3 (bit 2)	Selection of whether the return to the tool change position is to be executed upon issuance of T-command with the same TNo. but followed by a different suffix.		P3 (bit 2) = 0 The tool change position is reached. However, if the tool set values and nose R of the previous tool and those of the command tool are same, the tool change position is not reached. P3 (bit 2) = 1 The tool change position is not reached. Pay careful attention to the possible interference, if the tool set values of the previous tool and those of the command tool differ from each other. (except H/V turret type machine)																	
	Unit	—																		
	Effective condition	Instant																		
	Applicable program	M																		

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P3 (bit 3)	Selection of whether the Y-axial return to zero point is to be executed at the start of MAZATROL program		At the start of MAZATROL program: P3 (bit 3) = 1 Return to Y-axis zero point P3 (bit 3) = 0 No return to Y-axis zero point
	Unit	—	Note: Only valid when the optional Y-axis control is available.
	Effective condition	Instant	
	Applicable program	M	
P3 (bit 4)	Selection of the method for approach/escape during mill-line centr machining		P3 (bit 4) = 0 (M PLUS method) Approach to a position of "start point in program + tool radius + clearance U10 " and escape from a position of "end point in program + tool radius + clearance U10 ". Approach point is automatically established. If an approach point is designated, routing via that point is realized. P3 (bit 4) = 1 (T PLUS method) Approach to the start point in program and escape from the end point in program. Approach point is not automatically established. Even if an approach point is designated, it will be ignored.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P3 (bit 5)	Data auto-setting method selection for TAP/MTP (pipe tapping)		P3 (bit 5) = 0: Conventional method P3 (bit 5) = 1: Text file registration data reference method Data that has been registered in the required text file is used for auto-setting of the lathe-turning tap unit (TAP) or milling tap unit (MTP) in PROGRAM display for MAZATROL programs.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P3 (bit 7)	Selection of G1 or G0 as the axial relief feed mode for linear machining		Select G0 or G1 as the axial relief feed mode for linear machining under the following conditions: - In the case of the tool name scheme, when G1 is selected using the AFD item of the tool sequence of the linear machining unit (ZY, /Y, XT mode) - In the case of the tool number scheme, when parameter K41 is not 0 P3 (bit 7) = 0 The axial relief feed mode becomes equal to G1. P3 (bit 7) = 1 The axial relief feed mode becomes equal to G0.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P4 (bit 1)	Selection of display type of tapping tool in solide mode		In the solide mode of TOOL PATH display: P4 (bit 1) = 0 Simplified display of tapping tool P4 (bit 1) = 1 Detailed display of tapping tool
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P5 (bit 3)	Spindle synchronizing pattern		During spindle-to-spindle rotational transfer in the TRS unit: P5 (bit 3) = 0: The spindles do not synchronize. P5 (bit 3) = 1: The spindles synchronize.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P6 (bit 0)	Selection of whether immediate indexing of the automatically selected spare tool is to be made valid or invalid.		P6 (bit 0) = 0: Invalid After tool change, the new tool is immediately selected and used. P6 (bit 0) = 1: Valid After tool change, the new tool is selected last in the same tool group. (⇒ P16 Bit 3)
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P6 (bit 1)	Selection of the order of spare tool selection - TNo. order or Equal life order		P6 (bit 1) = 0: TNo. order Tools are selected in normal ascending order of the tool number within the same tool group. P6 (bit 1) = 1: Equal life order Tools are selected in the order of residual tool life, that is magnitude of the data obtained by subtracting the cumulative operation time of each tool (or the number of machined workpieces for each tool) from the initial design lives of the tools (or the estimated number of machinable workpieces). (⇒ P16 Bit 3)
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P6 (bit 2)	Tool offset type selection - Type A or type B		<p>P6 (bit 2) = 0 Tool offset type with 1 offset category (type A) is selected.</p> <p>P6 (bit 2) = 1 Tool offset type with GEOMETRIC OFFSET + WEAR COMP. (type B) is selected.</p>
	Unit	—	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
P6 (bit 4)	Counting all types of use under the same tool number for the tool life management on the TOOL DATA display executed/not executed		<p>P6 (bit 4) = 0 Counting each type of use under the same tool number individually.</p> <p>P6 (bit 4) = 1 Counting all types of use under the same tool number integrately.</p> <p>For EIA programs, this parameter is only valid when P16 bit 3 = 0.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P6 (bit 5)	Name/ID No. selection on the TOOL DATA display		<p>P6 (bit 5) = 0 A name can be selected.</p> <p>P6 (bit 5) = 1 An ID number can be selected.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P6 (bit 7)	VISUAL TOOL MANAGER display valid/invalid		<p>P6 (bit 7) = 0: VISUAL TOOL MANAGER display invalid.</p> <p>P6 (bit 7) = 1: VISUAL TOOL MANAGER display valid.</p> <p>This display is only made with M640MT.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display	PARAMETER (USER, CUTTING)
-------------------------	----------------------------------




Address	Meaning	Description
P7 (bit 1)	Selection of a shape-drawing position for milling (Inverted vertical spindle lathe tool plate specifications)	<p>Select whether the shape-drawing position for milling is to be shifted through 180 deg (opposed side).</p> <p>P7 (bit 1) = 0: As before P7 (bit 1) = 1: The milling shape is drawn at the opposite side. (This parameter is valid only for tool plate specifications (opposed-turret specifications).)</p>
	Unit	—
	Effective condition	Instant
	Applicable program	M
P7 (bit 2)	Input digit quantity selection of infeed point coordinate	<p>The following values of digits can be set for items CPT-X and CPT-Z of bar cutting unit (BAR) and copy machining unit (CPY).</p> <p>P7 (bit 2) = 0 For millimeter specification: One decimal digit CPT-X 0.1 to 9999.9 CPT-Z -9999.9 to 9999.9 For inch specification: Two decimal digits CPT-X 0.01 to 999.99 CPT-Z -999.99 to 999.99</p> <p>P7 (bit 2) = 1 For millimeter specification: Two decimal digits CPT-X 0.01 to 999.99 CPT-Z -999.99 to 999.99 For inch specification: Three decimal digits CPT-X 0.001 to 99.999 CPT-Z -99.999 to 99.999</p>
	Unit	—
	Effective condition	Instant
	Applicable program	M

3 PARAMETER

Title of display		PARAMETER (USER, CUTTING)							
Address	Meaning	Description							
P7 (bit 3)	Selection of conditions capable of setting tool data	P7 (bit 3) = 0 Tool data can always be set on all items of TOOL DATA display (Compensation display) and the item "DIAMETER/NOSE-R" of TOOL DATA display (Shape information display). P7 (bit 3) = 1 O: Data setting possible ×: Data setting impossible							
		Machine status	Setting of reprogramming switch	TOOL DATA display (Compensation display)					
				TOOL SET	WEAR COMP.	MAX WEAR	LIFE	USED	TL EYE COMP.
		During automatic operation	LOCK	×	○	×	×	×	×
			ENABLE	×	○	×	×	×	×
		In automatic mode (program execution not in progress)	LOCK	×	○	×	×	○	×
			ENABLE	×	○	○	○	○	○
		During manual operation	LOCK	×	○	×	×	○	×
			ENABLE	○	○	○	○	○	○
		Machine status	Setting of reprogramming switch	TOOL DATA display (Shape information display)					
				DIAMETER/NOSE-RA.-R		Other items			
		During automatic operation	LOCK	○		×			
			ENABLE	○		×			
		In automatic mode (program execution not in progress)	LOCK	○		×			
ENABLE	○		○						
During manual operation	LOCK	○		×					
	ENABLE	○		○					
Unit	—								
Effective condition	Instant								
Applicable program	M, E								

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P7 (bit 4)	JAW SHAPE display name/code selection		P7 (bit 4) = 0 A name can be selected. P7 (bit 4) = 1 A code can be selected.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P8 (bit 3)	Tool nose position storage function valid/invalid on the TOOL OFFSET display		Select whether the tool nose position storage function is to be made valid or invalid on the TOOL OFFSET display. P8 (bit 3) = 0 : Invalid P8 (bit 3) = 1 : Valid
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P8 (bit 7)	Selection of use/disuse of tool identification code skip function		P8 (bit 7) = 0 : Disuse Cursor allowed to be positioned at item for tool identification code setting P8 (bit 7) = 1 : Use Cursor moved by skipping items for tool identification setting
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P9 (bit 0)	Command data execution as it is/at 10 times		P9 (bit 0) = 0 Command data without a decimal point is executed as it is. P9 (bit 0) = 1 Command data without a decimal point is executed at 10 times. Both functions are valid only for coordinate data setting.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display		PARAMETER (USER, CUTTING)																		
Address	Meaning		Description																	
P9 (bit 2)	Selection of G-code series A		<p>P9 (bit 2) = 0 G code in series A selected.</p> <p>P9 (bit 2) = 1 G code in series B selected.</p> <p>If both bits 2 and 3 of P9 are set to 0, then the G-codes of series B become valid.</p> <p>If both bits 2 and 3 of P9 are set to 1, then the G-codes of series C become valid.</p> <table border="1" data-bbox="802 633 1382 871"> <thead> <tr> <th colspan="2">Setting</th> <th rowspan="2">G-code series</th> </tr> <tr> <th>Bit 3</th> <th>Bit 2</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>B</td> </tr> <tr> <td>0</td> <td>1</td> <td>A</td> </tr> <tr> <td>1</td> <td>0</td> <td>B</td> </tr> <tr> <td>1</td> <td>1</td> <td>C</td> </tr> </tbody> </table>	Setting		G-code series	Bit 3	Bit 2	0	0	B	0	1	A	1	0	B	1	1	C
	Setting			G-code series																
	Bit 3	Bit 2																		
	0	0		B																
0	1	A																		
1	0	B																		
1	1	C																		
Unit	—																			
Effective condition	Instant																			
Applicable program	E																			
P9 (bit 3)	Selection of G-code series B																			
	Unit	—																		
	Effective condition	Instant																		
	Applicable program	E																		
P9 (bit 5)	Selection of the command type without decimal point		<p>P9 (bit 5) = 0: Not select Position command data without decimal point united by specified minimum input unit (0.01, 0.001, 0.0001 mm or inches)</p> <p>P9 (bit 5) = 1: Select Position command data without decimal point processed by 1mm or inch</p>																	
	Unit	—																		
	Effective condition	Instant																		
	Applicable program	E																		

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P9 (bit 6)	Selection of rapid traverse (G00) interpolation method between interpolation/independent axis		<p>P9 (bit 6) = 0: Interpolation</p>  <p>Start point</p> <p>End point</p> <p>Tool path</p> <p>Traverse from start point to end point by shortest passage below maximum rapid feedrate of each axis</p> <p>P9 (bit 6) = 1: Independent axis</p>  <p>Start point</p> <p>End point</p> <p>Tool path</p> <p>Traverse from start point to end point at rapid traverse speed for each axis</p> <p>Note: Required time for traverse from start point to end point is the same for both methods.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P9 (bit 7)	Address E specification for thread number/ lead in precision thread cutting command (G32)		<p>P9 (bit 7) = 0 Thread number specified per inch for address E in thread cutting command</p> <p>P9 (bit 7) = 1 Precision lead for address E in thread cutting command</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P10 (bit 0)	Selection of whether short-cutting is to be executed during circular milling (CIR)		<p>During circular milling pattern B:</p> <p>P10 (bit 0) = 0 Short-cutting is not executed.</p> <p>P10 (bit 0) = 1 Short-cutting is executed.</p> 
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P10 (bit 5)	Use/disuse of interruption prevention function		<p>P10 (bit 5) = 0: Disuse Alarm caused if cutting into workpiece is recognized in interruption check during nose R compensation, and relevant block not executed</p> <p>P10 (bit 5) = 1: Use Tool path automatically changed when cutting into workpiece is recognized in interruption check during nose R compensation</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P10 (bit 6)	Selection between return to referential point/by escape distance in deep hole drilling cycle (G83/G87)		<p>P10 (bit 6) = 0 Tool tip returned to R point after completing steps of deep drilling cycle, and next step executed</p> <p>P10 (bit 6) = 1 Tool tip returned by escape distance (U45) after completing steps of deep drilling cycle, and next step executed</p> <p>(⇒U45)</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P10 (bit 7)	Selection between initial point/referential point for tool return position at the end of drilling cycle (G80s)		<p>P10 (bit 7) = 0 Tool tip returned to initial point upon end of drilling cycle</p> <p>P10 (bit 7) = 1 Tool tip returned to R point upon end of drilling cycle</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P11 (bit 0)	Selection of initial G96 (allowed only in G code series A)		<p>P11 (bit 0) = 0: Not select Peripheral speed constant control cancel mode automatically selected upon power on</p> <p>P11 (bit 0) = 1: Select Peripheral speed constant control mode automatically selected upon power on</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P11 (bit 1)	Selection of initial G99 (allowed only in G code series A)		<p>P11 (bit 1) = 0 : Not select Asynchronous feed mode automatically selected upon power on</p> <p>P11 (bit 1) = 1 : Select Synchronous feed mode automatically selected upon power on</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P11 (bit 2)	Selection of initial G90 (allowed only in G code series B and C)		<p>P11 (bit 2) = 0 : Not select Incremental programming (G91) automatically selected upon power on</p> <p>P11 (bit 2) = 1 : Select Absolute programming (G90) automatically selected upon power on</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P11 (bit 4)	Use/disuse of high speed processing function during machine lock		<p>P11 (bit 4) = 0: Disuse Processing by time at feedrate specified in program even if program is executed by selecting machine lock function</p> <p>P11 (bit 4) = 1: Use Feedrate entirely changed to rapid traverse speed when program is executed by selecting machine lock function, and dwell time (G04) ignored</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P11 (bit 5)	Selection between whether or not intermediate point should be ignored during execution of reference return command (G28/G30)		<p>P11 (bit 5) = 0: Not ignored Tool tip returned to reference point by passing intermediate point specified in program</p> <p>P11 (bit 5) = 1: Ignored Tool tip returned to reference point by ignoring intermediate point specified in program</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	







Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P11 (bit 6)	Selection of whether the machine is to be brought to a macro single-block stop		<p>P11 (bit 6) = 0 The machine does not stop for each macro block during single-block operation.</p> <p>P11 (bit 6) = 1 The machine stops for each macro block during single-block operation.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P11 (bit 7)	Absolute/incremental axis name selection		<p>P11 (bit 7) = 0 Selection of absolute/incremental programming by G code</p> <p>P11 (bit 7) = 1 Selection of absolute/incremental programming by address X, Z, Y, C absolute programming U, W, V, H incremental programming</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P12 (bit 0)	Selection of positioning method during fixed cycle		<p>P12 (bit 0) = 0: G00 Traverse by G00 to drilling position during fixed cycle mode</p> <p>P12 (bit 0) = 1: Modal Traverse by selected modal G code (G00 or G01) to drilling position during fixed cycle mode</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P12 (bit 1)	Selection of whether or not G50 is used during G53 mode		<p>P12 (bit 1) = 0: Disuse G50 command not used during G53 mode</p> <p>P12 (bit 1) = 1: Use G50 command used during G53 mode</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P12 (bit 2)	Selection of initial G53		<p>P12 (bit 2) = 0: Not select G50 coordinate system selected initially</p> <p>P12 (bit 2) = 1: Select MAZATROL coordinate system selected initially</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P12 (bit 3)	Selection of initial G00		<p>P12 (bit 3) = 0: Not select G01 mode automatically selected upon power on</p> <p>P12 (bit 3) = 1: Select G00 mode automatically selected upon power on</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P12 (bit 5)	M3 (M203)/M4 (M204) (spindle rotation command) selection - output at hole bottom during tapping cycle		<p>P12 (bit 5) = 0 Output of M4 or M204 at hole bottom during tapping cycle (G84/G88) (for right-handed thread)</p> <p>P12 (bit 5) = 1 Output of M3 or M203 at hole bottom during tapping cycle (G84/G88) (for left-handed thread)</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P12 (bit 6)	Selection of the operation occurring during the control of the tool tip point when command G49 is issued (when the tool length offset value is canceled)		<p>Select the type of operation occurring during the control of the tool tip point when command G49 is issued (when the tool length offset value is canceled).</p> <p>P12 (bit 6) = 0 The axis moves according to the tool length offset value.</p> <p>P12 (bit 6) = 1 The axis does not move.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P12 (bit 7)	Selection of coordinate system type for controlling the tool tip point		Select the coordinate system type for controlling the tool tip point. P12 (bit 7) = 0 The table coordinate system that rotates according to the particular rotation of the C-axis is defined as the programming coordinate system. P12 (bit 7) = 1 The work coordinate system is defined as the programming coordinate system.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P13 (bit 0)	Use/disuse of compensation movement during T command		P13 (bit 0) = 0: Disuse Compensation movement not made on T command P13 (bit 0) = 1: Use Compensation movement made on T command
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P13 (bit 1)	Use/disuse of block stop after restart		P13 (bit 1) = 0 Block stop not used after restart P13 (bit 1) = 1 Block stop used after restart
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P13 (bit 2)	Use/disuse of automatic return on resuming program		P13 (bit 2) = 0: Disuse Not returned to program start upon program end P13 (bit 2) = 1: Use Program head automatically called upon program end
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P13 (bit 3)	Use/disuse of G00 dry run		P13 (bit 3) = 0: Disuse Rapid traverse speed not changed to dry run speed P13 (bit 3) = 1: Use Rapid traverse speed changed to manually adjusted dry run speed
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P13 (bit 4)	Use/disuse of dry run during thread cutting		P13 (bit 4) = 0: Disuse of dry run during thread cutting cycle P13 (bit 4) = 1: Use of dry run during thread cutting cycle
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P13 (bit 5)	Use/disuse of feed hold during thread cutting		P13 (bit 5) = 0 Disuse of feed hold during thread cutting cycle P13 (bit 5) = 1 Use of feed hold during thread cutting cycle
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P13 (bit 7)	Use/disuse of reverse rotation error prevention function during G46 mode		P13 (bit 7) = 0: Disuse Alarm caused if nose R compensation direction is reversed during G46 mode. P13 (bit 7) = 1: Use Alarm not caused even if nose R compensation direction is reversed during G46 mode.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	



Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description															
P14 (bit 4)	Whether the workpiece barriers are to be activated																
	Unit	—															
	Effective condition	Instant															
	Applicable program	M															
<p>P14 (bit 4) = 0 The workpiece barriers do not function.</p> <p>P14 (bit 4) = 1 The workpiece barriers function.</p> <p>This parameter is valid only for a MULTIPLEX.</p>																	
P14 (bit 5)	Nose R compensation change-over																
	Unit	—															
	Effective condition	Instant															
	Applicable program	E															
<p>P14 (bit 5) = 0: T32 interchangeable mode P14 (bit 5) = 1: Standard mode</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th style="width: 20%; text-align: center;">Parameter setting</th> <th style="width: 40%; text-align: center;">0</th> <th style="width: 40%; text-align: center;">1</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">Operational difference</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">Single-block stopping position of inserted block</td> <td style="text-align: center;">Succeeding the inserted block</td> <td style="text-align: center;">Preceding the inserted block</td> </tr> <tr> <td style="text-align: center;">Opposed-turret mirror image (in G68/G69 mode)</td> <td style="text-align: center;">Direction of compensation changes</td> <td style="text-align: center;">Nose R compensation is temporarily cancelled</td> </tr> <tr> <td style="text-align: center;">Straight lines with an intersection angle of 1 deg. or less</td> <td style="text-align: center;">  <p style="text-align: center;">Solid line: Tool path</p> </td> <td style="text-align: center;">  <p style="text-align: center;">Solid line: Tool path</p> </td> </tr> </tbody> </table>			Parameter setting	0	1	Operational difference			Single-block stopping position of inserted block	Succeeding the inserted block	Preceding the inserted block	Opposed-turret mirror image (in G68/G69 mode)	Direction of compensation changes	Nose R compensation is temporarily cancelled	Straight lines with an intersection angle of 1 deg. or less	 <p style="text-align: center;">Solid line: Tool path</p>	 <p style="text-align: center;">Solid line: Tool path</p>
Parameter setting	0	1															
Operational difference																	
Single-block stopping position of inserted block	Succeeding the inserted block	Preceding the inserted block															
Opposed-turret mirror image (in G68/G69 mode)	Direction of compensation changes	Nose R compensation is temporarily cancelled															
Straight lines with an intersection angle of 1 deg. or less	 <p style="text-align: center;">Solid line: Tool path</p>	 <p style="text-align: center;">Solid line: Tool path</p>															
P14 (bit 6)	Selection as to handling of leading zeros in the DPRNT command mode																
	Unit	—															
	Effective condition	Instant															
	Applicable program	E															
<p>P14 (bit 6) = 0 Leading zeros are omitted.</p> <p>P14 (bit 6) = 1 Leading zeros are replaced with spaces.</p>																	

Title of display		PARAMETER (USER, CUTTING)		
Address	Meaning		Description	
P14 (bit 7)	Selecting a method of updating data during automatic nose measurement (for EIA)		<p>P14 (bit 7) = 0: Incremental method</p> <p>1. Normal tool (without reference tool) ·· B14 = 0</p> <p>Addition New offset value X or Z = Former offset value X or Z + Compensation value X or Z</p> <p>Subtraction New offset value X or Z = Former offset value X or Z – Compensation value X or Z</p> <p>2. Reference tool..... B14 = Value of address P</p> <p>Addition New offset value X or Z = Former offset value X or Z + Compensation value X or Z</p> <p>Subtraction New offset value X or Z = Former offset value X or Z – Compensation value X or Z</p> <p>3. Normal tool (with reference tool)</p> <p>B14 ≠ value of address P, B14 ≠ 0</p> <p>Addition New offset value X or Z = Former offset value X or Z + (Compensation value X or Z – Reference tool offset value X or Z)</p> <p>Subtraction New offset value X or Z = Former offset value X or Z – (Compensation value X or Z – Reference tool offset value X or Z)</p> <p>P14 (bit 7) = 1: Absolute method</p> <p>1. Normal tool (without reference tool) ·· B14 = 0</p> <p>New offset value X or Z = Compensation value X or Z</p> <p>2. Reference tool..... B14 = Value of address P</p> <p>New offset value X or Z = Compensation value X or Z</p> <p>1. Normal tool (with reference tool)</p> <p>B14 ≠ value of address P and B14 ≠ 0</p> <p>New offset value X or Z = Compensation value X or Z – Reference tool offset value X or Z</p>	
	Unit	—		
	Effective condition	Instant		
	Applicable program	E		
P15 (bit 0)	Overriding valid/invalid of the return speed during a synchronous tapping (parameter K70)		<p>P15 (bit 0) = 0</p> <p>Return speed overriding becomes valid.</p> <p>P15 (bit 0) = 1</p> <p>Return speed overriding becomes invalid.</p> <p>(⇒ J22)</p>	
	Unit	—		
	Effective condition	Instant		
	Applicable program	E		
P15 (bit 1)	Simplified wear offsetting valid/invalid		<p>P15 (bit 1) = 0 : (invalid)</p> <p>Time, quantity, and wear offset data become the basis for offsetting</p> <p>P15 (bit 1) = 1 : (valid)</p> <p>Simplified wear offsetting is used.</p>	
	Unit	—		
	Effective condition	Instant		
	Applicable program	M, E		



Title of display		PARAMETER (USER, CUTTING)														
Address	Meaning		Description													
P15 (bit 2)	Method of entering tool position offset data in X-axis direction - Entry in diameter/radius		<p>P15 (bit 2) = 0 The amount of offsetting can be entered in diameter.</p> <p>P15 (bit 2) = 1 The amount of offsetting can be entered in radius.</p>													
	Unit	—														
	Effective condition	Instant														
	Applicable program	E														
P15 (bit 3)	Selection of the minimum data unit for secondary auxiliary functions.		<p>P15 (bit 3) = 0: 0.001</p> <p>P15 (bit 3) = 1 Same as the entered unit 0.001 if metric, or 0.0001 if inch</p> <p>Example: B1 command</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td colspan="2" rowspan="2"></td> <td colspan="2">Setting</td> </tr> <tr> <td>0</td> <td>1</td> </tr> <tr> <td rowspan="2">Output</td> <td>Metric</td> <td>1000</td> <td>1000</td> </tr> <tr> <td>Inch</td> <td>1000</td> <td>10000</td> </tr> </table>			Setting		0	1	Output	Metric	1000	1000	Inch	1000	10000
						Setting										
				0	1											
	Output	Metric		1000	1000											
Inch		1000	10000													
Unit	—															
Effective condition	Instant															
Applicable program	E															
P15 (bit 4)	Address selection for direct input of chamfered corner R curved surface dimensions		<p>P15 (bit 4) = 0 (I), (K), (R), (,R), (,C) and (,A) can be used.</p> <p>P15 (bit 4) = 1 (R), (C) and (A) can be used.</p>													
	Unit	—														
	Effective condition	Instant														
	Applicable program	E														
P15 (bit 5)	Selection of whether tool shape offsetting is to be cancelled with offset number 0.		<p>P15 (bit 5) = 0 Tool shape offsetting is not cancelled with offset number 0.</p> <p>P15 (bit 5) = 1 Tool shape offsetting is cancelled with offset number 0.</p>													
	Unit	—														
	Effective condition	Instant														
	Applicable program	E														

PARAMETER (USER, CUTTING)

Address	Meaning	Description
P15 (bit 6)	Selection of a tool shape offsetting method	<p>P15 (bit 6) = 0 Tool shape offsetting is accomplished by shifting the coordinate system. (The current position is displayed in strict accordance with the program-designated data.)</p> <p>P15 (bit 6) = 1 Tool shape offsetting is accomplished by moving the tool. (The current position of the data having the tool compensation amount added to the program-designated data is displayed.)</p> <p><Program example> <Offset No.1> N1 T0101 X = 10 Z = 5 N2 G1X30.Z30.</p> <p style="text-align: center;">Program reference</p>  <p>P15 (bit 6) = 1 At the end of N2 Current position (X, Z)=(40, 35) Machine position (X, Z)=(40, 35)</p> <p>P15 (bit 6) = 0 At the end of N2 Current position (X, Z)=(30, 30) Machine position (X, Z)=(40, 35)</p> 
	Unit	—
	Effective condition	Instant
	Applicable program	E
P16 (bit 0)	Use/disuse of in-position check	<p>P16 (bit 0) = 0 In-position check not executed</p> <p>P16 (bit 0) = 1 In-position check executed</p> <p>Note: Refer to M51 and M52 of M Code List.</p>
	Unit	—
	Effective condition	Instant
	Applicable program	M, E

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P16 (bit 4)	Macro interrupt valid/invalid		<p>P16 (bit 4) = 0 Macro interrupt signals are not used to make macro interrupt program execution invalid</p> <p>P16 (bit 4) = 1 Macro interrupt signals are used to make macro interrupt program execution valid.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P16 (bit 5)	Selection of the type of interrupt program call for macro interruption - Macro type or subprogram type		<p>P16 (bit 5) = 0 Macro type (G65) [arguments can be used].</p> <p>P16 (bit 5) = 1 Subprogram type (M98) [arguments cannot be used].</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P16 (bit 6)	Whether local variables are to be cleared by resetting		<p>P16 (bit 6) = 0 Local variables from #1 to #33 are not cleared to <voids> by resetting.</p> <p>P16 (bit 6) = 1 Local variables from #1 to #33 are cleared to <voids> by resetting.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P16 (bit 7)	Whether common variables are to be cleared by resetting		<p>P16 (bit 7) = 0 Common variables from #100 to #149 are not cleared to <voids> by resetting.</p> <p>P16 (bit 7) = 1 Common variables from #100 to #149 are cleared to <voids> by resetting.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	


Title of display **PARAMETER (USER, CUTTING)**


Address	Meaning	Description																														
P17	<p>Selection of tool change position specification code</p>  <p style="font-size: small;">Zc : Stock material edge projection length Dmax : Stock material maximum outside diameter beta_x : Tool turning clearance (X-axis) U1/2 beta_z : Tool turning clearance (Z-axis) U2 Lx : Length of the longest tool in X direction Lz : Length of the longest tool in Z direction</p> <p style="font-size: x-small;">NM211-00215</p>	<p>Specify tool change position from 1 through 8 below.</p> <table border="1" style="width: 100%; border-collapse: collapse; font-size: x-small;"> <thead> <tr> <th>Setting</th> <th>X-axis</th> <th>Z-axis</th> </tr> </thead> <tbody> <tr><td>0</td><td>Clearance position</td><td>Clearance position</td></tr> <tr><td>1</td><td>Machine origin point</td><td>Clearance position</td></tr> <tr><td>2</td><td>Clearance position</td><td>Machine origin point</td></tr> <tr><td>3</td><td>Machine origin point</td><td>Machine origin point</td></tr> <tr><td>4</td><td>Fixed point</td><td>Fixed point</td></tr> <tr><td>5</td><td>Clearance position</td><td>End point of previous machining</td></tr> <tr><td>6</td><td>Machine origin point</td><td>End point of previous machining</td></tr> <tr><td>7</td><td>End point of previous machining</td><td>Clearance position</td></tr> <tr><td>8</td><td>End point of previous machining</td><td>Machine origin point</td></tr> </tbody> </table> <p>Note: P17=5 or 6, Z-axis tool change position is identical with the end point of previous machining. In the case below, however, this may not be applied. As shown here, if the longest tool comes into the hatched portion, the position will escape in Z-axis direction by the distance determined by U2.</p>  <p style="font-size: x-small; text-align: right;">NM211-00216</p>	Setting	X-axis	Z-axis	0	Clearance position	Clearance position	1	Machine origin point	Clearance position	2	Clearance position	Machine origin point	3	Machine origin point	Machine origin point	4	Fixed point	Fixed point	5	Clearance position	End point of previous machining	6	Machine origin point	End point of previous machining	7	End point of previous machining	Clearance position	8	End point of previous machining	Machine origin point
	Setting	X-axis	Z-axis																													
	0	Clearance position	Clearance position																													
	1	Machine origin point	Clearance position																													
2	Clearance position	Machine origin point																														
3	Machine origin point	Machine origin point																														
4	Fixed point	Fixed point																														
5	Clearance position	End point of previous machining																														
6	Machine origin point	End point of previous machining																														
7	End point of previous machining	Clearance position																														
8	End point of previous machining	Machine origin point																														
Unit	—																															
Effective condition	Instant	(⇒ U1, U2, A5)																														
Applicable program	M																															


PARAMETER (USER, CUTTING)



Address	Meaning	Description												
P18	Selection of spare tool indexing condition	<p>Select spare tool indexing conditions below.</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <thead> <tr> <th style="width: 15%;">Setting</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td>Indexing of spare tool when number of machined workpieces has reached limit</td> </tr> <tr> <td style="text-align: center;">2</td> <td>Indexing of spare tool when tool use time has reached limit</td> </tr> <tr> <td style="text-align: center;">4</td> <td>Indexing of spare tool when tool wear amount X has exceeded limit</td> </tr> <tr> <td style="text-align: center;">8</td> <td>Indexing of spare tool when tool wear amount Z has exceeded limit</td> </tr> <tr> <td style="text-align: center;">16</td> <td>Indexing of spare tool when tool wear amount Y has exceeded limit</td> </tr> </tbody> </table> <p>To combine the several conditions listed above, set the sum total of setting numbers corresponding the conditions to be selected.</p> <p>Example: To combine the workpiece machining quantity and tool wear amount X, set 5 (1 + 4).</p>	Setting	Description	1	Indexing of spare tool when number of machined workpieces has reached limit	2	Indexing of spare tool when tool use time has reached limit	4	Indexing of spare tool when tool wear amount X has exceeded limit	8	Indexing of spare tool when tool wear amount Z has exceeded limit	16	Indexing of spare tool when tool wear amount Y has exceeded limit
	Setting	Description												
	1	Indexing of spare tool when number of machined workpieces has reached limit												
	2	Indexing of spare tool when tool use time has reached limit												
4	Indexing of spare tool when tool wear amount X has exceeded limit													
8	Indexing of spare tool when tool wear amount Z has exceeded limit													
16	Indexing of spare tool when tool wear amount Y has exceeded limit													
Unit	—													
Effective condition	Instant													
Applicable program	M, E													
P19	Selection of data unit system (metric or inch)	<p>Specify input data unit system.</p> <p>P19 = 0 Data input in mm Minimum command unit0.001 mm</p> <p>P19 = 1 Data input in inch Minimum command unit0.0001 inches</p> <p>P19 = 2 Data input in mm Minimum command unit0.0001 mm</p> <p>P19 = 3 Data input in inch Minimum command unit0.00001 inches</p> <p>P19 = 5 A rotational speed of 88 min⁻¹ or more can be specified for the C-axis (rotational axis) under the inch specifications of the machine. To specify a rotational speed of 88 min⁻¹ or more, enter C-axial feed command data without a decimal point.</p> <p>Example: To specify 400 min⁻¹ (144000 deg/min) as the rotational speed, enter feed command F as shown below. F = 400 × 360 × 100 = 14400000</p> <p>Notes:</p> <ol style="list-style-type: none"> 1. When this parameter is changed, data below must also be changed. <ul style="list-style-type: none"> - Parameters whose data are to be recorded for mm and inch. - Cutting condition data Mere change of P19 will not convert automatically above data. 2. The setting of P19 = 2 or 3 is for EIA/ISO programs only. MAZATROL programs cannot be executed with this setting. 3. In the case of P19 = 5, the rotational speed is limited according to the particular specifications of the machine. 												
	Unit	—												
	Effective condition	Power OFF → ON												
	Applicable program	E												

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning		Description
P20	Measurement retry frequency in C offset measurement unit (MES-COF)		When touch sensor is actuated before reaching target point in C offset measurement, set retry frequency. P20 is set to N (N=0~3), measurement alarm will be indicated when touch sensor is actuated before reaching measurement target point in (N+1)th retry operation. (⇒U61)
	Unit	Times	
	Effective condition	Instant	
	Applicable program	M	
P21	Selection of separating ratio of GRAPHIC display		Selection of separation ratio between side view and front view (or rear view) when two split plane indication mode has been selected. P21 = 0 1:1 P21 = 1 2:1 P21 = 2 5:1 Example: P21 = 1 <div style="text-align: center;">  </div> NM211-00217
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P22	Tool command time for simulation		Setting of T command execution time (tool change time) at 0.05 sec intervals for simulation Example: Set 20 for 1 sec, and 20 × N for N sec.
	Unit	0.05 sec	
	Effective condition	Instant	
	Applicable program	M	


Title of display		PARAMETER (USER, CUTTING)											
Address	Meaning		Description										
P23	Auxiliary command time for simulation		Setting of M code and gear change execution time at 0.05 sec intervals for simulation										
	Unit	0.05 sec											
	Effective condition	Instant											
	Applicable program	M											
P24	Dwell (specification of spindle rotation number) at groove bottom in groove cutting unit (GRV)		Tool will stop at groove bottom while spindle rotates N times when P24 is set to N (N = 0 to 255).  Remaining at groove bottom until the spindle rotates N times. NM211-00218										
	Unit	Revolutions											
	Effective condition	Instant											
	Applicable program	M											
P26	Selection of escape pattern from wall (90°) in rough cutting cycle		This parameter will be used to select escape pattern (0, 1 or 2) when wall is vertical in G71/G72 mode. P26 = 0Identical with ordinary path P26 = 1Escape at 45° from wall P26 = 2Feedrate accelerated at wall Accelerated feedrate F is expressed as follows. $F = F_0 \times \frac{K3}{100}$ (where F ₀ =Feedrate specified in program) (⇒K3)										
	Unit	—											
	Effective condition	Instant											
	Applicable program	E											
P27	Specification of first M code for milling axis gear selection		This parameter automatically determines milling axis gear. Output M code will be as shown below if P27 is set to n. <table border="1" data-bbox="813 1668 1364 1758"> <thead> <tr> <th>Gear</th> <th>1st step</th> <th>2nd step</th> <th>3rd step</th> <th>4th step</th> </tr> </thead> <tbody> <tr> <td>M code</td> <td>n</td> <td>n + 1</td> <td>n + 2</td> <td>n + 3</td> </tr> </tbody> </table>	Gear	1st step	2nd step	3rd step	4th step	M code	n	n + 1	n + 2	n + 3
	Gear	1st step		2nd step	3rd step	4th step							
	M code	n		n + 1	n + 2	n + 3							
	Unit	—											
Effective condition	Instant												
Applicable program	M												

Title of display		PARAMETER (USER, CUTTING)											
Address	Meaning		Description										
P28	Specification of first M code for spindle gear selection		This parameter automatically determines spindle gear. Output M code will be as shown below if P28 is set to n. <table border="1" data-bbox="805 409 1353 488"> <thead> <tr> <th>Gear</th> <th>1st step</th> <th>2nd step</th> <th>3rd step</th> <th>4th step</th> </tr> </thead> <tbody> <tr> <td>M-code</td> <td>n</td> <td>n + 1</td> <td>n + 2</td> <td>n + 3</td> </tr> </tbody> </table>	Gear	1st step	2nd step	3rd step	4th step	M-code	n	n + 1	n + 2	n + 3
	Gear	1st step		2nd step	3rd step	4th step							
	M-code	n		n + 1	n + 2	n + 3							
	Unit	—											
Effective condition	Instant												
Applicable program	M												
P29	Specification of first M code for parts catcher control		It is a parameter to automatically control the parts catcher. If the set value of P29 is set to n, M code of No. n (parts catcher forward) is outputted at the start of cutting off (GRV #4, #5), and M code of No. n+1 (Parts catcher backward) is outputted at the end.										
	Unit	—											
	Effective condition	Instant											
	Applicable program	M											
P30	Threading chamfering angle		Set chamfering angle at thread portion in thread cutting cycle (G76/G92)  <p style="text-align: right;">NM211-00219</p>										
	Unit	Degree											
	Effective condition	Instant											
	Applicable program	E											
P31	Simultaneous operation pattern for transfer		Simultaneous operation pattern for transfer of workpieces between two unit jobsites P31 = 1 Rotation of the spindle and movement of the Z-axis P31 = 2 Orientation of the spindle and movement of the Z-axis P31 = 4 Positioning of the C-axis and movement of the Z-axis simultaneously occur. Note: To combine patterns, set the sum total of setting numbers corresponding the conditions.										
	Unit	—											
	Effective condition	Instant											
	Applicable program	M											

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P32	Threading termination waiting time processing		Set a threading termination waiting time. P32 = 0 - 1 128 - 256 No waiting time P32 = 2 - 127 (Setting - 1) × 3.5 msec
	Unit	3.5 msec	
	Effective condition	Instant	
	Applicable program	M	
P33	Number of times of roughing in the composite-type fixed cycle (G73)		If the number of times of roughing has not been specified in the program, operation will occur in accordance with the setting of this parameter. 
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P34	Final finishing repeat times in the composite-type fixed cycle (G76)		If the number of times of repetition has not been specified in the program, operation will occur in accordance with the setting of this parameter. 
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P35 P36 P37	Maximum workpiece length range on the CUT LEARN display		These parameters specify the maximum workpiece length range to be displayed on the CUT LEARN display. Data must be set so that a relational expression of P35 < P36 < P37 holds.
	Unit	mm or 0.1 inches	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P38 P39 P40	Maximum workpiece outside diameter range on the CUT LEARN display		<p>These parameters specify the maximum workpiece outside diameter range to be displayed on the CUT LEARN display.</p> <p>Data must be set so that a relational expression of P38 < P39 < P40 holds.</p>
	Unit	mm or 0.1 inches	
	Effective condition	Instant	
	Applicable program	M	
P41 P42	Macro call G code		<p>Set the G-code to be used for macro call.</p> <p>The macroprogram number corresponding to this G-code is to be set in parameter P49 or P50.</p> <p>Note: This section is a continuing part of the section of parameters K81 - K88.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P43 P44 P45 P46 P47	Macro call M code		<p>Set the M-code to be used for macro call.</p> <p>The macroprogram number corresponding to this M-code is to be set in parameter P51, P52, P53, P54 and P55.</p> <p>Note: This section is a continuing part of the section of parameters K89 - K93.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P49 P50	Macro program number corresponding to the macro call G code		<p>Set the macroprogram number corresponding to the G-code to be used for macro call.</p> <p>The parameters P49 and P50 correspond with the parameters P41 and P42 respectively.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	



Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P51 P52 P53 P54 P55	Macro program number corresponding to the macro call M code		Set the macroprogram number corresponding to the M-code to be used for macro call. The parameters P51 - P55 correspond with the parameters P43 and P47 respectively.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P57 P58 P59	Subprogram call M-code		Set the M-code to be used for subprogram call. The subprogram number corresponding to this M-code is to be set in parameter P60 , P61 and P62 .
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P60 P61 P62	Subprogram number corresponding to the subprogram call M code		Set the subprogram number corresponding to the M-code to be used for subprogram call. The parameters P60 , P61 and P62 correspond with the parameters P57 , P58 and P59 .
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P63	Upward cutting speed for inside threading (THR IN)		Specify the upward cutting speed for inside threading. - Valid only when chamfering is not specified by the THR IN unit in the MAZATROL program. - Valid only when bit 2 of parameter P111 is set to 1 (that is, the upward cutting speed for inside threading is valid). - If bit 2 of parameter P111 is set to 0, the upward cutting speed for inside threading will be the same as the setting of parameter A4 . - If the setting of this P63 parameter is 0, the upward cutting speed will be 1/4 of the A1 parameter setting.
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P65	Selection about tape operation mode data input		Select from where the program is to be read during the tape operation mode. P65 = 0 The program to be executed will be read from the tape reader. P65 = 1 The program to be executed will be read from the operating area of the hard disk.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P66	Method of judging whether the life of the tool is approaching		P66 = 0 When the rate of the cumulative operating time of the tool to its estimated life decreases below the value of P67 , the system will judge the life of that tool to be approaching. P66 = 1 When the residual life of the tool decreases below the value of P67 , the system will judge the life of that tool to be approaching.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P67	Criteria for judging whether the life of the tool is approaching		When P66 = 0 When the rate of the cumulative operating time of the tool to its estimated life decreases below the setting of this parameter, the system will judge the life of that tool to be approaching. When P66 = 1 When the residual life of the tool decreases below the setting of this parameter, the system will judge the life of that tool to be approaching. The above judgement is not applied when P67 = 0
	Unit	% or minute	
	Effective condition	Instant	
	Applicable program	M	
P73	Number of times of pecking up to the return of the tool to a position near the starting point of the #4 or #[4] very-deep-hole drilling cycle of a DRL or MDR unit		Set the number of times of pecking to be executed before returning the tool to a position near the starting point of the #4 or #[4] very-deep-hole drilling cycle of a DRL or MDR unit. Example: If P73 = 3 : 
	Unit	Times	
	Effective condition	Instant	
	Applicable program	M	


Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P74	Tool drawing accuracy in solid mode		As a larger value is set here, drawing accuracy increases in solid mode of TOOL PATH display.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P76	Selection of the shape correction function of the MAZATROL program		To select whether the shape correction function of the MAZATROL program is always effective or ineffective. 0: Ineffective 1: Effective
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P77	Selection of whether the C-axis on the WORK OFFSET display for the No. 2 spindle is to be made valid or invalid		Use P77 to select whether the C-axis that has been set on the WORK OFFSET display valid or invalid for the spindle No. 2 of the machine equipped with the C-axis or of the machine provided with a 0.001-degree index (orientation) function. 0: Invalid 1: Valid
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description																														
P95	<p>Selection of tool change position specification code for FLASH-tool or multi-tool holder</p>	<p>When a FLASH-tool or multi-tool holder is used, specify the position for indexing the tool, namely, the tool change position for indexing the tool of the same TNo. at the same B-axis angle during programmed operation.</p> <p>In all other cases, the tool change position specified by P17 becomes valid.</p>																														
	<p style="text-align: center;">NM211-00215</p>	<p>Zc : Stock material edge projection length Dmax : Stock material maximum outside diameter βx : Tool turning clearance (X-axis) U1/2 βz : Tool turning clearance (Z-axis) U2 Lx : Length of the longest tool in X direction Lz : Length of the longest tool in Z direction</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th style="width: 10%;">Setting</th> <th style="width: 40%;">X-axis</th> <th style="width: 50%;">Z-axis</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Clearance position</td> <td>Clearance position</td> </tr> <tr> <td>1</td> <td>Machine origin point</td> <td>Clearance position</td> </tr> <tr> <td>2</td> <td>Clearance position</td> <td>Machine origin point</td> </tr> <tr> <td>3</td> <td>Machine origin point</td> <td>Machine origin point</td> </tr> <tr> <td>4</td> <td>Fixed point</td> <td>Fixed point</td> </tr> <tr> <td>5</td> <td>Clearance position</td> <td>End point of previous machining</td> </tr> <tr> <td>6</td> <td>Machine origin point</td> <td>End point of previous machining</td> </tr> <tr> <td>7</td> <td>End point of previous machining</td> <td>Clearance position</td> </tr> <tr> <td>8</td> <td>End point of previous machining</td> <td>Machine origin point</td> </tr> </tbody> </table> <p>Note: When P95=5 or 6, Z-axis tool change position is identical with the end point of previous machining. In the case below, however, this may not be applied. As shown here, if the longest tool comes into the hatched portion, the position will escape in Z-axis direction by the distance determined by U2.</p> <p style="text-align: right;">NM211-00216</p>	Setting	X-axis	Z-axis	0	Clearance position	Clearance position	1	Machine origin point	Clearance position	2	Clearance position	Machine origin point	3	Machine origin point	Machine origin point	4	Fixed point	Fixed point	5	Clearance position	End point of previous machining	6	Machine origin point	End point of previous machining	7	End point of previous machining	Clearance position	8	End point of previous machining	Machine origin point
	Setting	X-axis	Z-axis																													
0	Clearance position	Clearance position																														
1	Machine origin point	Clearance position																														
2	Clearance position	Machine origin point																														
3	Machine origin point	Machine origin point																														
4	Fixed point	Fixed point																														
5	Clearance position	End point of previous machining																														
6	Machine origin point	End point of previous machining																														
7	End point of previous machining	Clearance position																														
8	End point of previous machining	Machine origin point																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">Unit</td> <td style="text-align: center;">—</td> </tr> <tr> <td>Effective condition</td> <td style="text-align: center;">Instant</td> </tr> <tr> <td>Applicable program</td> <td style="text-align: center;">M</td> </tr> </table>	Unit	—	Effective condition	Instant	Applicable program	M	<p>(⇒ U1, U2, A5)</p>																									
Unit	—																															
Effective condition	Instant																															
Applicable program	M																															


Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P97	Cutting depth in the composite-type fixed cycle (G71/G72)		If a cutting depth has not been specified in the program, operation will occur in accordance with the setting of this parameter. 
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	E	
P98	Amount of escape in an X-axial direction during the composite-type fixed cycle (G73)		If the amount of escape has not been specified in the program, operation will occur in accordance with the setting of this parameter. 
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	E	
P99	Amount of escape in a Z-axial direction during the composite-type fixed cycle (G73)		
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	E	
P100	Pitch of tapping tool for display in detail in solid mode		Set the pitch of tapping tool displayed when the tapping tool is displayed in detail (P4 bit 1 = 1) in solid mode on TOOL PATH display.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P101	Thread depth of tapping tool for display in detail in solid mode		Set the thread depth of tapping tool displayed when the tapping tool is displayed in detail (P4 bit 1 = 1) in solid mode on TOOL PATH display.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
P105 (bit 1)	EIA macroprogram call help function valid/invalid in MAZATROL screen mode		Select whether to make valid or invalid the function for supporting the entry of macrovariables by displaying argument information and special help screen information when calling up an EIA macroprogram as a subprogram from the MAZATROL program. If P105 (bit 1) = 0 : Invalid If P105 (bit 1) = 1 : Valid
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P105 (bit 2)	Cutting conditions studying function valid or invalid		If P105 (bit 2) = 0 : Invalid If P105 (bit 2) = 1 : Valid
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P105 (bit 3)	Fixed-amount offset function valid or invalid		If P105 (bit 3) = 0 : Invalid If P105 (bit 3) = 1 : Valid
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P105 (bit 4)	Whether the movable range of the inclined Y-axis is to be drawn on the TRACE display		If P105 (bit 4) = 0 : Not drawn If P105 (bit 4) = 1 : Drawn Example of drawing: 
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P105 (bit 6)	Text input/output valid/invalid for data I/O		P105 (bit 6) = 0: The text input/output functions are invalid for hard disk, floppy disk, or memory card I/O. P105 (bit 6) = 1: The text input/output functions are valid for hard disk, floppy disk, or memory card I/O.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P106 (bit 0)	Handling when the lives of all the same group number tools are reached in a standard EIA/ISO mode		If P106 (bit 0) = 0: An alarm will result when all tools reach their respective lives. If P106 (bit 0) = 1: Operation will continue when all tools reach their respective lives.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P106 (bit 1)	Method of estimating a residual life in standard EIA/ISO mode		If P106 (bit 1) = 0: The residual tool life can be estimated from the number of machined workpieces. If P106 (bit 1) = 1: The residual tool life can be estimated from the number of times of T-command execution.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P106 (bit 2)	Hard disk, floppy disk, and/or memory card input/output Conditions for loading the machining program of the same work number		Set up the hard disk, floppy disk, and/or memory card input/output bit to select whether the program of the same work number as that of the program registered in the NC unit is to be loaded. If P106 (bit 2) = 0: The current program data will not be updated and an alarm will be displayed. If P106 (bit 2) = 1: The current program data will be updated.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P106 (bit 3)	Selection of the display mode of ID numbers on the TOOL DATA display - Decimal or hexadecimal display		This parameter specifies whether the ID numbers on the TOOL DATA display are to be displayed in a decimal format or a hexadecimal format. If P106 (bit 3) = 0 : Decimal display If P106 (bit 3) = 1 : Hexadecimal display
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P106 (bit 5)	Tool set data protection in the automatic operation mode		If P106 (bit 5) = 0: The tool set data can be rewritten even in the automatic operation mode. If P106 (bit 5) = 1: The tool set data can not be rewritten in the automatic operation mode.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P106 (bit 6)	Selection of whether the GRAPHIC MAINTENANCE display is to be automatically displayed when the specific alarm occurs		If P106 (bit 6) = 0 : The GRAPHIC MAINTENANCE display does not appear, even though one of the specific alarms occurs. If P106 (bit 6) = 1 : The GRAPHIC MAINTENANCE display appears, when one of the specific alarms occurs.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning		Description
P106 (bit 7)	Selection of whether the ALARM NAVIGATION window is to be automatically displayed when the specific alarm occurs		<p>If P106 (bit 7) = 0 : The ALARM NAVIGATION window does not appear, even though one of the specific alarms occurs.</p> <p>If P106 (bit 7) = 1 : The ALARM NAVIGATION window appears, when one of the specific alarms occurs.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P107 (bit 0)	Whether workpiece and finishing shape data is to be output during EIA conversion output		<p>This parameter specifies whether the shape data of workpieces and finishing figures is to be output at the end of the program data.</p> <p>If P107 (bit 0) = 0 : Data is output.</p> <p>If P107 (bit 0) = 1 : Data is not output.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P107 (bit 2)	Selection of G0/G1 EIA conversion output during the polar coordinate mode (G12.1)		<p>If P107 (bit 2) = 0 : Positioning data during the polar coordinate mode is output with G0.</p> <p>If P107 (bit 2) = 1 : Positioning data during the polar coordinate mode is output with G1.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P107 (bit 3)	Selection of the approach operation for machining with the No. 2 spindle		<p>Select the approach operation for machining with the No. 2 spindle.</p> <p>If P107 (bit 3) = 0 : The machine approaches the position that allows for the stock material edge.</p> <p>If P107 (bit 3) = 1 : The machine approaches the back clearance position.</p> 
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description	
P107 (bit 4)	Selection of a FLASH-tool life management method	<p>If P107 (bit 4) = 0 :</p> <p>If there is a tip which has not reached its life, the turning tool is not changed for a spare.</p> <p>However, when multiple tips are to be used for a milling tool, the change for a spare tool is conducted if even one of the tips to be used has already arrived at its life.</p> <p>If P107 (bit 4) = 1 :</p> <p>Even one tip whose total operation time is already in excess of a predetermined life, that FLASH-tool is judged to have reached its life and is therefore changed for a spare.</p>	
	Unit		—
	Effective condition		Instant
	Applicable program		M, E
P107 (bit 5)	Selection of whether to hold spindle status during transfer (TRS) (machine with sub-spindle)	<p>If P107 (bit 5) = 0 :</p> <p>Spindle status is not held at the TRS unit when the workpiece is transferred.</p> <p>If P107 (bit 5) = 1 :</p> <p>Spindle status is held at the TRS unit when the workpiece is transferred.</p>	
	Unit		—
	Effective condition		Instant
	Applicable program		M
P107 (bit 6)	Selection of whether to execute the turning cycle when the approach point and ending point of G90/G94 match.	<p>Select whether the fixed turning cycle specified in G90/G94 is to be executed when the approach point and ending point of the command block match.</p> <p>If P107 (bit 6) = 0 : The cutting cycle is not executed.</p> <p>If P107 (bit 6) = 1 : The cutting cycle is executed.</p> <p>Example:</p> <pre>N001 G00 X46.Z2. N002 G90 X46.Z-25.F0.3 N003 X42. N004 X38.</pre> <div style="text-align: center;"> </div>	
	Unit		—
	Effective condition		Instant
	Applicable program		E

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P107 (bit 7)	Selection of the Z/C offset to be used for the subprogram when a subprogram call is performed from the MAZATROL program to the EIA program		<p>If P108 (bit 5) = 1 (the subprogram operates with the Z/C offset value specified in the main program), select the Z/C offset value to be used for the subprogram.</p> <p>If P107 (bit 7) = 0 : The Z/C offset value in the "SET UP DATA" of the main program will be used.</p> <p>If P107 (bit 7) = 1 : The Z/C offset value in the "TRANSFER INFORMATION" of the main program will be used.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P108 (bit 0)	How to handle EOR (%) - M02 or M30		<p>This parameter specifies whether designated EOR (%) is to be handled as M02 or M30.</p> <p>If P108 (bit 0) = 0 : Handled as M30.</p> <p>If P108 (bit 0) = 1 : Handled as M02.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P108 (bit 1)	Execution mode selection for a fixed turning cycle		<p>In the fixed turning cycle mode (G90/G92/G94)</p> <p>If P108 (bit 1) = 0 : The fixed turning cycle is executed for each block.</p> <p>If P108 (bit 1) = 1 : The fixed turning cycle is executed only for movement blocks.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P108 (bit 2)	Form of single-block stop during a fixed turning cycle		<p>This parameter specifies whether single-block operation during a fixed turning cycle (G90, G92 or G94) is to be stopped after the entire cycle has been executed, or for each block.</p> <p>If P108 (bit 2) = 0 : After execution of the cycle</p> <p>If P108 (bit 2) = 1 : For each block</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

Title of display		PARAMETER (USER, CUTTING)											
Address	Meaning		Description										
P108 (bit 3)	T-command compensation		The types of axes which undergo simultaneous compensation with execution of a move command in accordance with parameter P13 (bit 0) = 0 can be changed as follows: <table border="1" style="margin: 10px auto;"> <thead> <tr> <th></th> <th>P16 bit 3 = 0</th> <th>P16 bit 3 = 1</th> </tr> </thead> <tbody> <tr> <td>P108 bit 3 = 0</td> <td>Only the designated axis undergoes compensation.</td> <td>Only the designated axis undergoes compensation.</td> </tr> <tr> <td>P108 bit 3 = 1</td> <td>The X-, Y-, and Z-axes undergo compensation.</td> <td>Only the designated axis undergoes compensation.</td> </tr> </tbody> </table>		P16 bit 3 = 0	P16 bit 3 = 1	P108 bit 3 = 0	Only the designated axis undergoes compensation.	Only the designated axis undergoes compensation.	P108 bit 3 = 1	The X-, Y-, and Z-axes undergo compensation.	Only the designated axis undergoes compensation.	
		P16 bit 3 = 0		P16 bit 3 = 1									
	P108 bit 3 = 0	Only the designated axis undergoes compensation.		Only the designated axis undergoes compensation.									
	P108 bit 3 = 1	The X-, Y-, and Z-axes undergo compensation.		Only the designated axis undergoes compensation.									
Unit	—												
Effective condition	Instant												
Applicable program	E												
P108 (bit 4)	Whether to output M30 for a tool whose life has been reached		Set whether M30 is to be output to the PC if a tool life alarm occurs in the MAZATROL or EIA/ISO program. If P108 (bit 4) = 0 : Output (standard, conventional type) If P108 (bit 4) = 1 : No output (FLEX robot type)										
	Unit	—											
	Effective condition	Instant											
	Applicable program	M, E											
P108 (bit 5)	Whether to use the Z-offset existing when a subprogram call is performed from the MAZATROL program to an EIA/ISO program		If P108 (bit 5) = 0 : The subprogram operates at the Z/C offsets that have been set with WNo. of the subprogram. If P108 (bit 5) = 1 : The subprogram operates at the Z/C offsets that have been set with WNo. of the main program.										
	Unit	—											
	Effective condition	Instant											
	Applicable program	E											
P108 (bit 6)	Selection of the system variable for modal information reading		<table border="1" style="margin: 10px auto;"> <thead> <tr> <th>System variable</th> <th>Group number</th> <th>P108 bit 6 = 0</th> <th>P108 bit 6 = 1</th> </tr> </thead> <tbody> <tr> <td>#4001 · · · · ·</td> <td>Group 01 · · · · ·</td> <td rowspan="5">The group numbers at left apply only to T32 EIA.</td> <td rowspan="5">The group numbers at left apply only to standard EIA.</td> </tr> <tr> <td>#4023</td> <td>Group 23</td> </tr> </tbody> </table>	System variable	Group number	P108 bit 6 = 0	P108 bit 6 = 1	#4001 · · · · ·	Group 01 · · · · ·	The group numbers at left apply only to T32 EIA.	The group numbers at left apply only to standard EIA.	#4023	Group 23
	System variable	Group number		P108 bit 6 = 0	P108 bit 6 = 1								
	#4001 · · · · ·	Group 01 · · · · ·		The group numbers at left apply only to T32 EIA.	The group numbers at left apply only to standard EIA.								
	#4023	Group 23											
Unit	—												
Effective condition	Instant												
Applicable program	E												

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P108 (bit 7)	Selection of output codes for macro external output instructions (BPRNT, DPRNT)		Select the output codes for macro external output instructions (BPRNT, DPRNT). If P108 (bit 7) = 0 : ISO output If P108 (bit 7) = 1 : ASCII output
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P109 (bit 0)	Program protect flag (Whether editing of the programs of the order of WNo. 9000 is to be prohibited)		This parameter specifies whether editing of the programs of the order of WNo. 9000 is to be prohibited. If P109 (bit 0) = 0 : Not prohibited If P109 (bit 0) = 1 : Prohibited
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P109 (bit 1)	Program protect flag (Whether displaying of the programs of the order of WNo. 9000 is to be prohibited)		This parameter specifies whether displaying of the programs of the order of WNo. 9000 is to be prohibited. If P109 (bit 1) = 0 : Not prohibited If P109 (bit 1) = 1 : Prohibited
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P109 (bit 2)	Whether to save the data as an additional one during hard disk/floppy disk input/output		<p>Specify whether the data is to be saved as an additional one during hard disk/floppy disk input/output.</p> <p>If P109 (bit 2) = 0 : The data is saved in overwritten form.</p> <p>If P109 (bit 2) = 1 : The data is saved as an additional one.</p> <p>Example:</p> <p>Data is saved in an existing "FILE" folder.</p> <div style="display: flex; align-items: center; gap: 20px;"> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> <FILE> Program 100 User parameter Tool data </div> <div style="font-size: 2em;">←</div> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> Saving </div> <div style="display: inline-block; vertical-align: middle;"> Program 200 User parameter </div> </div> <p>Saving results in the case of P109 (bit 2) = 0</p> <div style="display: flex; align-items: center; gap: 20px;"> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> <FILE> Program 200 User parameter </div> <div style="display: inline-block; vertical-align: middle;"> The old data existing before saving was executed is overwritten with the newly saved data. </div> </div> <p>Saving results in the case of P109 (bit 2) = 1</p> <div style="display: flex; align-items: center; gap: 20px;"> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> <FILE> Program 100, 200 User parameter Tool data </div> <div style="display: inline-block; vertical-align: middle;"> Newly saved data is added. If the same data already exists, this data will be overwritten. (User parameter) </div> </div>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P109 (bit 4)	Program protect flag (Whether editing of the programs of the order of WNo. 8000 and WNo. 9000 is to be prohibited.)		<p>This parameter specifies whether editing of the programs of the order of WNo. 8000 and WNo. 9000 is to be prohibited.</p> <p>If P109 (bit 4) = 0 : Not prohibited</p> <p>If P109 (bit 4) = 1 : Prohibited</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P109 (bit 5)	Program protect flag (Whether displaying of the programs of the order of WNo. 8000 and WNo. 9000 is to be prohibited.)		<p>This parameter specifies whether displaying of the programs of the order of WNo. 8000 and WNo. 9000 is to be prohibited.</p> <p>If P109 (bit 5) = 0 : Not prohibited</p> <p>If P109 (bit 5) = 1 : Prohibited</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P109 (bit 6)	Selection of an alarm checking method for data input/output program saving		This parameter specifies when an alarm occurs if a program not present in the NC memory is specified during data input/output program saving. If P109 (bit 6) = 0 : An alarm occurs immediately before the specified program is saved. If P109 (bit 9) = 1 : An alarm occurs on selection of the saving start menu.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P109 (bit 7)	Selection of the jaw data reference method		Specify the jaw data reference method. If P109 (bit 7) = 0 : Reference using the code number of the jaw. If P109 (bit 7) = 1 : Reference using the name of the jaw.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P110 (bit 0)	Power-on display selection		If P110 (bit 0) = 0 : Then the POSITION display is selected. If P110 (bit 0) = 1 : Then the MAINTENANCE CHECK display is selected.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P110 (bit 1)	Page extension on the MAINTENANCE CHECK display		If P110 (bit 1) = 0 : Then the page can be extended to a maximum of two pages. If P110 (bit 1) = 1 : Then the page can be extended to a maximum of three pages.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	




Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P110 (bit 2)	When the visual tool ID/data management functions are valid — Stored tools registration function on the VISUAL TOOL MANAGER display valid/invalid		Specify whether the stored tools registration function on the VISUAL TOOL MANAGER display is to be made valid or invalid when the visual tool ID/data management functions are valid. If P110 (bit 2) = 0 : The stored tools registration function is invalid. If P110 (bit 2) = 1 : The stored tools registration function is valid. Note: When P110 (bit 2) is set to 0, the STOCK TOOL menu item will not be displayed.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P110 (bit 6)	Tool length input valid or not		If P110 (bit 6) = 0 : Tool length input is invalid. If P110 (bit 6) = 1 : Tool length input is valid.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P111 (bit 0)	M-command execution time processing		If P111 (bit 0) = 0 : The M-command execution time is processed as zero during time study of tool path checking. If P111 (bit 0) = 1 : During time study of tool path checking, the M-command execution time is added in accordance with the particular setting of parameter P23 .
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P111 (bit 1)	T-command execution time processing		If P111 (bit 1) = 0 : The T-command execution time is processed as zero during time study of tool path checking. If P111 (bit 1) = 1 : During time study of tool path checking, the T-command execution time is added in accordance with the particular setting of parameter P22 .
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	




Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
P111 (bit 2)	Upward cutting speed valid/invalid for inside diameter threading (THR IN)		Specify whether the upward cutting speed for inside threading is to be made valid or invalid. 1: Valid (the upward cutting speed for inside diameter threading is set to the value of the P63 parameter) 0: Invalid (the upward cutting speed for inside diameter threading is set to the normal value of the A4 parameter)
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
P111 (bit 5)	Using angle tool holder valid/invalid		If P111 (bit 5) = 0 : Angle tool holder can not be used. If P111 (bit 5) = 1 : Angle tool holder can be used.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
P111 (bit 6)	EIA tool command suffix valid/invalid		Specify whether the assignment of the tool identification code (suffix) by the T-command of the 640MT is valid or invalid. If P111 (bit 6) = 0 : The EIA tool command suffix is invalid. If P111 (bit 6) = 1 : The EIA tool command suffix is valid. Note: This parameter is valid only for the tool name method.
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
P111 (bit 7)	Selection of the method of moving axes to the tool change position		If P111 (bit 7) = 0 : The X-axis and the Z-axis simultaneously move to the tool change position specified by P17 or P95 . Note: When the tool nose stays within the (workpiece diameter + safety profile clearance), both axes move past the clearance position. If P111 (bit 7) = 1 : The X-axis first or then the Z-axis move to the tool change position specified by P17 or P95 . Note: When the tool nose stays within the (workpiece diameter + safety profile clearance), only the X-axis moves past the clearance position and the Z-axis does not move.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display	PARAMETER (USER, CUTTING)
-------------------------	----------------------------------


Address	Meaning	Description	
P112	Selection of measurement data items to be printed out	Selection of printout items in measurement data printout <div style="display: flex; align-items: center; margin-bottom: 5px;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">7</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">6</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">5</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">4</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">3</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">2</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div> <div style="border: 1px solid black; padding: 2px;">0</div> </div> (0: Not printout 1: Print out)	
	Unit	—	Work No., Unit No.
	Effective condition	Instant	Tool No., Work counter
	Applicable program	M, E	Measurement mode Target data Measurement data Offset data Tolerance upper/lower Day and time of measurement

3-3 PARAMETER (USER, CUTTING K)



Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
K1	Cut depth reduction rate for rough cutting in bar machining unit (BAR)		Cut depth can be reduced as remaining workpiece thickness becomes less in rough cutting in bar machining unit (BAR). Reduced cut depth (A) can be expressed by $A = T \times \frac{K1}{100}$ where T=Remaining thickness (radial value). Note: Up to 100 % can be set.
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K2	Acceleration rate in up-going taper for rough cutting in bar machining unit (BAR)		 <p style="text-align: right;">NM211-00262</p> $F_2 = F_1 \times \frac{K2}{100} \times \left \frac{b}{a} \right $ <p> F_1 : Feedrate for rough cutting F_2 : Increased feedrate </p> Notes: 1. This is effective only when P1 (bit 0)=1. 2. Up to 500 % can be set.
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K3	Acceleration rate in up-going wall slope (90°) for rough cutting in bar machining unit (BAR)		 <p style="text-align: right;">NM211-00263</p> $F_2 = F_1 \times \frac{K3}{100}$ <p> F_1 : Feedrate for rough cutting F_2 : Increased feedrate </p> Notes: 1. This is effective only when P1 (bit 0)=1. 2. Up to 500 % can be set.
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K4	Deceleration rate in down-going taper for rough cutting in bar machining unit (BAR)		 <p style="text-align: right;">NM211-00264</p> $F_3 = F_1 \times \frac{K4}{100} \times \left \frac{a}{b} \right $ <p> F_1 : Feedrate for rough cutting F_3 : Reduced feedrate </p> Notes: 1. This is effective only when P1 (bit 1)=1. 2. Up to 500 % can be set.
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	




Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
K5	Deceleration rate in down-going wall slope (90°) for rough cutting in bar machining unit (BAR)		 <p>F_1 : Feedrate for rough cutting F_3 : Reduced feedrate</p> <p style="text-align: right;">NM211-00265</p> $F_3 = F_1 \times \frac{K5}{100}$ <p>Notes:</p> <ol style="list-style-type: none"> 1. This is effective only when P1 (bit 1)=1. 2. Up to 500 % can be set.
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K6	Acceleration rate on outside stock contour for rough cutting in copy machining unit (CPY)		 <p>F_1 : Feedrate inside stock contour F_2 : Feedrate outside stock contour</p> <p style="text-align: right;">NM211-00266</p> $F_2 = F_1 \times \frac{K6}{100}$ <p>Note: Up to 500 % can be set.</p>
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K8	Rough cutting residue ratio in cutting off cycle (#4, #5) in groove cutting unit (GRV)		 <p>P_S : Programmed start point P_E : Programmed end point l : Groove machining depth $l = P_S - P_E$ d : Rough cutting residue $d = l \times \frac{K8}{100}$</p> <p style="text-align: right;">NM211-00267</p> <p>[1] Cutting at rough cutting feedrate to a point short of end P_E by distanced d [2] Cutting off at finish cutting feedrate to end point P_E</p> <p>Note: Up to 100 % can be set.</p>
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K9	Deceleration ratio for automatic corner overriding		<p>Set the deceleration ratio for automatic corner overriding.</p> <p>Note: Up to 100 % can be set.</p>
	Unit	%	
	Effective condition	Instant	
	Applicable program	E	

3 PARAMETER




Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
K10	Cut depth allowable incremental rate for rough cutting in groove cutting unit (GRV), edge machining unit (EDG) and copy machining unit (CPY)		Used to calculate minimum cutting frequency in groove cutting unit (GRV), edge machining unit (EDG) and copy machining unit (CPY) $d' = d \left(\frac{100 + \mathbf{K10}}{100} \right)$ d : Cut depth per cycle d' : Allowable maximum cut depth Note: Up to 100 % can be set.
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K11	Deceleration rate at cutting start time in drilling unit (DRL, MDR)		 <p>End point ← Programmed start point</p> <p>θ Drill D</p> <p>ℓ</p> <p>Feedrate at F' over distance ℓ from the programmed start point (DRL, MDR) NM211-00268</p> $F' = F \times \frac{\mathbf{K11}}{100}$ <p>F : Specified feedrate F' : Feedrate at cutting start</p> $\begin{cases} \ell = \frac{D}{2 \times \tan(\theta/2)} & (0^\circ < \theta < 180^\circ) \\ \ell = 0 & (\theta \geq 180^\circ) \end{cases}$ <p>Note: Up to 100 % can be set.</p>
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	



Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description
K12	Deceleration rate at cutting end time in drilling unit (DRL, MDR)	<div style="text-align: center;">  </div> <p style="text-align: right;">NM211-00269</p> <p>Feedrate at F' to the point distant by l from the end point</p> <p> $F' = F \times \frac{\mathbf{K12}}{100}$ F : Specified feedrate F' : Feedrate at cutting start </p> $\begin{cases} l = \frac{D}{2 \times \tan(\theta/2)} + \frac{D}{10} & (0^\circ < \theta < 180^\circ) \\ l = \frac{D}{10} & (\theta \geq 180^\circ) \end{cases}$ <p>Note: Up to 100 % can be set.</p>
	Unit	%
	Effective condition	Instant
	Applicable program	M
K13	Deceleration rate at rough cutting start time in bar machining unit (BAR) and copy machining unit (CPY)	<div style="text-align: center;">  </div> <p style="text-align: right;">NM211-00270</p> <p> $F' = F \times \frac{\mathbf{K13}}{100}$ F : Specified feedrate F' : Feedrate at cutting start </p> <p>Note: Up to 100 % can be set.</p>
	Unit	%
	Effective condition	Instant
	Applicable program	M

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning	Description	
K14	Maximum permissible rate of increase of the initial cutting depth during BAR roughing	<p>This parameter is valid during initial cutting in a bar roughing cycle. If the remainder obtained by dividing the thickness of cutting during the roughing cycle by the corresponding cutting depth stays within the range specified by this parameter, that value will be added to the initial cutting depth to reduce the cutting repeat times.</p> <p>Example 1: K14 = 0 (R-DEP.: 5)</p>  <p>Example 2: K14 = 10% (R-DEP.: 5)</p>  <p>Cutting to a depth of 10.1 is executed three split times (5, 5, and 0.1).</p> <p>Cutting at a depth setting of X=5 results in a final cutting depth of 0.1. Since 10% of the depth setting of X=5 is 0.5 and this value is larger than the final cutting depth, this final cutting depth is added to the initial cutting depth.</p> <p>Note: Up to 100% can be set. When a value larger than 100% is set, it is regarded as 0.</p>	
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
K15	Pitch error correction during threading acceleration	<p>Set the starting pitch error rate of threading.</p>  <p>Ideal pitch = Starting pitch of threading [1] + K15</p>	
	Unit	0.001 mm	
	Effective condition	Instant	
	Applicable program	M	
K17	Drilling cut depth calculation coefficient	<p>Used for automatic determination of first cut depth in drilling</p> $d_1 = D \times \frac{K17}{100}$ <p>D : Drilling hole diameter d₁ : Cut depth of first cut</p> <p>Note: Up to 1000 % can be set.</p>	
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description	
K18	Reamer return speed calculation coefficient	<div style="display: flex; justify-content: space-around; align-items: center;">  <div style="text-align: right; font-size: small;"> NM211-00271 F₁ : Specified feedrate F₂ : Return speed P₁ : Start point P₂ : End point </div> </div> $F_2 = F_1 \times \frac{K18}{100}$ <p>Note: Up to 999 % can be set.</p>	
	Unit		%
	Effective condition		Instant
	Applicable program		M
K19	Chamfering data calculation coefficient in thread cutting unit (THR)	<div style="display: flex; justify-content: space-around; align-items: center;">  <div style="text-align: right; font-size: small;"> NM211-00272 L : Effective thread length L₁ : Same pitch incomplete thread length (copy delay) L₂ : Chamfering data ψ : Chamfering angle </div> </div> $L_2 = L_0 \times \frac{K19}{10}$ <p style="margin-left: 40px;">L₀ : Thread lead</p> <p>Note: Up to 40 can be set.</p>	
	Unit		Lead/10
	Effective condition		Instant
	Applicable program		M, E
K20	Incomplete threading portion length calculation coefficient for tap tip	$\ell = P \times \frac{K20}{10}$ <p>P : Tapping pitch ℓ : Incomplete thread portion length</p> <div style="display: flex; justify-content: space-around; align-items: center;">  <div style="text-align: right; font-size: small;"> NM211-00273 Cutting end point specified farther by this length ℓ </div> </div> <p>Note: Up to 99 can be set.</p>	
	Unit		Pitch/10
	Effective condition		Instant
	Applicable program		M

Title of display		PARAMETER (USER, CUTTING)		
Address	Meaning		Description	
K21	Tapper elongation calculation coefficient		$\ell = P \times \frac{K21}{10}$ P : Tapping pitch ℓ : Tapper elongation  <p style="text-align: right;">NM211-00274</p>	
	Unit	Pitch/10		Note: Up to 99 can be set.
	Effective condition	Instant		
	Applicable program	M		
K23	Calculation coefficient for axial feedrate of milling line machining (MGV, LCT, RGT, LFT)		Ratio of axial feedrate to diametral feedrate is set. $(\text{Axial feedrate}) = (\text{Radial feedrate}) \times \frac{K23}{100}$  <p style="text-align: right;">NM211-00275</p> <p>K23 for finish cutting</p> <p>Notes:</p> <ol style="list-style-type: none"> Up to 999 % can be set. If 0 is entered, the ratio will be regarded as 100%. This parameter is valid only for the tool number scheme. 	
	Unit	%		
	Effective condition	Instant		
	Applicable program	M		

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description
K24	Thread height calculation coefficient for outside diameter, face/rear thread cutting (metric)	
	Unit	0.01%
	Effective condition	Instant
	Applicable program	M
K25	Thread height calculation coefficient for inside diameter thread cutting (metric)	
	Unit	0.01%
	Effective condition	Instant
	Applicable program	M
K26	Thread height calculation coefficient for outside diameter, face/rear thread cutting (inch)	
	Unit	0.01%
	Effective condition	Instant
	Applicable program	M
K27	Thread height calculation coefficient for inside diameter thread cutting (inch)	
	Unit	0.01%
	Effective condition	Instant
	Applicable program	M

The thread height is calculated using the following calculation expression:


$$h = P \times \frac{\mathbf{K24 \text{ to } K27}}{10000}$$

h : Thread height
P : Thread pitch


	Metric	Inch
O. D.	K24	K26
Face	K24	K26
Rear	K24	K26
I. D.	K25	K27

PARAMETER (USER, CUTTING)

Address	Meaning	Description
K29	Feedrate calculation reference diameter in mill drilling unit (MDR)	
	Unit	0.1 mm or 0.01 inches
	Effective condition	Instant
	Applicable program	M
K30	Feedrate calculation reference diameter in mill boring unit (BOR)	
	Unit	0.1 mm or 0.01 inches
	Effective condition	Instant
	Applicable program	M
K31	Radial direction feedrate calculation reference diameter for rough cutting in milling line machining unit (MGV, LCT, RGT, LFT)	
	Unit	0.1 mm or 0.01 inches
	Effective condition	Instant
	Applicable program	M






f : Feedrate
f₀ : Data depending on cutting conditions
D : Hole diameter
D₀ : **K29** × α (MDR unit)
D₀ : **K30** × α (BOR unit)
α : 0.1 (for metric specs.) or 0.01 (for inch specs.)





f : Feedrate
f₀ : Data depending on cutting conditions
D : Groove width
D₀ : **K31** × α
α : 0.1 (for metric specs.) or 0.01 (for inch specs.)

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description																								
K32	Radial direction feedrate calculation reference diameter for finish cutting in milling line machining unit (MGV, LCT, RGT, LFT)																									
	Unit	0.1 mm or 0.01 inches																								
	Effective condition	Instant																								
	Applicable program	M																								
		<p>This parameter, the roughness code, etc. determine the finishing feedrate.</p> <p>- If the radial-finishing feedrate is taken as F_1, then:</p> $U19 \times \frac{D}{K32 \times \alpha} \times K_f \times Z \quad (D < K32 \times \alpha)$ $U19 \times K_f \times Z \quad (D \geq K32 \times \alpha)$ <p>- If the axial-finishing feedrate is taken as F_2, then:</p> $F_2 = F_1 \times \frac{K23}{100}$ <p>D : Tool diameter α : 0.1 (for metric specs.) or 0.01 (for inch specs.) K_f : Roughness coefficient (Refer to the list below) Z : Number of teeth</p> <table border="1" style="width: 100%; text-align: center; border-collapse: collapse;"> <thead> <tr> <th>Roughness code</th> <th>K_f</th> <th>Roughness code</th> <th>K_f</th> <th>Roughness code</th> <th>K_f</th> </tr> </thead> <tbody> <tr> <td>∇ 1</td> <td>$K_0 \times 0.8^{-3}$</td> <td>∇∇ 4</td> <td>K_0</td> <td>∇∇∇∇ 7</td> <td>$K_0 \times 0.8^3$</td> </tr> <tr> <td>∇ 2</td> <td>$K_0 \times 0.8^{-2}$</td> <td>∇∇∇ 5</td> <td>$K_0 \times 0.8$</td> <td>∇∇∇∇ 8</td> <td>$K_0 \times 0.8^4$</td> </tr> <tr> <td>∇∇ 3</td> <td>$K_0 \times 0.8^{-1}$</td> <td>∇∇∇ 6</td> <td>$K_0 \times 0.8^2$</td> <td>∇∇∇∇ 9</td> <td>$K_0 \times 0.8^5$</td> </tr> </tbody> </table> <p style="text-align: right;"><small>K_0=Standard data 0.5</small></p> <p>(⇒U19, K23)</p>	Roughness code	K_f	Roughness code	K_f	Roughness code	K_f	∇ 1	$K_0 \times 0.8^{-3}$	∇∇ 4	K_0	∇∇∇∇ 7	$K_0 \times 0.8^3$	∇ 2	$K_0 \times 0.8^{-2}$	∇∇∇ 5	$K_0 \times 0.8$	∇∇∇∇ 8	$K_0 \times 0.8^4$	∇∇ 3	$K_0 \times 0.8^{-1}$	∇∇∇ 6	$K_0 \times 0.8^2$	∇∇∇∇ 9	$K_0 \times 0.8^5$
Roughness code	K_f	Roughness code	K_f	Roughness code	K_f																					
∇ 1	$K_0 \times 0.8^{-3}$	∇∇ 4	K_0	∇∇∇∇ 7	$K_0 \times 0.8^3$																					
∇ 2	$K_0 \times 0.8^{-2}$	∇∇∇ 5	$K_0 \times 0.8$	∇∇∇∇ 8	$K_0 \times 0.8^4$																					
∇∇ 3	$K_0 \times 0.8^{-1}$	∇∇∇ 6	$K_0 \times 0.8^2$	∇∇∇∇ 9	$K_0 \times 0.8^5$																					
K33	Polishing margin width for #1 to #3																									
	Unit	0.001 mm or 0.0001 inches																								
	Applicable program	M																								
K34	Polishing margin depth #1 to #3																									
	Unit	0.001 mm or 0.0001 inches																								
	Effective condition	Instant																								
	Applicable program	M																								
		<p><#1></p>  <p><#2></p>  <p><#3></p>  <p>P: Program end point</p>																								


3 PARAMETER

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
K35	Polishing margin width for #4		<#4>  P: Program end point NM211-00280
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
K36	Polishing margin depth for #4		
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
K37	Polishing margin width for #5		<#5>  P: Program end point NM211-00278
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
K38	Polishing margin depth for #5		
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description
K39	Polishing margin width for #6	
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M
K40	Polishing margin depth for #6	
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M
K41	Rate of adjustment of the axial cutting/relief feedrate during linear milling	
	Unit	%
	Effective condition	Instant
	Applicable program	M


<#6>



NM211-00279

P: Program end point


K41 ≠ 0






$F = Fa \times \frac{K41}{100}$

Fa : Designated axial feedrate
 F : Adjusted feedrate (valid for the 2nd cutting operation onward)

K41 = 0







Fa : Designated axial feedrate

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
K42	Distance from the ending point of a mill-drilling unit (MDR) where the feedrate is to be modified		 $F' = F \times \frac{K42}{100}$ <p>F : Designated feedrate F' : Feedrate at the end of cutting</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
K43	Radial clearance for circular milling		<p>Set the clearance between the pre-hole diameter and tool diameter for determining whether the rapid feed mode or the cutting feed mode is to be used to axially feed the tool for circular milling.</p> <p>If pre-hole diameter \leq (Tool diameter + K43): Cutting feed</p> <p>If pre-hole diameter $>$ (Tool diameter + K43): Rapid feed</p>  <p>Tool</p> <p>Cutting feed</p> <p>Rapid feed</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
K45	Reference diameter for calculating the circular milling radial feedrate		 $f = f_0 \times \frac{D}{D_0} \quad (D < D_0)$ $f = f_0 \quad (D \geq D_0)$ <p>f : Feedrate f₀ : Designated value for the particular cutting conditions D : Hole diameter D₀ : K45 × α α : 0.1 if metric, 0.01 if inch</p>
	Unit	0.1 mm or 0.01 inches	
	Effective condition	Instant	
	Applicable program	M	
K46	Coefficient for calculating the circular milling axial feedrate		<p>Set the ratio of the axial feedrate to the radial feedrate.</p> $(\text{Axial feedrate}) = (\text{Radial feedrate}) \times \frac{K46}{100}$
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	


Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
K47	Selection of position for output of reciprocating rotation M code at milling tapping		K47 = 0 Dwell after output of the reciprocating rotation M code at the bottom of hole. K47 = 1 Output of the reciprocating rotation M code after dwell at the bottom of hole.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
K49	Selection of manual feed per revolution or per minute		This parameter specifies whether manual JOG feed is to be executed in the feed per revolution mode or in the feed per minute mode. If K49 = 0 : Feed per minute If K49 = 1 : Feed per revolution
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
K50	Direction of rotation of the C-axis during C-axial threading with G01.1		Select the direction of rotation of the C-axis during C-axial threading based on G01.1. If K50 = 0 : The C-axis rotates CW (forward). If K50 = 1 : The C-axis rotates CCW (backward).
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	

PARAMETER (USER, CUTTING)

Address	Meaning	Description	
K51	Selection of whether to move the tool past a clearance point immediately before executing move command of the turning/milling manual program machining unit that follows I. D. machining	Select whether the tool is to be moved past a clearance point immediately before executing move command of the turning/milling manual program machining unit that follows inside-diameter machining. If K51 = 0 : The tool directly moves from the ending position of I. D. machining, to the position specified by the move command data line on the turning/milling manual program machining unit. If K51 = 1 : The tool moves from the ending position of I. D. machining, through a clearance point, to the position specified by the move command data in the turning/milling manual program machining unit. <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <p>K51 = 0</p> <p>Move command data in the turning/milling manual program machining unit</p>  <p>Ending position</p> </div> <div style="text-align: center;"> <p>K51 = 1</p> <p>Move command data in the turning/milling manual program machining unit</p>  <p>Ending position Clearance point</p> </div> </div>	
	Unit	—	<p>Note: This parameter is valid only when the return to the tool change position is set to 'Invalid' (0) in the turning/milling manual program machining unit.</p>
	Effective condition	Instant	
	Applicable program	M	
K55	Selection of a shape definition method for the Z-C plane in a linear machining unit	Select a definition method for the shape that is to be programmed on the Z-C plane of a linear machining unit (LINE CTR, LINE RGT, LINE LFT, LINE IN, or LINE OUT). If K55 = 0 : Define the shape on the plane of SHIFT-R. Even if the value of SRV-A is changed, the position of the C-axis for defining the shape to be programmed will not change. If K55 = 1 : Define the shape on the plane of SHIFT-R + SRV-A (conventional method). The position of the C-axis for defining the shape to be programmed changes according to the particular value of SRV-A.	
	Unit	—	<div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;">  <p>Shape definition with K55 = 0</p> </div> <div style="text-align: center;">  <p>Shape definition with K55 = 1</p> </div> </div>
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)																																									
Address	Meaning		Description																																								
K57	Method of nose R offsetting during finishing with EIA conversion output		This parameter specifies whether nose R offsetting is to be executed and whether G41 and G42 are to be added prior to output during finishing. If K57 = 0 : Nose R offsetting is executed and G41/G42 is not added during finishing. If K57 = 1 : Nose R offsetting is not executed and G41/G42 is added during finishing. If K57 = 2 : Nose R offsetting is executed and G41/G42 is added during finishing.																																								
	Unit	—																																									
	Effective condition	Instant																																									
	Applicable program	E																																									
K58	Language selection		This parameter specifies whether the first language or the second language is to be used. <table border="1" data-bbox="783 801 1401 1088"> <thead> <tr> <th>Setting</th> <th>Language</th> <th>Setting</th> <th>Language</th> </tr> </thead> <tbody> <tr><td>0</td><td>English</td><td>9</td><td>Chinese</td></tr> <tr><td>1</td><td>Japanese</td><td>10</td><td>Dutch</td></tr> <tr><td>2</td><td>German</td><td>11</td><td>Korean</td></tr> <tr><td>3</td><td>French</td><td>12</td><td>Portuguese</td></tr> <tr><td>4</td><td>Italian</td><td>13</td><td>Danish</td></tr> <tr><td>5</td><td>Spanish</td><td>14</td><td>Czech</td></tr> <tr><td>6</td><td>Norwegian</td><td>15</td><td>Turkish</td></tr> <tr><td>7</td><td>Swedish</td><td>16</td><td>Polish</td></tr> <tr><td>8</td><td>Finnish</td><td>17</td><td>Rumanian</td></tr> </tbody> </table>	Setting	Language	Setting	Language	0	English	9	Chinese	1	Japanese	10	Dutch	2	German	11	Korean	3	French	12	Portuguese	4	Italian	13	Danish	5	Spanish	14	Czech	6	Norwegian	15	Turkish	7	Swedish	16	Polish	8	Finnish	17	Rumanian
	Setting	Language		Setting	Language																																						
	0	English		9	Chinese																																						
	1	Japanese		10	Dutch																																						
2	German	11	Korean																																								
3	French	12	Portuguese																																								
4	Italian	13	Danish																																								
5	Spanish	14	Czech																																								
6	Norwegian	15	Turkish																																								
7	Swedish	16	Polish																																								
8	Finnish	17	Rumanian																																								
Unit	—																																										
Effective condition	Power OFF → ON																																										
Applicable program	M, E																																										
K60 (bit 0) (bit 1)	Data entry for communication with the magazine-side display unit (Serial port)		Specify the serial port number of the NC unit that is to be used for communication with the magazine-side display unit. <table border="1" data-bbox="788 1227 1339 1424"> <thead> <tr> <th>Bit 1</th> <th>Bit 0</th> <th>Serial port</th> </tr> </thead> <tbody> <tr><td>0</td><td>0</td><td>COM1</td></tr> <tr><td>0</td><td>1</td><td>COM2</td></tr> <tr><td>1</td><td>0</td><td>COM3</td></tr> <tr><td>1</td><td>1</td><td>COM4</td></tr> </tbody> </table>	Bit 1	Bit 0	Serial port	0	0	COM1	0	1	COM2	1	0	COM3	1	1	COM4																									
	Bit 1	Bit 0		Serial port																																							
	0	0		COM1																																							
	0	1		COM2																																							
1	0	COM3																																									
1	1	COM4																																									
Unit	—																																										
Effective condition	Power OFF → ON																																										
Applicable program	M, E																																										
K60 (bit 2)	Data entry for communication with the magazine-side display unit (Communication setting file)		Fixed (0)																																								
	Unit	—																																									
	Effective condition	Power OFF → ON																																									
	Applicable program	M, E																																									

Title of display		PARAMETER (USER, CUTTING)																	
Address	Meaning		Description																
K60 (bit 4) (bit 5)	Data entry for communication with the magazine-side display unit (Type of ID amplifier)		Specify the type of ID amplifier. <table border="1"> <thead> <tr> <th>Bit 5</th> <th>Bit 4</th> <th>Type</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>Mazak ID</td> </tr> <tr> <td>0</td> <td>1</td> <td>Invalid</td> </tr> <tr> <td>1</td> <td>0</td> <td>Invalid</td> </tr> <tr> <td>1</td> <td>1</td> <td>Invalid</td> </tr> </tbody> </table>	Bit 5	Bit 4	Type	0	0	Mazak ID	0	1	Invalid	1	0	Invalid	1	1	Invalid	
	Bit 5	Bit 4		Type															
	0	0		Mazak ID															
	0	1		Invalid															
1	0	Invalid																	
1	1	Invalid																	
Unit	—																		
Effective condition	Power OFF → ON																		
Applicable program	M, E																		
K60 (bit 6) (bit 7)	Data entry for communication with the magazine-side display unit (R-register)		Specify whether the timing of the R-register is to be made valid during tool removal or mounting. <table border="1"> <thead> <tr> <th>Bit 7</th> <th>Bit 6</th> <th>Setting</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>R-register is not used</td> </tr> <tr> <td>0</td> <td>1</td> <td>R-register is used (fixed)</td> </tr> <tr> <td>1</td> <td>0</td> <td>Invalid</td> </tr> <tr> <td>1</td> <td>1</td> <td>Invalid</td> </tr> </tbody> </table>	Bit 7	Bit 6	Setting	0	0	R-register is not used	0	1	R-register is used (fixed)	1	0	Invalid	1	1	Invalid	
	Bit 7	Bit 6		Setting															
	0	0		R-register is not used															
	0	1		R-register is used (fixed)															
1	0	Invalid																	
1	1	Invalid																	
Unit	—																		
Effective condition	Power OFF → ON																		
Applicable program	M, E																		
K65	Selection of a cylindrical interpolation rotational axis for cylindrical interpolation plane selection		This parameter specifies which axis is to be set as the cylindrical interpolation rotational axis for selecting a cylindrical interpolation plane. <table border="1"> <thead> <tr> <th>Setting</th> <th>Meaning</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Neither the three fundamental axes nor their parallel axes</td> </tr> <tr> <td>1</td> <td>X-axis among the three fundamental axes</td> </tr> <tr> <td>2</td> <td>Y-axis among the three fundamental axes</td> </tr> <tr> <td>3</td> <td>Z-axis among the three fundamental axes</td> </tr> <tr> <td>5*</td> <td>Axis parallel to the X-axis</td> </tr> <tr> <td>6*</td> <td>Axis parallel to the Y-axis</td> </tr> <tr> <td>7</td> <td>Axis parallel to the Z-axis</td> </tr> </tbody> </table> * Only either one During plane selection in the cylindrical interpolation mode, reference is made to the setting of this parameter. If the setting is 5, only G18 can be used. If the setting is 6, only G19 can be used.	Setting	Meaning	0	Neither the three fundamental axes nor their parallel axes	1	X-axis among the three fundamental axes	2	Y-axis among the three fundamental axes	3	Z-axis among the three fundamental axes	5*	Axis parallel to the X-axis	6*	Axis parallel to the Y-axis	7	Axis parallel to the Z-axis
	Setting	Meaning																	
	0	Neither the three fundamental axes nor their parallel axes																	
	1	X-axis among the three fundamental axes																	
2	Y-axis among the three fundamental axes																		
3	Z-axis among the three fundamental axes																		
5*	Axis parallel to the X-axis																		
6*	Axis parallel to the Y-axis																		
7	Axis parallel to the Z-axis																		
Unit	—																		
Effective condition	Instant																		
Applicable program	E																		

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
K67	Angle of the tool nose during the G76 mode		<p>If, during the composite-type fixed cycle G76 mode, a tool nose angle has not been specified in the program, the setting of this parameter will become the angle of the tool nose.</p> 
	Unit	Degree	
	Effective condition	Instant	
	Applicable program	E	
K68	Number of common variables between turrets (#100 onward)		<p>Set the number of common variables which can be read and written between the turrets. Variables from #100 to #149 become the subject of processing of K68 (variables from #500 to #531 become the subject of processing of K69).</p> <p>Example 1: If 10 is set in K68</p> <p>#100 to #109 : Common variables that are valid for both turrets #110 to #149 : Common variables that are valid only for one turret</p> <p>Example 2: If 10 is set in K69</p> <p>#500 to #509 : Common variables that are valid for both turrets #510 to #531 : Common variables that are valid only for one turret</p> <p>Note: The maximum permissible value will be used if the designated value is larger than that one.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
K69	Number of common variables between turrets (#500 onward)		
	Unit	—	
	Effective condition	Instant	
	Applicable program	E	
K70	Return speed overriding during a synchronous tapping		<p>Feedrate overriding during removal of synchronous tapping tool is set by this parameter. This parameter is valid only for EIA/ISO programs.</p>
	Unit	%	
	Effective condition	Instant	
	Applicable program	E	


Title of display		PARAMETER (USER, CUTTING)																
Address	Meaning		Description															
K72	Tool registration quantity pattern on the TOOL LIFE display		<p>This parameter specifies a combination pattern of the number of groups and the registration quantity on the TOOL LIFE display.</p> <table border="1"> <thead> <tr> <th>Setting</th> <th>Number of groups</th> <th>Registration quantity</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>16</td> <td>16</td> </tr> <tr> <td>1</td> <td>32</td> <td>8</td> </tr> <tr> <td>2</td> <td>64</td> <td>4</td> </tr> <tr> <td>3</td> <td>128</td> <td>2</td> </tr> </tbody> </table> <p>Note: After the setting of this parameter has been changed, TOOL LIFE display data needs to be initialized in the data-initializing window.</p>	Setting	Number of groups	Registration quantity	0	16	16	1	32	8	2	64	4	3	128	2
	Setting	Number of groups		Registration quantity														
	0	16		16														
	1	32		8														
2	64	4																
3	128	2																
Unit	—																	
Effective condition	Instant																	
Applicable program	E																	
K74	Number of cutting edges of a FLASH-tool for milling (Only for a milling tool not specified in the TOOL FILE display)		<p>Specify the number of cutting edges of the FLASH-tool to be used as a milling tool other than the end mills, face mills, chamfering cutters, or ball end mills to be registered in the TOOL FILE display.</p> <p>The number of cutting edges is 2 if the setting of parameter K74 is '0'. The tip to be used for the milling tool is identified from the relationship between the tip position data in the TOOL DATA display and the number of cutting edges specified in K74</p> <p>The setting range is from 0 to 255.</p>															
	Unit	—																
	Effective condition	Instant																
	Applicable program	M, E																
K75	Selection about planetary tapping chip ejection		<p>Select whether the chips arising from planetary tapping are to be ejected.</p> <p>0: Chips not to be ejected. 1: Chips to be ejected.</p>															
	Unit	—																
	Effective condition	Instant																
	Applicable program	M																
K76	Reduction ratio for the G00-based relief rate during a very-deep-hole drilling cycle		<p>Set the reduction ratio for the G00-based relief rate during the #4 or [#4] cycle (very-deep-hole drilling) in a DRL, MDR unit.</p> <p>← Cutting feed ← - - Rapid feed (G00)</p>															
	Unit	%																
	Effective condition	Instant																
	Applicable program	M																





Title of display		PARAMETER (USER, CUTTING)										
Address	Meaning		Description									
K77	Dwell at the hole bottom during a DRL or MDR unit		Set the number of revolutions of the spindle or the tool during dwell time at the bottom of a hole when the #0 - #4 non-through hole drilling cycle is selected in DRL or MDR unit.									
	Unit	Revolutions										
	Effective condition	Instant										
	Applicable program	M										
K81 to K88	Macro call G-code and corresponding macroprogram number		Set the G-code to be used for macro call and the macroprogram number corresponding to the macro call G-code. Set G-code and macroprogram number for the data item "CODE" and "NUM." respectively. Example: <table style="margin-left: 40px;"> <tr> <td></td> <td>CODE</td> <td>NUM.</td> </tr> <tr> <td>K81</td> <td>100</td> <td>1234</td> </tr> <tr> <td>:</td> <td>:</td> <td>:</td> </tr> </table> If G100 ; is set, the macroprogram 1234 will be called.		CODE	NUM.	K81	100	1234	:	:	:
		CODE		NUM.								
	K81	100		1234								
	:	:		:								
Unit	—											
Effective condition	Instant											
Applicable program	E											
K89 to K93	Macro call M-code and corresponding macroprogram number		Set the M-code to be used for macro call and the macroprogram number corresponding to the macro call M-code. Set M-code and macroprogram number for the data item "CODE" and "NUM." respectively. Example: <table style="margin-left: 40px;"> <tr> <td></td> <td>CODE</td> <td>NUM.</td> </tr> <tr> <td>K89</td> <td>101</td> <td>1235</td> </tr> <tr> <td>:</td> <td>:</td> <td>:</td> </tr> </table> If M101 ; is set, the macroprogram 1235 will be called.		CODE	NUM.	K89	101	1235	:	:	:
		CODE		NUM.								
	K89	101		1235								
	:	:		:								
Unit	—											
Effective condition	Instant											
Applicable program	E											
K94 K95 K96	Macro call S, T or B-code and corresponding macroprogram number		Set the S, T or B-code to be used for macro call and the macroprogram number corresponding to the macro call S, T or B-code. Set S, T or B-code and macroprogram number for the data item "CODE" and "NUM." respectively. Example: <table style="margin-left: 40px;"> <tr> <td></td> <td>CODE</td> <td>NUM.</td> </tr> <tr> <td>K94</td> <td>102</td> <td>1236</td> </tr> <tr> <td>:</td> <td>:</td> <td>:</td> </tr> </table> If S102 ; is set, the macroprogram 1236 will be called.		CODE	NUM.	K94	102	1236	:	:	:
		CODE		NUM.								
	K94	102		1236								
	:	:		:								
Unit	—											
Effective condition	Instant											
Applicable program	E											

3-4 PARAMETER (USER, CUTTING U)





Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning	Description	
U1	Tool turning clearance (diametral value) in X-axis	<p>Tool turning clearance is required to prevent interference between the tool and stock material during tool change in automatic operation.</p> <p style="text-align: right;">NM211-00220</p> <p>Dmax: Stock material maximum outside diameter l_0: Stock material edge projection length</p>	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U2	Tool turning clearance (diametral value) in Z-axis		
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	

Title of display **PARAMETER (USER, CUTTING)**



Address	Meaning	Description	
U3	Safety contour clearance — Outside diameter clearance (diametral value)	<p>Safety contour clearance is provided for outside of the stock material shape specified by common data in program. Tool approach and escape paths for each unit will be automatically determined according to set data (outside diameter, inside diameter, front clearance, back clearance) for parameters from U3 to U6.</p>  <p style="text-align: right;">NM211-00221</p> <p>Dmax: Stock material maximum outside diameter Dmin: Stock material minimum inside diameter l_0: Stock material edge projection length l: Stock material length</p>	
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M
U4	Safety contour clearance — Inside diameter clearance (diametral value)		
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M
U5	Safety contour clearance — Front clearance		
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M
U6	Safety contour clearance — Back clearance		
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning	Description	
U7	Thread cutting clearance (radial value)	<p>Thread cutting clearance is provided to specify tool return distance for each cycle in thread cutting unit (THR). Thread cutting clearance will be added to the highest portion of thread and repeating path will be determined automatically.</p> <p><OUT></p>  <p style="text-align: right;">NM211-00222</p>	
		<p><IN></p>  <p style="text-align: right;">NM211-00223</p>	
		<p><FCE></p>  <p style="text-align: right;">NM211-00224</p>	
		<p><BAK></p>  <p style="text-align: right;">NM211-00225</p>	
Unit	0.001 mm or 0.0001 inches		
Effective condition	Instant		
Applicable program	M		


Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description	
U8	Groove cutting clearance (diametral value) in X-axis	<p>Groove cutting clearance is provided at machining start portion in groove cutting unit (GRV).</p> <p><OUT></p>  <p style="text-align: right;">NM211-00226</p> <p><IN></p>  <p style="text-align: right;">NM211-00227</p> <p><FCE></p>  <p style="text-align: right;">NM211-00228</p> <p><BAK></p>  <p style="text-align: right;">NM211-00229</p>	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U9	Groove cutting clearance (diametral value) in Z-axis		
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	




PARAMETER (USER, CUTTING)

Address	Meaning	Description
<p>U10</p>	<p>Milling line right/left cutting clearance</p>	<p>Milling line right/left cutting clearance is provided to specify tool approach point and escape point in milling line right and left cutting unit (LFT, RGT).</p>  <p style="text-align: right;">NM211-00230</p>
	<p>Unit</p>	<p>0.001 mm or 0.0001 inches</p>
	<p>Effective condition</p>	<p>Instant</p>
	<p>Applicable program</p>	<p>M</p>
<p>U11</p>	<p>Workpiece transfer clearance</p>	<p>Workpiece transfer clearance is provided to specify workpiece transfer position in workpiece transfer unit (TRS).</p> <p>Example: Workpiece transferred from No. 1 spindle head to No. 2 spindle head.</p>  <p style="text-align: right;">NM211-00231</p> <p>No. 2 spindle head traverse by rapid feedrate from transfer position to position distant by clearance distance U11, and then transfer operation initiated.</p> <p>(⇒ U26, U27, U50)</p>
	<p>Unit</p>	<p>0.001 mm or 0.0001 inches</p>
	<p>Effective condition</p>	<p>Instant</p>
	<p>Applicable program</p>	<p>M</p>

Title of display **PARAMETER (USER, CUTTING)**



Address	Meaning	Description						
U12	Amount of edge clearance after EDG roughing	After EDG unit roughing, this parameter works instead of safety contour clearance FCE parameter U5 . If, however, U12 is zero, then U5 is used.						
	Unit		0.001 mm or 0.0001 inches					
	Effective condition		Instant					
	Applicable program		M					
U13	Radial finishing allowance for Y-axis mill-grooving unit (MGV)	The radial finishing allowance of arc cutting in the MAZATROL program mill-grooving unit (MGV) of Y-axis machining is set as follows: For the data <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: left;">UNo. UNIT # GRV-WID DEPTH FINISH</td> </tr> <tr> <td style="text-align: left;">MGV OUT [1]-[2] [3]</td> </tr> <tr> <td style="text-align: left;">[1] #2 : CW cutting</td> </tr> <tr> <td style="text-align: left;">#3 : CCW cutting</td> </tr> <tr> <td style="text-align: left;">[2] 2 : Radial and axial finishing</td> </tr> <tr> <td style="text-align: left;">[3] Axial finishing allowance</td> </tr> </table> </div> the radial finishing allowance becomes equal to [(Finishing allowance [3]) × (this parameter/100)].	UNo. UNIT # GRV-WID DEPTH FINISH	MGV OUT [1]-[2] [3]	[1] #2 : CW cutting	#3 : CCW cutting	[2] 2 : Radial and axial finishing	[3] Axial finishing allowance
	UNo. UNIT # GRV-WID DEPTH FINISH							
	MGV OUT [1]-[2] [3]							
	[1] #2 : CW cutting							
#3 : CCW cutting								
[2] 2 : Radial and axial finishing								
[3] Axial finishing allowance								
Unit	%							
Effective condition	Instant							
Applicable program	M							
U14	Amount of overlapping for Y-axis mill-grooving unit (MGV)	The amount of radial overlapping for arc cutting in the MAZATROL program mill-grooving unit (MGV) of Y-axis machining is set as follows: For the data <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: left;">UNo. UNIT # GRV-WID DEPTH</td> </tr> <tr> <td style="text-align: left;">MGV OUT [1]-[2]</td> </tr> <tr> <td style="text-align: left;">[1] #2 : CW cutting</td> </tr> <tr> <td style="text-align: left;">#3 : CCW cutting</td> </tr> </table> </div> the amount of radial overlapping is set so that the tool moves as shown below. <div style="text-align: center; margin: 10px 0;">  <p style="text-align: center;">Top view of grooves</p> </div>	UNo. UNIT # GRV-WID DEPTH	MGV OUT [1]-[2]	[1] #2 : CW cutting	#3 : CCW cutting		
	UNo. UNIT # GRV-WID DEPTH							
	MGV OUT [1]-[2]							
	[1] #2 : CW cutting							
#3 : CCW cutting								
Unit	0.001 mm or 0.0001 inches							
Effective condition	Instant							
Applicable program	M							

PARAMETER (USER, CUTTING)




Address	Meaning	Description																								
U18	Return speed at pecking portion in groove cutting unit (GRV) and drilling unit (DRL, MDR)	<p>Pecking speed</p>  <p>[1] Cutting: (G1) F command data [2] Pecking: (G1) U18 [3] Cutting: (G1) F command data</p> <p>When executing groove cutting with grooving pattern #0 (only for oblique groove) the tool returns from the groove bottom also at the "G1" feedrate determined by this parameter.</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>GRV #0 (Right-angled groove)</p>  <p>Returns at G0</p> </div> <div style="text-align: center;"> <p>GRV #0 (Oblique groove)</p>  <p>Returns at G1</p> </div> </div> <p>Note: In drilling unit (DRL, MDR), U18 setting will be used only for #2 [#2] type.</p>																								
	Unit	0.001 mm/rev or 0.0001 inches/rev																								
	Effective condition	Instant																								
	Applicable program	M																								
U19	Feedrate specification reference speed for finish cutting in milling line machining unit (MGV, LCT, RGT, LFT)	<p>This parameter, the roughness code, etc. determine the finish feedrate.</p> <p>If the radial-finishing feedrate is taken as F_1, then:</p> $F_1 \begin{cases} \mathbf{U19} \times \frac{D}{\mathbf{K32} \times \alpha} \times K_f \times Z & (D < \mathbf{K32} \times \alpha) \\ \mathbf{U19} \times K_f \times Z & (D \geq \mathbf{K32} \times \alpha) \end{cases}$ <p>If the axial-finishing feedrate is taken as F_2, then:</p> $F_2 = F_1 \times \frac{\mathbf{K23}}{100}$ <p>D : Tool diameter α : 0.1 (for metric specs.) or 0.01 (for inch specs.) K_f : Roughness coefficient (Refer to the list below.) Z : Number of teeth</p> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th>Roughness code</th> <th>K_f</th> <th>Roughness code</th> <th>K_f</th> <th>Roughness code</th> <th>K_f</th> </tr> </thead> <tbody> <tr> <td>▽ 1</td> <td>$K_0 \times 0.8^{-3}$</td> <td>▽▽ 4</td> <td>K_0</td> <td>▽▽▽▽ 7</td> <td>$K_0 \times 0.8^3$</td> </tr> <tr> <td>▽ 2</td> <td>$K_0 \times 0.8^{-2}$</td> <td>▽▽▽ 5</td> <td>$K_0 \times 0.8$</td> <td>▽▽▽▽ 8</td> <td>$K_0 \times 0.8^4$</td> </tr> <tr> <td>▽▽ 3</td> <td>$K_0 \times 0.8^{-1}$</td> <td>▽▽▽ 6</td> <td>$K_0 \times 0.8^2$</td> <td>▽▽▽▽ 9</td> <td>$K_0 \times 0.8^5$</td> </tr> </tbody> </table> <p style="text-align: right;">K_0=Standard data 0.5</p>	Roughness code	K_f	Roughness code	K_f	Roughness code	K_f	▽ 1	$K_0 \times 0.8^{-3}$	▽▽ 4	K_0	▽▽▽▽ 7	$K_0 \times 0.8^3$	▽ 2	$K_0 \times 0.8^{-2}$	▽▽▽ 5	$K_0 \times 0.8$	▽▽▽▽ 8	$K_0 \times 0.8^4$	▽▽ 3	$K_0 \times 0.8^{-1}$	▽▽▽ 6	$K_0 \times 0.8^2$	▽▽▽▽ 9	$K_0 \times 0.8^5$
	Roughness code	K_f	Roughness code	K_f	Roughness code	K_f																				
	▽ 1	$K_0 \times 0.8^{-3}$	▽▽ 4	K_0	▽▽▽▽ 7	$K_0 \times 0.8^3$																				
	▽ 2	$K_0 \times 0.8^{-2}$	▽▽▽ 5	$K_0 \times 0.8$	▽▽▽▽ 8	$K_0 \times 0.8^4$																				
▽▽ 3	$K_0 \times 0.8^{-1}$	▽▽▽ 6	$K_0 \times 0.8^2$	▽▽▽▽ 9	$K_0 \times 0.8^5$																					
Unit	0.001 mm/rev or 0.0001 inches/rev																									
Effective condition	Instant																									
Applicable program	M	(⇒ K23 , K32)																								

Title of display **PARAMETER (USER, CUTTING)**




Address	Meaning		Description
U21	Measurement skip feedrate (X-axis, Z-axis)		<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>(1) Workpiece measurement</p> <p>Measurement stroke (U59)</p> </div> <div style="text-align: center;"> <p>(2) Tool tip measurement</p> <p>Measurement stroke (U60)</p> </div> </div> <p>fa: Measurement approach speed (U22)</p> <p style="text-align: center;">NM211-00233 NM211-00234</p> <p>(⇒ U22, U59, U60)</p>
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M	
U22	Measurement approach speed (X-axis, Z-axis)		<p>Refer to (1) of U21.</p>
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M	
U23	Measurement skip speed (C-axis)		<p>[1], [3] : Traverse speed [2] : Measurement approach speed (U24) [4] : U23</p> <p style="text-align: right;">NM211-00235</p> <p>(⇒ U24)</p>
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M	
U24	Measurement approach speed (C-axis)		<p>Refer to U23.</p>
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
U25	Approaching speed for TPS function		Set a speed at which the tool approaches for the TPS function (tool nose position memory function) prior to the start of cutting feed.
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M	
U26	Workpiece pressing speed in workpiece transfer unit (TRS)		<p>Example: Workpiece transferred from No. 1 spindle head to No. 2 spindle head</p>  <p style="text-align: right;">NM211-00236</p> <p>Note: Set this parameter equal to or as close as possible to its standard value. Excessive or insufficient setting may cause a contact error.</p>
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M	
U27	Revolution number (min^{-1}) of two spindles in workpiece transfer while the spindles are rotating in workpiece transfer unit (TRS)		<p>Example: Workpiece transferred from No. 1 spindle head to No. 2 spindle head</p>  <p style="text-align: right;">NM211-00237</p>
	Unit	min^{-1} (rpm)	
	Effective condition	Instant	
	Applicable program	M	





Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description	
U28	Feedrate for escape by short distance	<p>For escape by very short distance, G01 feed speed will be faster than G00 to complete the operation. (If G00 is used, smoothing 0 detection will be made at the end position.) Therefore, for escape very short distance, use G01 command, and set the feed speed of this command as parameter.</p> <p>Example:</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Escape in finish cutting of EDG unit</p>  </div> <div style="text-align: center;"> <p>Escape in rough cutting of BAR unit</p>  </div> </div> <p>[1]: Feed speed in this block specified by G01 (U28)</p> <p style="text-align: right;">NM211-00238</p>	
	Unit	mm/min or 0.1 inches/min	(⇒ U33, U34, U43)
	Effective condition	Instant	
	Applicable program	M	
U29	Maximum angle for automatic corner overriding	<p>Designate the maximum angle for automatic corner overriding.</p> 	
	Unit	Degree	(⇒ U33, U34, U43)
	Effective condition	Instant	
	Applicable program	E	





PARAMETER (USER, CUTTING)

Address	Meaning	Description
U33	Return distance (diametral value) in X-axis at wall during rough cutting in bar cutting unit (BAR) or in corner machining unit (CNR)	<p>Example 1: Standard type cutting Prior to cutting up along the wall in the end of final cycle, escape will be made by specified distance.</p>  <p style="text-align: right;">NM211-00239</p>
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M
U34	Return distance (diametral value) in Z-axis at wall during rough cutting in bar cutting unit (BAR) or in corner machining unit (CNR) / Return distance after cutting in the rough-cutting cycle (G71, G72)	<p>Example 2: High speed rough cutting Escape will be made by U33 and U34 specified distance during return after reaching the wall.</p>  <p style="text-align: right;">NM211-00240</p>
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M, E
U34	Return distance (diametral value) in Z-axis at wall during rough cutting in bar cutting unit (BAR) or in corner machining unit (CNR) / Return distance after cutting in the rough-cutting cycle (G71, G72)	<p>Example 3: In the rough-cutting cycle (G71, G72) of the EIA program The tool escapes through the specified distance after cutting.</p> 
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M, E






Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description	
U35	Cut depth per cycle for machining inside diameter in bar machining unit (BAR)	<p>Inside diameter enlarging cycle</p>  <p style="text-align: right;">NM211-00241</p> <p style="text-align: center;">Cutting is promoted gradually from the edge, and machining chip removal efficient.</p>  <p>cf. Standard inside diameter cutting</p>  <p style="text-align: right;">Cutting to specified depth once through, and machining chip removal not efficient</p> <p style="text-align: right;">NM211-00242</p>	
		Unit	0.001 mm or 0.0001 inches
		Effective condition	Instant
		Applicable program	M
U36	Reverse feed tolerance for contour machining	<p>Example: Outside diameter machining in normal (- Z-axis direction)</p>  <p style="text-align: right;">dr: Reverse feed contour data</p> <p style="text-align: right;">NM211-00243</p> <p>dr ≤ U36 No alarm dr > U36 Alarm</p>	
		Unit	0.001 mm or 0.0001 inches
		Effective condition	Instant
		Applicable program	M




PARAMETER (USER, CUTTING)

Address	Meaning	Description	
U37	Overtravelling in X-axis direction in edge machining unit (EDG)	<div style="display: flex; justify-content: space-around;">   </div> <p style="text-align: right; font-size: small;">PS: Start point PE: End point NM211-00244</p> <p>Note: By setting an adequate value for U37, uncut residue will not be produced in edge machining.</p>  <p style="text-align: right; font-size: small;">Uncut residue because of nose R. etc. NM211-00245</p>	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U38	Acceleration distance clamp value for thread cutting unit (THR)	 <p style="text-align: right; font-size: small;">Program start point Thread cutting start point NM211-00246</p> <p style="font-size: small;">L : Effective thread length L₀: Acceleration distance</p> <p style="font-size: small;">If $L_0 > U38$, alarm will be caused. If, however, P1 (bit 3) = 0, alarm will not be caused.</p>	
	Unit	Lead/10	
	Effective condition	Instant	
	Applicable program	M	(⇒ P1 (Bit 3))

Title of display **PARAMETER (USER, CUTTING)**

Address	Meaning	Description
U39	Cut depth (diametral value) for final cut in thread cutting unit (THR) Cut depth (diametral value) for final cut in composite type thread cutting cycle G76	
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M, E
 <p style="text-align: right;">NM211-00247</p>		
U41	Pecking return distance in groove cutting unit (GRV)	
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M, E
 <p style="text-align: right;">NM211-00248</p>		
U42	Overlap distance for machining wide groove in groove cutting unit (GRV)	
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M
 <p style="text-align: right;">NM211-00249</p>		
U43	Escape value after machining in edge machining unit (EDG)	
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Instant
	Applicable program	M
<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><Rough cutting></p>  </div> <div style="text-align: center;"> <p><Finish cutting></p>  </div> </div> <p style="text-align: right;">NM211-00250</p>		

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning	Description	
U44	Drilling depth decrement in drilling unit (DRL, MDR)	<p style="text-align: right;">NM211-00251</p> <p>D : Drilling depth d1 : Cut depth in 1st cycle di : Cut depth in i-th cycle $d1 - U44 \times (i - 1)$ ($d_i \geq b$) b ($d_i < b$) b : Drilling depth clamping value (U46)</p>	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
		(⇒U46)	
U45	Pecking return distance in drilling unit (DRL, MDR)	<p style="text-align: right;">NM211-00252</p> <p>P1: Start point P2: End point D_n (n=1 to 4)=Cut depth</p>	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
U46	Drilling cut depth clamp value in drilling unit (DRL, MDR)	Minimum drilling cut depth is set.	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
		(⇒U44)	


Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
U47	Escape value after milling spindle orientating at hole button in boring unit (BOR)		<p>A: Cutting start point B: Milling spindle orientating position H: Machining depth</p>  <p style="text-align: right;">NM211-00252</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U48	Distance of deceleration for automatic corner overriding		<p>Set the area where automatic corner overriding is to be activated.</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	E	
U49	Tolerance for radial value difference at start and end points in arc command		 <p style="text-align: right;">NM211-00254</p> <p>[1]: Start point radius [2]: End point radius</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	E	
U50	Workpiece pressing distance in workpiece transfer unit (TRS)		<p>Example: Workpiece transferred from No. 1 spindle to No. 2 spindle</p>  <p>Workpiece transfer position specified in TRANSFER display</p> <p style="text-align: right;">NM211-00255</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
U51	Deceleration clearance at start of rough cutting in bar machining unit (BAR) and copy machining unit (CPY)		<p>Note: Using this parameter will reduce load in the initial contact between the tool and workpiece. (⇒K13)</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U52	Tolerance for escape in high speed rough cutting cycle of bar machining unit (BAR)		<p>d : Distance in cutting direction between P₁ and P₂</p> <p>If U52 ≥ d, tool eacape from the workpiece. If U52 < d, tool doesn't escape from the workpiece.</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U53	Minimum overlap distance for mill-grooving unit (MGV) and circular milling unit (CIR)		<p><Mill-grooving unit></p> <p>PS : Programmed start point PE : Programmed end point CS : Actual cutting start point CE : Actual cutting end point</p> <p><Circular milling unit></p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	




Title of display	PARAMETER (USER, CUTTING)
-------------------------	----------------------------------



Address	Meaning	Description
U54	Spindle revolution clamp value in cutting off cycle (GRV)	<p>If 0 or 1 is set up in U56: T32 mode This value will be used as the spindle revolution clamp value in cutting off cycle (GRV #4/#5).</p> <p>If 2 or more is set up in U56: New mode Immediately before the cutting off area (*) is reached during the cutting off cycle, this value will be used as the spindle revolution clamp value. Within the cutting off area, however, machining will be executed at the speed corresponding to this value.</p> <p>*: Cutting off area = (Starting position X – Ending position X) × K8/100</p>
	Unit	min ⁻¹ (rpm)
	Effective condition	Instant
	Applicable program	M
U55	Number of times of finishing when #0 (standard pattern) is selected in threading unit	<p>During finishing that uses #0 (standard pattern) of a threading unit, finishing is executed the number of times that has been set in parameter U55 with the depth of U39/U55.</p> <p>U55 = 0 or 1 Then the finishing is executed one time with the depth of U39.</p> <p>U55 ≥ 2 The finishing is repeated the number of times determined by U55 with the depth of U39/U55.</p> <p>Notes:</p> <ol style="list-style-type: none"> 1. Parameter U55 is valid only for #0 or [#0]. It is not valid for #1, [#1], #2 or [#2]. 2. Parameter U55 is not valid if U39 = 0. 3. The refinishing of threading is executed once as before.
	Unit	Times
	Effective condition	Instant
	Applicable program	M

PARAMETER (USER, CUTTING)

Address	Meaning	Description
U56	Number of times that the feedrate is to be reduced during the #4 and #5 cutting-off cycles of a grooving unit	<p>The starting feed value for cutting-off is a feed value that has been designated in unit data, and the ending feed value for cutting-off is a feed value that has been designated in sequence data. The feedrate from the start of machining to the end is reduced in steps according to the number of times that has been designated here.</p> <p>Example: Feedrate set at "R-FEED" item in unit data = 0.5 Feedrate set at "ROUGH" item in sequence data = 0.1 U56: 3</p> <div style="text-align: center;">  </div>
	Unit	Times
	Effective condition	Instant
	Applicable program	M
U57	Specification of measuring tolerance (lower limit)	<p>(1) Tool compensation will be made in cases below. $\frac{a_1 - a_2}{100} \times \mathbf{U58} \geq \text{Compensation data} \geq \frac{a_1 - a_2}{100} \times \mathbf{U57}$ $- \frac{a_1 - a_2}{100} \times \mathbf{U57} \geq \text{Compensation data} \geq - \frac{a_1 - a_2}{100} \times \mathbf{U58}$</p> <p>(2) Tool compensation will not be made in cases below. $\frac{a_1 - a_2}{100} \times \mathbf{U57} > \text{Compensation data} > - \frac{a_1 - a_2}{100} \times \mathbf{U57}$</p> <p>(3) Alarm will be caused in cases below. Compensation data $> \frac{a_1 - a_2}{100} \times \mathbf{U58}$ $- \frac{a_1 - a_2}{100} \times \mathbf{U58} > \text{Compensation data}$ where a_1 = Tolerance upper limit a_2 = Tolerance lower limit (Specified in program)</p>
	Unit	%
	Effective condition	Instant
	Applicable program	M, E
U58	Specification of measuring tolerance (upper-limit)	<p>Notes:</p> <ol style="list-style-type: none"> U57 and U58 are not used in tool tip measurement. Up to 100 % can be set.
	Unit	%
	Effective condition	Instant
	Applicable program	M, E

PARAMETER (USER, CUTTING)

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
U59	Measurement stroke for workpiece measurement		 <p>a : Approach point b : Measurement start point c : Measurement point (target data) d : Measurement end point</p> <p style="text-align: right;">NM211-00259</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U60	Measurement stroke for tool nose measurement		 <p>b : Measurement start point c : Measurement point (target data) d : Measurement end point</p> <p style="text-align: right;">NM211-00260</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U61	Coefficient to determine rotation angle when retrying measurement in C offset measurement unit (MES-COF)		<p>During approach operation to measurement start point, if touch sensor is actuated, the C-axis will rotate by angle determined by the measurement object shape angle and setting value U61.</p> <p>Example: CW programmed as measurement direction</p>  <p>α : Measurement object shape angle β : $\alpha \times \mathbf{U61}/100$</p> <p>C-axis rotation by angle β in this direction</p> <p style="text-align: right;">NM211-00261</p>
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
U62	Feed override for the section that is to be chamfered for planetary tapping cycle		Set the feed override for the section that is to be chamfered in the planetary tapping cycle. Chamfering feed = Feed of tapping tool sequence × U62 /100 
	Unit	%	
	Effective condition	Instant	
	Applicable program	M	
U63	Amount of escape at hole bottom for planetary tapping cycle		Specify the amount of escape at hole bottom of the planetary tapping cycle in terms of total threads. Amount of escape = Tapping pitch × U63 /10 
	Unit	0.1 thread	
	Effective condition	Instant	
	Applicable program	M	
U64	Specification of automatic pre-holing feed rate value for planetary tapping cycle		Set the pre-holing feed rate for the planetary tapping cycle.
	Unit	0.01 mm/rev or 0.001 inch/rev	
	Effective condition	Instant	
	Applicable program	M	
U65	Delay timer of M code for the parts catcher (No. 1 headstock)		Set dwell time for the parts catcher at No. 1 spindle head.
	Unit	0.001 sec	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
U66	Delay timer of M code for the parts catcher (No. 2 headstock)		Set dwell time for the parts catcher at No. 2 spindle head.
	Unit	0.001 sec	
	Effective condition	Instant	
	Applicable program	M	
U67	M-code value for making shape correction valid in the MAZATROL program		To make the shape correction function valid in the MAZATROL program, assign the value of U67 as the M-code. Also, the value of U67 is output as the M-code. However, M121 is output if '0' is specified in this parameter.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
U68	M-code value for making shape correction invalid in the MAZATROL program		To make the shape correction function invalid in the MAZATROL program, assign the value of U68 as the M-code. Also, the value of U68 is output as the M-code. However, M122 is output if '0' is specified in this parameter.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)										
Address	Meaning	Description										
U71	Selection of transfer pattern (TRS)	<p>Transfer pattern for the intended workpiece is specified by selecting 0, 1, 2 or 3 described below.</p> <table border="1"> <thead> <tr> <th>Setting</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>CHK, BAR : standard operation [CHK] : cannot be selected</td> </tr> <tr> <td>1</td> <td>CHK, BAR : standard operation [CHK] : cannot be selected</td> </tr> <tr> <td>2</td> <td>CHK, BAR : high-speed operation [CHK] : cannot be selected</td> </tr> <tr> <td>3</td> <td>CHK, BAR : high-speed operation [CHK] : cannot be selected</td> </tr> </tbody> </table> <p>Notes:</p> <ol style="list-style-type: none"> 1. Selecting [CHK] function specifies the transfer pattern by the gantry robot. 2. Even if 2 or 3 is selected, the operation of CHK or BAR may become standard one depending on machine model. 	Setting	Description	0	CHK, BAR : standard operation [CHK] : cannot be selected	1	CHK, BAR : standard operation [CHK] : cannot be selected	2	CHK, BAR : high-speed operation [CHK] : cannot be selected	3	CHK, BAR : high-speed operation [CHK] : cannot be selected
	Setting	Description										
	0	CHK, BAR : standard operation [CHK] : cannot be selected										
	1	CHK, BAR : standard operation [CHK] : cannot be selected										
2	CHK, BAR : high-speed operation [CHK] : cannot be selected											
3	CHK, BAR : high-speed operation [CHK] : cannot be selected											
Unit	—											
Effective condition	Instant											
Applicable program	M											
U75	Timer setting for manual TOOL EYE measurement	<p>During manual TOOL EYE measurement, it will not be regarded as a sensor ON status even if a sensor turns on for a time shorter than that which has been set in this parameter.</p>										
	Unit	7.1 msec										
	Effective condition	Instant										
	Applicable program	M, E										
U78	Selection as to tool life management alarm display	<p>Select whether alarms on tool life management (based on time, quantity and wear) are to be displayed.</p> <p>U78 = 0 Alarms on tool life management are displayed. [Time] Alarm No. 177 "TOOL LIFE EXCEED TIME" [Quantity] Alarm No. 178 "USED TOOL NUMBER EXCEED" [Wear] Alarm No. 179 "X-MAX OR Z-MAX OFFSET OVER"</p> <p>U78 = 1 Alarms are not displayed and machining continues.</p>										
	Unit	—										
	Effective condition	Instant										
	Applicable program	M, E										

Title of display		PARAMETER (USER, CUTTING)	
Address	Meaning		Description
U79	Setting range of MTP dwell time data		<p>U79 = 0 Any data from 0 to 99999 msec can be set on the PROGRAM display.</p> <p>U79 = 1 to 65535 Any data from 0 to U79 – 1 msec can be set on the PROGRAM display.</p>
	Unit	msec	
	Effective condition	Instant	
	Applicable program	M	
U81	Raw jaw forming workpiece length		<p>This parameter determines the workpiece length to be set in a program that has been automatically edited using the raw jaw forming function.</p> <p><For outside jaw 1 and inside jaw 1> Workpiece length = #4 + U81 (#4 : Raw jaw forming data)</p> <p><For outside jaw 2 and inside jaw 2> Workpiece length = #4 + #6 + U81 (#4, #6 : Raw jaw forming data)</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
U82	Specification of automatic feed rate value for planetary tapping cycle		Set the automatic feed rate for the planetary tapping cycle.
	Unit	0.01 mm/rev or 0.001 inch/rev	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, CUTTING)		
Address	Meaning	Description		
U83	Height of the second referential point during the Tornado cycle	<p>Set the height of the second referential point during the Torando cycle. ← Cutting feed With chamfering ($i_0 \neq 0$) ← Rapid feed</p>		
		<p>Without chamfering ($i_0 = 0$)</p>		
		Unit	0.001 mm or 0.0001 inches	
		Effective condition	Instant	
Applicable program	M			



MEP322

3-5 PARAMETER (USER, POINT D)


Title of display	PARAMETER (USER, POINT)
------------------	--------------------------------



Address	Meaning	Description																				
D1	Height of the second referential point during point machining	<div style="text-align: center;"> <p>Height of the second R-point</p> <p>Initial point</p> <p>D1</p> <p>Second R-point</p> <p>MPL001</p> </div> <p>The height of the referential point during point machining is basically U3 or U6, however, it is changed to D1 under the following conditions.</p> <table border="1" style="width: 100%;"> <thead> <tr> <th>Tool sequence</th> <th>Conditions</th> </tr> </thead> <tbody> <tr> <td>Drill</td> <td>Bit 6 of parameter D91 is set to 1 (D1 valid). There is a spot drill in the pre-machining tool sequence of the same unit.</td> </tr> <tr> <td>Reamer</td> <td>Bit 2 of parameter D92 is set to 1 (D1 valid). There is a chamfering cutter in the pre-machining tool sequence of the same unit.</td> </tr> </tbody> </table>	Tool sequence	Conditions	Drill	Bit 6 of parameter D91 is set to 1 (D1 valid). There is a spot drill in the pre-machining tool sequence of the same unit.	Reamer	Bit 2 of parameter D92 is set to 1 (D1 valid). There is a chamfering cutter in the pre-machining tool sequence of the same unit.														
	Tool sequence	Conditions																				
	Drill	Bit 6 of parameter D91 is set to 1 (D1 valid). There is a spot drill in the pre-machining tool sequence of the same unit.																				
	Reamer	Bit 2 of parameter D92 is set to 1 (D1 valid). There is a chamfering cutter in the pre-machining tool sequence of the same unit.																				
Unit	0.001 mm or 0.0001 inches																					
Effective condition	Instant																					
Applicable program	M																					
D2	Nominal diameter of spot-machining tool	<p>The nominal diameter of a spot-machining tool that is automatically set during automatic tool development.</p> <p>Example:</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: left;">SNo.</td> <td style="text-align: left;">TOOL</td> <td style="text-align: left;">NOM</td> <td style="text-align: left;">HOLE-φ</td> <td style="text-align: left;">HOLE-DEP</td> </tr> <tr> <td style="text-align: left;">1</td> <td style="text-align: left;">CTR-DR</td> <td style="text-align: left;">(20.)</td> <td style="text-align: left;">10.</td> <td style="text-align: left;">◆</td> </tr> <tr> <td></td> <td></td> <td style="text-align: center;">↑</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td style="text-align: center;">D2</td> <td></td> <td></td> </tr> </table>	SNo.	TOOL	NOM	HOLE-φ	HOLE-DEP	1	CTR-DR	(20.)	10.	◆			↑					D2		
	SNo.	TOOL	NOM	HOLE-φ	HOLE-DEP																	
	1	CTR-DR	(20.)	10.	◆																	
			↑																			
		D2																				
Unit	1 mm or 0.1 inches																					
Effective condition	Instant																					
Applicable program	M																					
D3	Spot-machining hole bottom dwell time element	<p>Axis feed dwell time at the hole bottom in a spot-machining cycle. Set this time in milling spindle revolutions.</p> <div style="text-align: center;"> <p>(Stops at hole bottom.)</p> </div> <p>When the spot-machining tool reaches the hole bottom, the Z-axis will firstly stop moving until the milling spindle makes D3 revolutions, and then return to the original position at the rapid feedrate.</p> <p style="text-align: right;">MPL002</p>																				
	Unit	Revolution																				
	Effective condition	Instant																				
	Applicable program	M																				

PARAMETER (USER, POINT)





Address	Meaning	Description								
D4	Maximum allowable spot-chamfering hole diameter element	<p>Element used to set the maximum spot-chamfering hole diameter (d) during automatic tool development</p>  <p>Spot-chamfering occurs if $d \leq D2 - D4$. If $d > D2 - D4$, the chamfering cutter is developed automatically.</p> <p style="text-align: right;">MPL003</p>								
	Unit	0.1 mm or 0.01 inches								
	Effective condition	Instant								
	Applicable program	M								
D5	Prehole through speed during inversed spot-facing	<p>The feedrate of a tool as it is being passed through the prehole during an inversed spot-facing cycle</p> <p>Note: 0.5 mm/rev if this parameter setting is 0.</p>  <p style="text-align: right;">MPL004</p>								
	Unit	1 mm or 0.1 inches								
	Effective condition	Instant								
	Applicable program	M								
D6	Drill-machining cycle setting element	<p>Element used to automatically set drill-machining cycles during automatic tool development</p> <table border="1" data-bbox="790 1265 1380 1534"> <thead> <tr> <th>Machining cycle</th> <th>Conditions</th> </tr> </thead> <tbody> <tr> <td>Drilling cycle</td> <td>$\frac{\text{DEPTH}}{\text{DIA}} \leq D6$</td> </tr> <tr> <td>High-speed deep-hole drilling cycle</td> <td>$D6 < \frac{\text{DEPTH}}{\text{DIA}} \leq D7$</td> </tr> <tr> <td>Deep-hole drilling cycle</td> <td>$D7 < \frac{\text{DEPTH}}{\text{DIA}}$</td> </tr> </tbody> </table>	Machining cycle	Conditions	Drilling cycle	$\frac{\text{DEPTH}}{\text{DIA}} \leq D6$	High-speed deep-hole drilling cycle	$D6 < \frac{\text{DEPTH}}{\text{DIA}} \leq D7$	Deep-hole drilling cycle	$D7 < \frac{\text{DEPTH}}{\text{DIA}}$
	Machining cycle	Conditions								
	Drilling cycle	$\frac{\text{DEPTH}}{\text{DIA}} \leq D6$								
	High-speed deep-hole drilling cycle	$D6 < \frac{\text{DEPTH}}{\text{DIA}} \leq D7$								
Deep-hole drilling cycle	$D7 < \frac{\text{DEPTH}}{\text{DIA}}$									
Unit	—									
Effective condition	Instant									
Applicable program	M									
D7	Drill-machining cycle setting element									
	Unit	—								
	Effective condition	Instant								
	Applicable program	M								


Title of display **PARAMETER (USER, POINT)**

Address	Meaning	Description										
D8	Maximum diameter of holes machinable on one drill	Element used to automatically set the number of drills which are automatically developed according to the hole diameter of the drill unit <table border="1" style="margin: 10px auto; border-collapse: collapse;"> <thead> <tr> <th style="width: 40%;">Number of drills developed</th> <th style="width: 60%;">Conditions</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">$DIA \leq D8$</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">$D8 < DIA \leq D9$</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">$D9 < DIA \leq D10$</td> </tr> <tr> <td style="text-align: center;">Alarm</td> <td style="text-align: center;">$D10 < DIA$</td> </tr> </tbody> </table>	Number of drills developed	Conditions	1	$DIA \leq D8$	2	$D8 < DIA \leq D9$	3	$D9 < DIA \leq D10$	Alarm	$D10 < DIA$
	Number of drills developed		Conditions									
	1		$DIA \leq D8$									
	2		$D8 < DIA \leq D9$									
3	$D9 < DIA \leq D10$											
Alarm	$D10 < DIA$											
Unit	1 mm or 0.1 inches											
Effective condition	Instant											
Applicable program	M											
D9	Maximum diameter of holes machinable on two drills											
	Unit		1 mm or 0.1 inches									
	Effective condition		Instant									
	Applicable program		M									
D10	Maximum diameter of holes machinable on three drills											
	Unit		1 mm or 0.1 inches									
	Effective condition		Instant									
	Applicable program		M									
D11	Through-hole/Tap-prehole machining overshoot	Element used to automatically set the hole-drilling, endmilling, and boring depths during automatic tool development of inversed spot-facing, tapping, back-boring, through-hole drilling, through-hole counter-boring, and spot-faced tapping units <div style="text-align: center; margin: 10px 0;">  </div> <p>Example:</p> <table style="margin: 0 auto; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">SNo.</th> <th style="text-align: left;">TOOL</th> <th style="text-align: left;">NOM</th> <th style="text-align: left;">HOLE-φ</th> <th style="text-align: left;">HOLE-DEP</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td style="text-align: left;">DRILL</td> <td style="text-align: center;">10.</td> <td style="text-align: center;">10.</td> <td style="text-align: center;">(21) ← (DEPTH + D11)</td> </tr> </tbody> </table> <p>Note: See also parameter K20 for tapping units.</p>	SNo.	TOOL	NOM	HOLE-φ	HOLE-DEP	1	DRILL	10.	10.	(21) ← (DEPTH + D11)
	SNo.		TOOL	NOM	HOLE-φ	HOLE-DEP						
	1		DRILL	10.	10.	(21) ← (DEPTH + D11)						
	Unit		0.1 mm or 0.01 inches									
Effective condition	Instant											
Applicable program	M											

Title of display		PARAMETER (USER, POINT)	
Address	Meaning		Description
D12	Stop-hole machining hole-bottom clearance		Element used to automatically set the hole-drilling depth during automatic tool development of stop-hole counter-boring and stop-hole boring units  Example: SNo. TOOL NOM HOLE-φ HOLE-DEP 1 DRILL 10. 10. (19.) ↑ (DEPTH – tool tip compensation – D12) Note: This parameter is invalid when the residual hole diameter is not 0. MPL006
	Unit	0.1 mm or 0.01 inches	
	Effective condition	Instant	
	Applicable program	M	
D13	Spot-machining hole diameter (fixed value)		Hole diameter is automatically set during automatic tool development when spot-chamfering is not to be performed.  Example: SNo. TOOL NOM HOLE-φ HOLE-DEP 1 CTR-DR 20. (10.) ◆ ↖ D13
	Unit	1 mm or 0.1 inches	
	Effective condition	Instant	
	Applicable program	M	
D14	Depth-of-cut setting element for drilling (ALMINUM)		Element used to automatically set the depth-of-cut per drilling operation during automatic tool development HOLE-φ × D14 : when the material of the stock workpiece is AL (aluminum) in article MAT. 6 HOLE-φ × D15 : when the material of the stock workpiece is other than AL in article MAT. 6
	Unit	0.1	
	Effective condition	Instant	
	Applicable program	M	
D15	Depth-of-cut setting element for drilling (except AL)		
	Unit	0.1	
	Effective condition	Instant	
	Applicable program	M	





Title of display **PARAMETER (USER, POINT)**

Address	Meaning		Description
D16	Hole-bottom dwell time for chamfering cutter		<p>Z-axis feed dwell time at the hole bottom in a chamfering cutter machining cycle. Set this time in milling spindle revolutions.</p>  <p>(Stops at hole bottom.)</p> <p>When the chamfering cutter reaches the hole bottom, the axis will firstly stop moving until the milling spindle makes D16 revolutions, and then return to the original position at the rapid feedrate.</p> <p>Note: This parameter is invalid for chamfering with true-circle processing.</p> <p style="text-align: right;">MPL008</p>
	Unit	Revolution	
	Effective condition	Instant	
	Applicable program	M	
D17	Interference clearance of chamfering cutter		<p>The clearance in order to prevent tool interference with a wall of the workpiece or with the hole bottom during a chamfering cycle</p>  <p style="text-align: right;">MPL009</p>
	Unit	0.01 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
D18	Return feedrate for reaming or boring (cycle 3)		<p>The feedrate at which the tool is returned from the hole bottom during reaming or boring.</p>  <p style="text-align: right;">MPL010</p> <p>Notes:</p> <ol style="list-style-type: none"> Valid only when the setting of ZFD for the reamer (tool sequence) is G01. Valid only when the setting of PRE-DIA for the boring tool (tool sequence) is CYCLE 3. If this parameter is 0, the tool is returned at the same feedrate as that of cutting.
	Unit	1 mm/min or 0.1 inch/min	
	Effective condition	Instant	
	Applicable program	M	
D19	Hole-bottom dwell time for end milling		<p>Axis feed dwell time at the hole bottom in an end milling cycle. Set this time in milling spindle revolutions.</p>  <p>(Stops at hole bottom.)</p> <p>When the end mill reaches the hole bottom, the axis will firstly stop moving until the milling spindle makes D19 revolutions, and then return to the original position at the rapid feedrate.</p> <p>Note: This parameter is invalid for true-circle processing.</p> <p style="text-align: right;">MPL011</p>
	Unit	Revolution	
	Effective condition	Instant	
	Applicable program	M	

Title of display		PARAMETER (USER, POINT)																	
Address	Meaning		Description																
D20	Radial depth-of-cut setting element for end milling		Element used to automatically set the radial depth-of-cut per end milling operation $\text{Depth-of-cut} = \text{nominal diameter} \times \text{D20}$ Depth-of-cut is automatically set according to the value of this parameter when nominal diameter of the end mill is input. Example: SNO. TOOL NOM HOLE-φ HOLE-DEP PRE-DIA PRE-DEP RGH DEPTH 1 E-MILL 20. 40. 10. 30. ◆ 0. (12.) (NOM × D20) ↗																
	Unit	%																	
	Effective condition	Instant																	
	Applicable program	M																	
D21	Reference bottom-finishing allowance for end milling		The reference value for calculation of a bottom-finishing allowance which corresponds to the roughness level of the end milling (tool sequence). The finishing allowance in the case of roughness level 4 becomes the value of this parameter, and the values for all other roughness levels are set using the expressions listed in the table below.																
	Unit	0.001 mm or 0.0001 inches																	
	Effective condition	Instant																	
	Applicable program	M																	
		<table border="1"> <thead> <tr> <th>Roughness</th> <th>Bottom-finishing allowance</th> </tr> </thead> <tbody> <tr> <td>0 to 3</td> <td>0.0</td> </tr> <tr> <td>4</td> <td>D21</td> </tr> <tr> <td>5</td> <td>D21 × 0.7</td> </tr> <tr> <td>6</td> <td>D21 × 0.7 × 0.7</td> </tr> <tr> <td>7</td> <td>D21 × 0.7 × 0.7 × 0.7</td> </tr> <tr> <td>8</td> <td>D21 × 0.7 × 0.7 × 0.7 × 0.7</td> </tr> <tr> <td>9</td> <td>D21 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7</td> </tr> </tbody> </table>		Roughness	Bottom-finishing allowance	0 to 3	0.0	4	D21	5	D21 × 0.7	6	D21 × 0.7 × 0.7	7	D21 × 0.7 × 0.7 × 0.7	8	D21 × 0.7 × 0.7 × 0.7 × 0.7	9	D21 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7
Roughness	Bottom-finishing allowance																		
0 to 3	0.0																		
4	D21																		
5	D21 × 0.7																		
6	D21 × 0.7 × 0.7																		
7	D21 × 0.7 × 0.7 × 0.7																		
8	D21 × 0.7 × 0.7 × 0.7 × 0.7																		
9	D21 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7																		
D22	Tapping-cycle dwell time		Dwell time at the hole bottom in the tapping cycle.																
	Unit	0.01 sec																	
	Effective condition	Instant																	
	Applicable program	M																	
D24	Hole-bottom dwell time for boring		Axis feed dwell time at the hole bottom in a boring cycle. Set this time in milling spindle revolutions.																
	Unit	Revolution																	
	Effective condition	Instant																	
	Applicable program	M																	
		 <p>(Stops at hole bottom.)</p> <p>When the boring bar reaches the hole bottom, the axis will firstly stop moving until the milling spindle makes D24 revolutions, and then the milling spindle orientation will be performed.</p> <p>Note: This parameter is invalid if the roughness of the boring (tool sequence) is 0.</p>																	



MPL013

PARAMETER (USER, POINT)

Title of display		PARAMETER (USER, POINT)									
Address	Meaning		Description								
D26	Boring or back-boring hole-bottom return		<p>The distance which the boring or back-boring tool is returned at the same feedrate as for cutting after the tool has reached the hole bottom</p>  <p>[1] Has reached the hole bottom. [2] Returned at the same feedrate. [3] Returned at a rapid feedrate.</p> <p>MPL015</p> <p>Note: Not valid if the setting for the roughness of the boring (tool sequence) is 1.</p>								
	Unit	0.001 mm or 0.0001 inches									
	Effective condition	Instant									
	Applicable program	M									
D28	Bottom-finishing amount of boring		<p>The distance which the boring bar is fed in at 70% of the original feedrate to finish the hole bottom</p>  <p>MPL016</p> <p>The feedrate is reduced to 70% of the original value before the hole bottom is reached.</p> <p>Note: Not valid if the setting for the roughness of the boring (tool sequence) is 1.</p>								
	Unit	0.001 mm or 0.0001 inches									
	Effective condition	Instant									
	Applicable program	M									
D33	Back-boring tool tip relief		<p>The amount of relief provided for a back-boring tool tip to be kept clear of the prehole walls as it is being passed through the prehole in the oriented state of the spindle</p>  <p>[1] During back-boring [2] During passage</p> <p>MPL019</p>								
	Unit	0.001 mm or 0.0001 inches									
	Effective condition	Instant									
	Applicable program	M									
D35	Prehole-drilling diameter setting element for reamer (drilling)		<p>Element used to automatically set the prehole-drilling diameter during automatic tool development of the reamer unit (When the pre-machining unit is drilling.)</p>  <p>MPL020</p> <p>Example:</p> <table border="0"> <tr> <td>SNo.</td> <td>TOOL</td> <td>NOM</td> <td>HOLE-φ</td> </tr> <tr> <td>1</td> <td>DRILL</td> <td>10.</td> <td>(10) ← D35</td> </tr> </table>	SNo.	TOOL	NOM	HOLE-φ	1	DRILL	10.	(10) ← D35
	SNo.	TOOL		NOM	HOLE-φ						
	1	DRILL		10.	(10) ← D35						
	Unit	0.01 mm or 0.001 inches									
Effective condition	Instant										
Applicable program	M										

Title of display		PARAMETER (USER, POINT)		
Address	Meaning		Description	
D36	Prehole-drilling diameter setting element for reamer (boring)		used to automatically set the prehole-drilling diameter during automatic tool development of the reamer unit (When the pre-machining unit is boring.) 	
	Unit	0.01 mm or 0.001 inches		Example: SNo. TOOL NOM HOLE-φ 1 DRILL 10. (10.) ← D36
	Effective condition	Instant		
	Applicable program	M		
D37	Prehole-drilling diameter setting element for reamer (end milling)		Element used to automatically set the prehole-drilling diameter during automatic tool development of the reamer unit (When the pre-machining unit is end milling.) 	
	Unit	0.01 mm or 0.001 inches		Example: SNo. TOOL NOM HOLE-φ 1 DRILL 10. (10.) ← D37
	Effective condition	Instant		
	Applicable program	M		
D38	Machining hole diameter setting element for boring tool or end mill in the reamer unit		1) In automatic tool development of the reamer unit, if the pre-machining unit is boring: 	
	Unit	0.01 mm or 0.001 inches		Example: SNo. TOOL NOM HOLE-φ 1 BOR BAR 10. (10.) ← (DIA - D38)
	Effective condition	Instant		
	Applicable program	M		
D39	Machining hole diameter setting element for end mill in the reamer unit		2) In automatic tool development of the reamer unit, if the pre-machining unit is end milling: 	
	Unit	0.01 mm or 0.001 inches		Example: SNo. TOOL NOM HOLE-φ 1 E-MILL 15. (20.) ← (DIA - D39) 1 E-MILL 10. (21.) ← (DIA - D38)
	Effective condition	Instant		
	Applicable program	M		

Title of display **PARAMETER (USER, POINT)**

Address	Meaning	Description						
D40	Spot-faced hole bottom dwell time for inversed spot-facing	<p>Axis feed dwell time at the spot-faced hole bottom in an inversed spot facing cycle. Set this time in milling spindle revolutions.</p>  <p>(Feeding stops at hole bottom.)</p> <p>When the inversed spot-facing tool reaches the hole bottom, firstly the axis will stop moving until the milling spindle makes D40 revolutions, and then the rotational direction of the milling spindle will reverse.</p> <p>MPL023</p>						
	Unit	Revolution						
	Effective condition	Instant						
	Applicable program	M						
D42	Height of the third referential point during point machining	<p>Height of the third referential point</p>  <p>MPL001</p> <p>The height of the referential point during point machining is basically U3 to U6, however, it is changed to D42 under the following conditions.</p> <table border="1" data-bbox="774 1153 1412 1377"> <thead> <tr> <th>Tool sequence</th> <th>Conditions</th> </tr> </thead> <tbody> <tr> <td>Drill</td> <td>- Bit 6 of parameter D91 is set to 1 (D42 valid). - There is a spot drill in the pre-machining tool sequence of the same unit.</td> </tr> <tr> <td>Chamfering cutter</td> <td>- Bit 7 of parameter D91 is set to 1 (D42 valid). - CYCLE 2 is selected for the machining cycle.</td> </tr> </tbody> </table>	Tool sequence	Conditions	Drill	- Bit 6 of parameter D91 is set to 1 (D42 valid). - There is a spot drill in the pre-machining tool sequence of the same unit.	Chamfering cutter	- Bit 7 of parameter D91 is set to 1 (D42 valid). - CYCLE 2 is selected for the machining cycle.
	Tool sequence	Conditions						
	Drill	- Bit 6 of parameter D91 is set to 1 (D42 valid). - There is a spot drill in the pre-machining tool sequence of the same unit.						
	Chamfering cutter	- Bit 7 of parameter D91 is set to 1 (D42 valid). - CYCLE 2 is selected for the machining cycle.						
Unit	0.001 mm or 0.0001 inches							
Effective condition	Instant							
Applicable program	M							

PARAMETER (USER, POINT)



Address	Meaning	Description										
D43	Number of incomplete threads in tapping cycle	<p>To set number of incomplete threads in tapping cycle for piped screws (PT, PF, PS). In tapping, internal thread is tapped extra for the depth of (D43 × pitch/10).</p> <p>This is also used as an element for automatically determining hole-drilling depth in the automatic tool development of the tapping unit.</p> <div style="text-align: center;"> </div> <p style="text-align: right;">MPL07</p> <p>Example:</p> <table style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>SNo.</th> <th>TOOL</th> <th>NOM</th> <th>HOLE-φ</th> <th>HOLE-DEP</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">DRILL</td> <td style="text-align: center;">10.</td> <td style="text-align: center;">10.</td> <td style="text-align: center;">(19.)</td> </tr> </tbody> </table> <p style="text-align: center;">↑ DEPTH + D11 + (D43 × pitch/10)</p>	SNo.	TOOL	NOM	HOLE-φ	HOLE-DEP	1	DRILL	10.	10.	(19.)
	SNo.	TOOL	NOM	HOLE-φ	HOLE-DEP							
	1	DRILL	10.	10.	(19.)							
	Unit	Pitch/10										
Effective condition	Instant											
Applicable program	M											
D44	Automatic calculation method for the amount of chamfering using the tapping unit	<p>This parameter specifies a method of automatic calculation of the amount of chamfering using the tapping unit.</p> <p>0: Amount of chamfering = $\frac{(\text{MAJOR-}\phi + 2 \times \text{PITCH}) - \text{PRE-DIA}}{2}$</p> <p>1: Amount of chamfering = $\frac{\text{MAJOR-}\phi - \text{PRE-DIA}}{2}$</p> <p>Note: Select 1 for a thin part if the loss of the threaded section by chamfering is likely.</p>										
	Unit	—										
	Effective condition	Instant										
	Applicable program	M										

Title of display **PARAMETER (USER, POINT)**

Address	Meaning	Description												
D45	Amount of mill-drilling depth attenuation	<p>Set the amount of mill-drilling depth attenuation.</p> <p style="text-align: right;">NM211-00251</p> <p>D : Drilling depth d1 : Cut depth in 1st cycle di : Cut depth in i-th cycle $d_i : d_1 - D45 \times (i - 1)$ ($d_i \geq b$) $d_i : b$ ($d_i < b$) b : Drilling depth clamping value (D46)</p>												
	Unit	0.001 mm or 0.0001 inches												
	Effective condition	Instant												
	Applicable program	M	(⇒D46)											
D46	Mill-drilling depth clamping value	<p>Set the minimum drilling depth.</p>												
	Unit	0.001 mm or 0.0001 inches												
	Effective condition	Instant												
	Applicable program	M	(⇒D45)											
D47	Reamer-prehole machining overshoot	<p>Element used to automatically set the hole depth of drilling, end milling and boring during automatic tool development of the reamer unit</p> <p style="text-align: right;">MPL025</p>												
	Unit	0.01 mm or 0.001 inches												
	Effective condition	Instant												
	Applicable program	M	<p>Example:</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;">SNo.</td> <td style="width: 10%;">TOOL</td> <td style="width: 10%;">NOM</td> <td style="width: 10%;">HOLE-φ</td> <td style="width: 10%;">HOLE-DEP</td> <td></td> </tr> <tr> <td>1</td> <td>DRILL</td> <td>10.</td> <td>10.</td> <td style="text-align: center;">(21)</td> <td>← (DEPTH + D47)</td> </tr> </table>	SNo.	TOOL	NOM	HOLE-φ	HOLE-DEP		1	DRILL	10.	10.	(21)
SNo.	TOOL	NOM	HOLE-φ	HOLE-DEP										
1	DRILL	10.	10.	(21)	← (DEPTH + D47)									

Title of display		PARAMETER (USER, POINT)									
Address	Meaning		Description								
D73 to D75	Learning of cutting conditions (For end mill, DEP-A range)		<p>Specify the range of end mill DEP-A using the cutting-conditions learning function.</p> <p>The cutting conditions will be learned when the specified DEP-A range falls within the specifications shown below.</p> <p>Re-learning will not occur if the learned data already exists.</p> <p>Set the value of the "cutting depth/tool diameter" (0.1% steps) as the range of end mill DEP-A.</p> <table border="1"> <tr> <td>DEP-A range</td> <td>1</td> <td>2</td> <td>3</td> </tr> <tr> <td>DEP-A/NOM (0.1 %)</td> <td>0 to D73</td> <td>D73 to D74</td> <td>D74 to D75</td> </tr> </table>	DEP-A range	1	2	3	DEP-A/NOM (0.1 %)	0 to D73	D73 to D74	D74 to D75
	DEP-A range	1		2	3						
	DEP-A/NOM (0.1 %)	0 to D73		D73 to D74	D74 to D75						
	Unit	0.1 %									
Effective condition	Instant										
Applicable program	M										
D76 D77	Learning of cutting conditions (For face mill, DEP-A range)		<p>Specify the range of face mill DEP-A using the cutting-conditions learning function.</p> <p>The cutting conditions will be learned when the specified DEP-A range falls within the specifications shown below.</p> <p>Re-learning will not occur if the learned data already exists.</p> <p>Set the value of the cutting depth (0.1 mm/0.01 inch steps) as the range of face mill DEP-A.</p> <table border="1"> <tr> <td>DEP-A range</td> <td>1</td> <td>2</td> </tr> <tr> <td>DEP-A (0.1 mm/0.01 in.)</td> <td>0 to D76</td> <td>D76 to D77</td> </tr> </table>	DEP-A range	1	2	DEP-A (0.1 mm/0.01 in.)	0 to D76	D76 to D77		
	DEP-A range	1		2							
	DEP-A (0.1 mm/0.01 in.)	0 to D76		D76 to D77							
	Unit	0.1 mm or 0.01 inches									
Effective condition	Instant										
Applicable program	M										
D78 D79	Learning of cutting conditions (Boring tool/Back boring tool, DEP-R range)		<p>Specify the range of boring/back boring tool DEP-R using the cutting-conditions learning function.</p> <p>The cutting conditions will be learned when the specified DEP-R range falls within the specifications shown below.</p> <p>Re-learning will not occur if the learned data already exists.</p> <p>Set the value of the cutting depth (0.1 mm/0.01 inch steps) as the range of boring/back boring tool DEP-R.</p> <table border="1"> <tr> <td>DEP-R range</td> <td>1</td> <td>2</td> </tr> <tr> <td>DEP-R (0.1 mm/0.01 in.)</td> <td>0 to D78</td> <td>D78 to D79</td> </tr> </table>	DEP-R range	1	2	DEP-R (0.1 mm/0.01 in.)	0 to D78	D78 to D79		
	DEP-R range	1		2							
	DEP-R (0.1 mm/0.01 in.)	0 to D78		D78 to D79							
	Unit	0.1 mm or 0.01 inches									
Effective condition	Instant										
Applicable program	M										
D80 to D82	Learning of cutting conditions (End mill, DEP-R range)		<p>Specify the range of end mill DEP-R using the cutting-conditions learning function.</p> <p>The cutting conditions will be learned when the specified DEP-R range falls within the specifications shown below.</p> <p>Re-learning will not occur if the learned data already exists.</p> <p>Set the value of the "cutting depth/tool diameter" (0.1% steps) as the range of end mill DEP-R.</p> <table border="1"> <tr> <td>DEP-R range</td> <td>1</td> <td>2</td> <td>3</td> </tr> <tr> <td>DEP-R/NOM (0.1 %)</td> <td>0 to D80</td> <td>D80 to D81</td> <td>D81 to D82</td> </tr> </table>	DEP-R range	1	2	3	DEP-R/NOM (0.1 %)	0 to D80	D80 to D81	D81 to D82
	DEP-R range	1		2	3						
	DEP-R/NOM (0.1 %)	0 to D80		D80 to D81	D81 to D82						
	Unit	0.1 %									
Effective condition	Instant										
Applicable program	M										


Title of display **PARAMETER (USER, POINT)**


Address	Meaning		Description
D91	—		 <p>(1: Execution, 0: No execution)</p> <p>If a spot drill/drill is included in the pre-machining tool sequence of the same unit, the referential point height of the drill is set as D1 or D42.</p> <p>The referential point height of the chamfering cutter during the cycle 2 is set as D42.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
D92	—		 <p>(1: Execution, 0: No execution)</p> <p>During a true-circle processing (end milling) cycle, K41 is used for axial feed.</p> <p>The referential point 1 height of the back spot facing is set as D1.</p> <p>If a chamfering cutter is included in the pre-machining tool sequence of the same unit, the referential point height of the reamer is set as D1.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
D95 (bit 0)	Data auto-setting method selection for pipe tapping		<p>P95 (bit 0) = 0: Conventional method</p> <p>P95 (bit 0) = 1: Text file registration data reference method</p> <p>Data that has been registered in the required text file is used for automatic pipe-tapping data setting in MAZATROL PROGRAM display or TOOL DATA display.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
D95 (bit 1)	Data auto-setting method selection for unified tapping		<p>P95 (bit 1) = 0: Conventional method</p> <p>P95 (bit 1) = 1: Text file registration data reference method</p> <p>Data that has been registered in the required text file is used to set the pre-hole drilling diameter automatically for automatic development of unified tapping data in MAZATROL PROGRAM display.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	




3 PARAMETER



Title of display		PARAMETER (USER, POINT)	
Address	Meaning		Description
D95 (bit 2)	Data auto-setting method selection for metric tapping		<p>P95 (bit 2) = 0: Conventional method P95 (bit 2) = 1: Text file registration data reference method</p> <p>Data that has been registered in the required text file is used to set the pre-hole drilling diameter automatically for automatic development of metric tapping data in MAZATROL PROGRAM display.</p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

3-6 PARAMETER (USER, LINE E)



Title of display		PARAMETER (USER, LINE)																	
Address	Meaning		Description																
E1	Closed-pattern cutting start point and escape point setting element		<p>Element used to set cutting start point and escape point for closed-pattern line- or face-machining</p> <p>Example:</p>  <p>[Applicable units] - LINE OUT, LINE IN, CHMF OUT and CHMF IN - Wall finishing of POCKET</p>																
	Unit	0.001 mm or 0.0001 inches																	
	Effective condition	Instant																	
	Applicable program	M																	
E4	Reference allowance of finishing in radial direction		<p>The reference value of each finishing allowance R (FIN-R) which is automatically set when the roughness levels of the line- or face-machining units have been set</p> <p>The finishing allowance R in the case of roughness level 4 becomes the value of this parameter, and the values for all other roughness levels are calculated using the expressions listed in the table below.</p> <table border="1" data-bbox="821 996 1364 1243"> <thead> <tr> <th>Roughness</th> <th>FIN-R</th> </tr> </thead> <tbody> <tr> <td>0 to 3</td> <td>0.0</td> </tr> <tr> <td>4</td> <td>E4</td> </tr> <tr> <td>5</td> <td>E4 × 0.7</td> </tr> <tr> <td>6</td> <td>E4 × 0.7 × 0.7</td> </tr> <tr> <td>7</td> <td>E4 × 0.7 × 0.7 × 0.7</td> </tr> <tr> <td>8</td> <td>E4 × 0.7 × 0.7 × 0.7 × 0.7</td> </tr> <tr> <td>9</td> <td>E4 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7</td> </tr> </tbody> </table>	Roughness	FIN-R	0 to 3	0.0	4	E4	5	E4 × 0.7	6	E4 × 0.7 × 0.7	7	E4 × 0.7 × 0.7 × 0.7	8	E4 × 0.7 × 0.7 × 0.7 × 0.7	9	E4 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7
	Roughness	FIN-R																	
	0 to 3	0.0																	
	4	E4																	
5	E4 × 0.7																		
6	E4 × 0.7 × 0.7																		
7	E4 × 0.7 × 0.7 × 0.7																		
8	E4 × 0.7 × 0.7 × 0.7 × 0.7																		
9	E4 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7																		
Unit	0.001 mm or 0.0001 inches																		
Effective condition	Instant																		
Applicable program	M																		
E5	Element used to set the cutting start point and escape point (the second clearance)		<p>Element used to set the cutting start point and escape point (the second clearance)</p> <p>U10 is used generally as a clearance on the plane, however, E5 is used when the condition meets both of 1) and 2) mentioned below.</p> <ol style="list-style-type: none"> 1) There is pre-machining in the same unit. 2) The parameter (E92, E95) that makes E5 effective is set to ON (1). <p>[Applicable units] LINE OUT, LINE IN, POCKET</p> <p>[Related parameters]</p> <p>E92 bit 3 } Parameter that effectuates E5 in the applicable unit. E95 bit 7 }</p>																
	Unit	0.001 mm or 0.0001 inches																	
	Effective condition	Instant																	
	Applicable program	M																	

Title of display		PARAMETER (USER, LINE)																	
Address	Meaning		Description																
E6	Reference allowance of finishing in axial direction		<p>The reference value of each finishing allowance which is automatically set when the roughness levels of the line- or face-machining units have been set</p> <p>The finishing allowance in the case of roughness level 4 becomes the value of this parameter, and the values for all other roughness levels are calculated using the expressions listed in the table below.</p> <table border="1"> <thead> <tr> <th>Roughness</th> <th>FIN-A</th> </tr> </thead> <tbody> <tr> <td>0 to 3</td> <td>0.0</td> </tr> <tr> <td>4</td> <td>E6</td> </tr> <tr> <td>5</td> <td>E6 × 0.7</td> </tr> <tr> <td>6</td> <td>E6 × 0.7 × 0.7</td> </tr> <tr> <td>7</td> <td>E6 × 0.7 × 0.7 × 0.7</td> </tr> <tr> <td>8</td> <td>E6 × 0.7 × 0.7 × 0.7 × 0.7</td> </tr> <tr> <td>9</td> <td>E6 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7</td> </tr> </tbody> </table>	Roughness	FIN-A	0 to 3	0.0	4	E6	5	E6 × 0.7	6	E6 × 0.7 × 0.7	7	E6 × 0.7 × 0.7 × 0.7	8	E6 × 0.7 × 0.7 × 0.7 × 0.7	9	E6 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7
	Roughness	FIN-A																	
	0 to 3	0.0																	
	4	E6																	
5	E6 × 0.7																		
6	E6 × 0.7 × 0.7																		
7	E6 × 0.7 × 0.7 × 0.7																		
8	E6 × 0.7 × 0.7 × 0.7 × 0.7																		
9	E6 × 0.7 × 0.7 × 0.7 × 0.7 × 0.7																		
Unit	0.001 mm or 0.0001 inches																		
Effective condition	Instant																		
Applicable program	M																		
E7	Allowance of cutting start point in axial direction (the second clearance)		<p>Allowance of cutting start point in axial direction</p> <p>For the line- or face-machining, U3 to U6 is used as an axial clearance for rapid access to the machining point from the initial point, however, E7 is used when the condition meets both of 1) and 2) mentioned below.</p> <ol style="list-style-type: none"> 1) There is pre-machining in the same unit. 2) The parameter (E92, E95, E96 and E97) that makes E7 effective is set to ON (1). <p>[Applicable units] All line-/face-machining units except the face milling face unit.</p> <p>[Related parameters]</p> <table border="0"> <tr> <td>E92 bit 2</td> <td rowspan="4">} Parameter that effectuates E7 in the applicable unit.</td> </tr> <tr> <td>E95 bit 6</td> </tr> <tr> <td>E96 bit 1</td> </tr> <tr> <td>E97 bit 2</td> </tr> </table>	E92 bit 2	} Parameter that effectuates E7 in the applicable unit.	E95 bit 6	E96 bit 1	E97 bit 2											
	E92 bit 2	} Parameter that effectuates E7 in the applicable unit.																	
	E95 bit 6																		
	E96 bit 1																		
E97 bit 2																			
Unit	0.001 mm or 0.0001 inches																		
Effective condition	Instant																		
Applicable program	M																		
E8	Radial interference clearance of chamfering cutter		<p>The amount of clearance that prevents interference of the chamfering cutter with the hole walls during face-machining</p>  <p style="text-align: right;">MPL028</p>																
	Unit	0.001 mm or 0.0001 inches																	
	Effective condition	Instant																	
	Applicable program	M																	

Title of display		PARAMETER (USER, LINE)	
Address	Meaning		Description
E10	Depth-of-cut-R automatic setting element (Face milling, End milling-top)		Element used to automatically set the radial depth-of-cut of the tool sequence in FACE MIL or TOP EMIL unit $WID-R = \frac{NOM \times E10}{10}$ Example: SNO. TOOL NOM APRCH-1 APRCH-2 TYPE AFD DEP-A WID-R R1 F-MILL 100A ? ? XBI ◆ 1. (19) ↑ $\frac{NOM \times E10}{10}$
	Unit	10%	
	Effective condition	Instant	
	Applicable program	M	
E11	Axial interference clearance of chamfering cutter		The amount of clearance that prevents interference of the chamfering cutter with the hole bottom during chamfering 
	Unit	0.001 mm or 0.0001 inches	MPL030
	Effective condition	Instant	
	Applicable program	M	
E12	Radial interference clearance of face milling unit		The amount of clearance that prevents interference between the tool and the figure during face milling Example: 
	Unit	0.001 mm or 0.0001 inches	MPL031
	Effective condition	Instant	
	Applicable program	M	
E13	Tool path setting element for end milling-top unit		Element used to set the tool path internal to the figure for end milling-top unit Example: $\text{Tool diameter} \times \frac{E13}{10}$ 
	Unit	10%	MPL032
	Effective condition	Instant	
	Applicable program	M	




Title of display		PARAMETER (USER, LINE)																		
Address	Meaning	Description																		
E14	Depth-of-cut-R automatic setting element (Pocket milling)	<p>Element used to automatically set the radial depth-of-cut of the tool sequence in POCKET unit</p> $WID-R = \frac{NOM \times E14}{10}$ <p>Example:</p> <table border="1"> <tr> <td>SNO.</td> <td>TOOL</td> <td>NOM</td> <td>APRCH-1</td> <td>APRCH-2</td> <td>TYPE</td> <td>AFD</td> <td>DEP-A</td> <td>WID-R</td> </tr> <tr> <td>R1</td> <td>E-MILL</td> <td>20.</td> <td>?</td> <td>?</td> <td>CW</td> <td>G01</td> <td>10.</td> <td>12</td> </tr> </table> <p style="text-align: right;"> $\frac{NOM \times E14}{10}$ </p>	SNO.	TOOL	NOM	APRCH-1	APRCH-2	TYPE	AFD	DEP-A	WID-R	R1	E-MILL	20.	?	?	CW	G01	10.	12
	SNO.	TOOL	NOM	APRCH-1	APRCH-2	TYPE	AFD	DEP-A	WID-R											
	R1	E-MILL	20.	?	?	CW	G01	10.	12											
	Unit	10%																		
Effective condition	Instant																			
Applicable program	M																			
E15	Tool path setting element for face milling-top unit (reciprocating short)	<p>Element used to set the tool path external to the defined figure for reciprocating-short machining with face milling unit</p> <p>Example:</p>  <p style="text-align: right;"> $\frac{E15}{10}$ MPL033 </p>																		
	Unit	10%																		
	Effective condition	Instant																		
	Applicable program	M																		
E17	Axial cutting feed override	<p>Denote the feed override value for axial movement to the intended plane during the use of a line- or plane-machining unit, except for face-milling.</p> <p>Notes:</p> <ol style="list-style-type: none"> 1. This parameter is valid only when tool sequence AFD is G01. 2. Feed override is invalid if this parameter is "0". <p>Example:</p>  <p style="text-align: right;"> $\frac{E17}{10}$ MPL035 </p>																		
	Unit	10%																		
	Effective condition	Instant																		
	Applicable program	M																		

Title of display **PARAMETER (USER, LINE)**

Address	Meaning	Description
E18	Override in case of the overall width cutting for pocket-machining	<p>Override value of feedrate when the pocket-machining radial depth-of-cut becomes equal to the tool diameter</p> <p>Example:</p>  <p style="text-align: right;">$FR \times \frac{E18}{10}$</p> <p style="text-align: right;">MPL036</p>
	Unit	10%
	Effective condition	Instant
	Applicable program	M
		<p>Note:</p> <p>Overriding for overall width cutting is not valid when this parameter is 0.</p> <p>[Applicable units]</p> <p>Rough-machining of POCKET</p>
E21	Overlapping depth during wall cutting in a closed pattern	<p>Denote the depth of overlapping between the starting and ending positions of wall cutting in a closed line- or plane-machining pattern.</p> <p>Example:</p>  <p style="text-align: right;">MPL037</p>
	Unit	0.001 mm or 0.0001 inch
	Effective condition	Instant
	Applicable program	M
		<p>[Applicable units]</p> <ul style="list-style-type: none"> - LINE OUT, LINE INE, CHMF OUT and CHMF IN - Wall finishing of E-MIL and SLOT.

Title of display		PARAMETER (USER, LINE)	
Address	Meaning	Description	
E92	Tool-path pattern selection for pocket milling unit	<p> { 0: Machining from inside to outside { 1: Machining from outside to inside { 0: The referential point height is set always as U3 to U6. { 1: The referential point height is set as E7 or U3 to U6 when there is or isn't pre-machining in the same unit, respectively. { 0: The clearance in plane direction is set always as U10. { 1: The clearance in plane direction is set as E5 or U10 when there is or isn't pre-machining in the same unit, respectively. { 1: Rapid feed up to the intended surface + U3 to U6 </p>	
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

PARAMETER (USER, LINE)


Address	Meaning	Description								
<p>E95</p> <p>Tool-path pattern selection for line-machining unit</p>		<div style="text-align: center;"> <table border="1" style="margin: auto;"> <tr> <td style="padding: 2px;">7</td><td style="padding: 2px;">6</td><td style="padding: 2px;">5</td><td style="padding: 2px;">4</td><td style="padding: 2px;">3</td><td style="padding: 2px;">2</td><td style="padding: 2px;">1</td><td style="padding: 2px;">0</td> </tr> </table> </div> <p>↑↑↑↑↑↑↑↑</p> <ul style="list-style-type: none"> For the 2nd and subsequent rounds of cutting: <ul style="list-style-type: none"> 0: Not via the approach point 1: Via the approach point For the 2nd and subsequent rounds of cutting: <ul style="list-style-type: none"> 0: Escape to the axis initial point 1: No escape on the axis 1: Rapid feed up to the intended surface + U3 to U6 1: Escape is set to a point where the tool comes out of the removal allowance. The referential point height for central, right hand, left hand, outside and inside linear machining is: <ul style="list-style-type: none"> 0: Set always as U3 to U6 1: Set as E7 or U3 to U6 when there is or isn't pre-machining in the same unit, respectively. The plane direction clearance for outside and inside linear machining is: <ul style="list-style-type: none"> 0: Set always as U10 1: Set as E5 or U10 when there is or isn't pre-machining in the same unit, respectively. <p>- Bit 2</p>  <p style="text-align: right;">MPL501</p> <p>- Bit 3</p>  <p style="text-align: right;">MPL502</p> <p>- Bit 5</p>  <p style="text-align: right;">MPL503</p> <p>Note: Bit 3 valid only for inside/outside linear machining unit.</p>	7	6	5	4	3	2	1	0
	7	6	5	4	3	2	1	0		
	Unit	—								
	Effective condition	Instant								
Applicable program	M									

Title of display		PARAMETER (USER, LINE)	
Address	Meaning		Description
E96	Tool-path pattern selection for end milling-slot unit		<p> 0: The referential point height is set always as U3 to U6. 1: The referential point height is set as E7 or U3 to U6 when there is or isn't pre-machining in the same unit, respectively. For the 2nd and subsequent rounds of cutting: 0: Not via the approach point 1: Via the approach point 1: Rapid feed up to the intended surface + U3 to U6 </p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
E97	Tool-path pattern selection for end milling-top unit		<p> 0: The referential point height is set always as U3 to U6 1: The referential point height is set as E7 or U3 to U6 when there is or isn't pre-machining in the same unit, respectively. 1: Rapid feed up to the intended surface + U3 to U6 </p>
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	

3-7 PARAMETER (MACHINE, CONTROL A)

MACHINE PARAMETER of control axis A group



Data related to the axes is to be set in MACHINE parameter adresse A.




Title of display		PARAMETER (MACHINE, CONTROL)	
Address	Meaning		Description
A1	Maximum rapid traverse speed		<p>Traverse speed for each axis is set. For positioning (straight line positioning) by use of interpolation, positioning feed speed must be the maximum value within the limit data set for this parameter in any axis.</p> <p>Example:</p>  <p style="text-align: right;">NM211-00301</p> <p>Feed speed for each axis will be determined according to vector from start point to end point. Fx or Fz will be corresponding to data set for this parameter, and remaining will be determined according to vector quantity.</p>
	Unit	mm/min (0.1 inches/min) or deg/min	
	Effective condition	Instant	
	Applicable program	M, E	
A2	Clamping value for the cutting feedrate during tool tip point control		<p>Set the maximum feedrate for the cutting feedrate during tool tip point control.</p> <p>- If the setting of this parameter is "0", the program will operate with parameter A1.</p>
	Unit	mm/min (0.1 inches/min) or deg/min	
	Effective condition	Instant	
	Applicable program	M, E	
A3	Origin return speed		<p>Rapid traverse in manual mode (origin return mode, rapid traverse mode) will be made at speed set for this parameter.</p>
	Unit	mm/min (0.1 inches/min) or deg/min	
	Effective condition	Instant	
	Applicable program	M, E	

3 PARAMETER



Title of display		PARAMETER (MACHINE, CONTROL)	
Address	Meaning		Description
A4	Cutting feedrate clamp value Thread chamfering feedrate		Setting of maximum C axis feedrate in milling line machining unit (LCT, RGT, LFT) and polar coordinate interpolation mode (G12.1) in EIA/ISO programs. Set the chamfering feedrate for the threading cycle. If 0 is set here, the machine will operate at one-fourth of the setting of parameter A1 .
	Unit	mm/min (0.1 inches/min) or deg/min	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display **PARAMETER (MACHINE, CONTROL)**



Address	Meaning	Description
A5	Fixed point return position or second reference point return position	<p>(1) X-axis (diametral value), Z-axis Specifying fixed point position. Coordinates are determined on the machine coordinate system based on the origin points as reference.</p> <div style="text-align: center;">  </div> <p style="text-align: right;">NM211-00302</p> <p>(2) C-axis Specifying fixed point position Coordinates are based on the deviation angle from the C-axis machine origin point.</p> <div style="text-align: center;">  </div> <p style="text-align: right;">NM211-00303</p>
	Unit	0.001 mm (0.0001 inches) or 0.001 deg
	Effective condition	Instant
	Applicable program	M, E

Title of display		PARAMETER (MACHINE, CONTROL)		
Address	Meaning	Description		
A6	Tool tip measurement tool change position or third reference point return position in X-axis (diametral value), Z-axis Setting tool tip measurement tool change position on the machine coordinate system	<p>Setting tool tip measurement tool change position on the machine coordinate system</p>  <p style="text-align: right;">NM211-00304</p>		
	Unit			0.001 mm or 0.0001 inches
	Effective condition			Instant
	Applicable program			M, E
A7	Workpiece origin (fixed point) coordinate or fourth reference point return position	<p>Setting workpiece origin point position with respect to machine origin point on the machine coordinate system</p>  <p style="text-align: right;">NM211-00305</p> <p>(This parameter determines workpiece origin point upon power on. This can be changed by G50 command.)</p>		
	Unit			0.001 mm or 0.0001 inches
	Effective condition			Instant
	Applicable program			E
A8	Machine reference position	<p>Setting reference workpiece origin point position with respect to machine origin point</p>  <p style="text-align: right;">NM211-00306</p>		
	Unit			0.001 mm or 0.0001 inches
	Effective condition			Instant
	Applicable program			M, E



Title of display **PARAMETER (MACHINE, CONTROL)**

Address	Meaning		Description
A9	Soft limit upper end		Setting movable range of each axis in (-) and (+) directions from machine origin point 
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
A10	Soft limit lower end		NM211-00307 - If the upper-limit value (A9) and lower-limit value (A10) for the axis are 0 or the same, the soft-limits for that axis are invalid. - Specify the required data to make the illegal axis area upper limit (A29)/lower limit (A30) valid.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
A11	Single direction positioning shift distance		Setting of shift distance in single direction positioning 
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
A12	Handle interruption clamp data		Maximum data for handle interruption is set. Diametral value is used for X-axis.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	


3 PARAMETER

Title of display		PARAMETER (MACHINE, CONTROL)	
Address	Meaning		Description
A13	Origin point dog shift distance		Setting shift distance of origin point dog  Diametral value is used for X-axis.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
A14	Machine position shift distance		Setting shift distance of machine position  Diametral value is used for X-axis.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
A15	Floating reference point		Set the machine coordinates of floating reference point. Example: G30.1 X10. Z10.; With this command, the tool moves past a middle point of X10. Z10 and then moves at rapid feedrate to the floating reference point that has been set in this parameter.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	E	

Title of display **PARAMETER (MACHINE, CONTROL)**

Address	Meaning	Description
A16	Amount of watchdog-less origin shift	<p>Shift the specified watchdog-less origin through the specified distance.</p> <p><If the axis is not yet returned to its home position></p>  <p><If the axis is already returned to its home position></p> 
	Unit	0.001 mm/0.0001 inch/ 0.001 deg
	Effective condition	Instant
	Applicable program	M, E
A17	Feed-forward gain	Specify the pre-interpolation acceleration/deceleration feed-forward gain levels for each axis.
	Unit	%
	Effective condition	Instant
	Applicable program	M, E
A18 (bit 0)	Selection of a linear-type rotational axis	<p>Select whether the rotational axis is of the linear type or the rotational type(this selection is to be made for each axis.)</p> <p>A18 (bit 0) = 0 : Rotational type A18 (bit 0) = 1 : Linear type</p>
	Unit	—
	Effective condition	Power OFF → ON
	Applicable program	M, E

Title of display		PARAMETER (MACHINE, CONTROL)
Address	Meaning	Description
A18 (bit 1)	Selection as to how to determine the rotational direction of the rotational axis	Select how to determine the rotational direction of the rotational axis. A18 (bit 1) = 0 Rotation based on program-specified codes A18 (bit 1) = 1 Shortcut rotation
	Unit	—
	Effective condition	Power OFF → ON
	Applicable program	M, E
A25 A26	Upper/lower limit setting as stored stroke limits II	Set the upper and lower limits as stored stroke limits II. A25: Upper limit A26: Lower limit
	Unit	0.001 mm or 0.0001 inches
	Effective condition	After traveling stop
	Applicable program	M, E
A27	Rear-turret machine coordinate origin (Dual-turret specs. only)	Set the machine coordinate origin for the rear turret.
	Unit	0.001 mm or 0.0001 inches
	Effective condition	After traveling stop
	Applicable program	M, E



PARAMETER (MACHINE, CONTROL)


Title of display		PARAMETER (MACHINE, CONTROL)	
Address	Meaning		Description
A29	Illegal axis area upper limits (Type A)		<p>The diagram shows a coordinate system with X and Yt axes. The origin is labeled (X,Yt) = (0,0). The X-axis has an upper limit A29(X) and a lower limit A30(X). The Yt-axis has an upper limit A29(Yt) and a lower limit A30(Yt). Soft limits are also shown: A9(Yt) for the Yt-axis upper soft-limit and A10(Yt) for the Yt-axis lower soft-limit. Shaded areas (A) and (A') represent illegal axis areas. Area (A) is bounded by A9(X), A29(Yt), and A30(X). Area (A') is bounded by A10(Yt), A30(X), and A9(X). Interference areas are also indicated.</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
A30	Illegal axis area lower limits (Type A)		<p>Upper: Shaded area (A) in the above diagram, determined by parameters A9 (X), A9 (Yt), A29 (X), and A29 (Yt), is referred to as the illegal axis area. An alarm will result if an attempt is made to move the machine into the area.</p> <p>Lower: Shaded area (A') in the above diagram, determined by parameters A10 (X), A10 (Yt), A30 (X), and A30 (Yt), is referred to as the illegal axis area. An alarm will result if an attempt is made to move the machine into the area.</p> <ul style="list-style-type: none"> - Parameters A29 and A30 are valid only for the X-axis and the Yt-axis. - If the X-axis and Yt-axis upper limits (A29) and lower limits (A30) are all zeros, the illegal axis area check function is invalid.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
A29	Illegal axis area upper limits (Type B)		<p>The diagram shows a coordinate system with X and Yt axes. The origin is labeled (X,Yt) = (0,0). The X-axis has an upper soft-limit A9(X) and a lower limit A30(X). The Yt-axis has an upper limit A29(Yt) and a lower soft-limit A10(Yt). Shaded areas (A) and (A') represent illegal axis areas. Area (A) is bounded by A9(X), A29(Yt), and A30(X). Area (A') is bounded by A10(Yt), A30(X), and A9(X). Interference areas are also indicated.</p>
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
A30	Illegal axis area lower limits (Type B)		<p>Upper: Shaded area (A) in the above diagram, determined by parameters A9 (X), A10 (Yt), A29 (X), and A29 (Yt), is referred to as the illegal axis area. An alarm will result if an attempt is made to move the machine into the area.</p> <p>Lower: Shaded area (A') in the above diagram, determined by parameters A10 (X), A9 (Yt), A30 (X), and A30 (Yt), is referred to as the illegal axis area. An alarm will result if an attempt is made to move the machine into the area.</p> <ul style="list-style-type: none"> - Parameters A29 and A30 are valid only for the X-axis and the Yt-axis. - If the X-axis and Yt-axis upper limits (A29) and lower limits (A30) are all zeros, the illegal axis area check function is invalid.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (MACHINE, CONTROL)		
Address	Meaning	Description		
A29	Illegal axis area upper limits (Type C) (Stored Stroke Limit III, upper limit)			
	Unit	0.001 mm or 0.0001 inches		
	Effective condition	Instant		
	Applicable program	M, E		
A30	Illegal axis area lower limits (Type C) (Stored Stroke Limit III, lower limit)		<p>Fixed (0)</p>	
	Unit	0.001 mm or 0.0001 inches		
	Effective condition	Instant		
	Applicable program	M, E		
A31	—		<p>Enter in terms of diameter the X-axial distance from the center of the B-axis to that of the C-axis at the time of arrival at the home position.</p>	
	Unit	—		
	Effective condition	Instant		
	Applicable program	E		
A32	X-axial distance from the center of the B-axis to that of the C-axis at the time of arrival at the home position		<p>Machine zero point</p> <p>B-axis rotational center</p> <p>Workpiece reference point</p> <p>C-axis rotational center</p> <p>A32 (X)</p>	
	Unit	—		
	Effective condition	Instant		
	Applicable program	E		

3-8 PARAMETER (MACHINE, MACHINE B)













MACHINE PARAMETER of Machine B group


- The Machine Parameter is found within each head or turret.
- The display of the Machine Parameter is changed by HEAD SELECT key or TURRET SELECT key on the operation panel. In case of there is no description of “no setting for No.2 spindle head”, it is necessary to set for both of No. 1 and No. 2 spindle heads.




Title of display		PARAMETER (MACHINE, MACHINE)		
Address	Meaning		Description	
B1 B3 B5 B7 B9	Tool head No. B1 - #1 B3 - #2 B5 - #3 B7 - #4 B9 - #5		Tool Nos. are assigned machine by machine. Example: If tool Nos. are assigned as below: 	
	Unit	—		
	Effective condition	Instant		
	Applicable program	M, E		
B2 B4 B6 B8 B10	Number of tools B2 - #1 B4 - #2 B6 - #3 B8 - #4 B10 - #5		Data are set by procedure as below. B1 = 1 (First tool No. of outside diameter tool) B2 = 10 (Number of outside diameter tools) B3 = 21 (First tool No. of inside diameter tool) B4 = 5 (Number of inside diameter tools)	
	Unit	—		
	Effective condition	Instant		
	Applicable program	M, E		





Title of display		PARAMETER (MACHINE, MACHINE)																							
Address	Meaning		Description																						
B11	Number of turret pockets		Number of turret pockets for tool mounting is set.																						
	Unit	—																							
	Effective condition	Instant																							
	Applicable program	M, E																							
B14	Selection of reference tool in updating data method during automatic nose measurement (for EIA)		See the description of P14 (bit 7).																						
	Unit	—																							
	Effective condition	Instant																							
	Applicable program	E																							
B15	Reference tool number		Designate a reference tool to be used for nose measurement. If a tool is not designated here, the amount of reference tool wear compensation will be "0" in the calculation of compensation data. <For normal nose measurement> $a = \text{Target value} - \text{Measured value}$ $a \geq 0 \text{ Compensation} = a - \text{Reference tool wear compensation}$ $a < 0 \text{ Compensation} = a + \text{Reference tool wear compensation}$ <For a reference tool> $\text{Compensation} = \text{Target value} - \text{Measured value}$ Set a suffix as follows: <table border="1" data-bbox="778 1518 1406 1599"> <thead> <tr> <th>Suffix</th> <th>None</th> <th>A</th> <th>B</th> <th>C</th> <th>D</th> <th>E</th> <th>F</th> <th>G</th> <th>H</th> <th>V</th> </tr> </thead> <tbody> <tr> <td>B16 setting</td> <td>0</td> <td>1</td> <td>2</td> <td>3</td> <td>4</td> <td>5</td> <td>6</td> <td>7</td> <td>8</td> <td>9</td> </tr> </tbody> </table>	Suffix	None	A	B	C	D	E	F	G	H	V	B16 setting	0	1	2	3	4	5	6	7	8	9
	Suffix	None		A	B	C	D	E	F	G	H	V													
	B16 setting	0		1	2	3	4	5	6	7	8	9													
	Unit	—																							
Effective condition	Instant																								
Applicable program	M, E																								
B16	Reference tool suffix																								
	Unit	—																							
	Effective condition	Instant																							
	Applicable program	M, E																							





Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B17	Direction of N° orientation indexing		Select the direction of indexing for N° orientation. B17 = 0: Shortcut (other than 1 and 2 below) B17 = 1: Forward B17 = 2: Backward
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
B18	Number of pins to be driven for N° orientation		Set the number of pins to be driven for N° orientation of a machine having an orientation capability.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (MACHINE, MACHINE)			
Address	Meaning	Description			
B19	Angular direction of spindle orientation	Set the angular direction of orientation of the spindle 1.			
					
		When viewed from the direction of the arrow			
		<table border="1"> <thead> <tr> <th>B19 = 0</th> <th>B19 ≠ 0</th> </tr> </thead> <tbody> <tr> <td>  </td> <td>  </td> </tr> </tbody> </table>		B19 = 0	B19 ≠ 0
B19 = 0	B19 ≠ 0				
					
Set the angular direction of orientation of the spindle on headstock 2.					
					
When viewed from the direction of the arrow					
<table border="1"> <thead> <tr> <th>B19 = 0</th> <th>B19 ≠ 0</th> </tr> </thead> <tbody> <tr> <td>  </td> <td>  </td> </tr> </tbody> </table>		B19 = 0	B19 ≠ 0		
B19 = 0	B19 ≠ 0				
					
Unit	—				
Effective condition	Power OFF → ON				
Applicable program	M, E				




Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B29	Selecting Type A/Type B of illegal axis area limits		Type A or Type B of illegal axis area limits defined with parameters A9 , A10 , A29 and A30 is selected. B29 = 0: Type A of illegal axis area limits is selected. B29 = 1: Type B of illegal axis area limits is selected. Note: The illegal axis area check function is only valid when 0 or 1 is set in the parameter B29 .
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
B31	Name of the fourth axis		Set the name of the axis. To display the axis name only at "POSITION", set the decimal number corresponding to the ASCII code for the axis name which is to be displayed. Example: To display the axis name as 'W', enter 87 since a hexadecimal ASCII code of 'W' = 0x57 is equivalent to a decimal number of 87. To display the axis name at both "POSITION" and "MACHINE", set the minus decimal number corresponding to the ASCII code for the axis name which is to be displayed. Example: To display the axis name as 'W', enter -87 since a hexadecimal ASCII code of 'W' = 0x57 is equivalent to a decimal number of 87.
	Unit	ASCII by decimal digit	
	Effective condition	Instant	
	Applicable program	M, E	
B32	Name of the fifth axis		
	Unit	ASCII by decimal digit	
	Effective condition	Instant	
	Applicable program	M, E	
B33	Chuck outside diameter (for chuck barrier)		Setting of chuck outside diameter  NM211-00312 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	





Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B34	Chuck width (for chuck barrier)		Setting of chuck width  NM211-00313 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B35	Chuck inside diameter (for chuck barrier)		Setting of chuck inside diameter  NM211-00314 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B37	Tail body outside diameter (for tail barrier)		Setting of tail body outside diameter  NM211-00315 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B38	Tail body length (for tail barrier)		Setting of tail body length  NM211-00316 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B39	Tail spindle outside diameter (for tail barrier)		Setting of tail spindle outside diameter  NM211-00317 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B40	Length with tail spindle at back end (for tail barrier)		Setting of length with tail spindle at back end  NM211-00318 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B41	Tail head outside diameter (for tail barrier)		Setting of tail head outside diameter  NM211-00319 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B42	Tail head length (for tail barrier)		Setting of tail head length  NM211-00320 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	


Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B43	Tail head taper angle (for tail barrier)		Setting of tail head taper angle  NM211-00321
	Unit	0.001 deg	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B44	Tail head biting diameter (for tail barrier)		Setting of biting diameter when tail head is used  Workpiece origin point NM211-00322 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B45	Turret radius		Setting of turret radius  Reference point of turret (center) Turret B45 NM211-00323 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B46	Turret width		Setting of turret width  Turret B45 NM211-00324 *: The setting unit when the EIA decimal digit adding function is valid
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	





Title of display **PARAMETER (MACHINE, MACHINE)**

Address	Meaning	Description	
B47	Turret reference position in X-axis direction	<p>Turret position when X-axis is returned to machine origin point is set by diametral value.</p>  <p style="text-align: right;">Reference workpiece origin point NM211-00325</p> <p>*: The setting unit when the EIA decimal digit adding function is valid</p>	
	Unit		0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition		Power OFF → ON
	Applicable program		M, E
B48	Turret reference position in Z-axis direction	<p>Turret position when Z-axis is returned to machine origin point is set.</p>  <p style="text-align: center;">Spindle edge NM211-00326</p> <p>*: The setting unit when the EIA decimal digit adding function is valid</p> <p>Note: The display value of B48 at the No. 2 spindle side is the same as that of B72 at the No. 1 spindle side. Do not change the value of B48 at the No. 2 spindle side, except for the MULTIPLEX or DUAL TURN specifications.</p>	
	Unit		0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition		Power OFF → ON
	Applicable program		M, E
B49 B52 B55 B58	Tool holder mounting position B49 - Type 1 B52 - Type 2 B55 - Type 3 B58 - Type 4	<p>Setting of tool holder mounting position. When plus data is used, the tool holder is mounted horizontally, and minus data downward.</p> <p>Example: Type 1</p>  <p style="text-align: right;">NM211-00327</p> <p>Same for types 2, 3, 4</p>	
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M



Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B50 B53 B56 B59	Tool holder width in X-axis direction B50 - Type 1 B53 - Type 2 B56 - Type 3 B59 - Type 4		Setting tool holder width in X-axis direction Example: Type 1  NM211-00328
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
			Same for types 2, 3, 4
B51 B54 B57 B60	Tool holder width in Z-axis direction B51 - Type 1 B54 - Type 2 B57 - Type 3 B60 - Type 4		Setting of tool holder width in Z-axis direction Example: Type 1  NM211-00329
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
			Same for types 2, 3, 4
B61	Tool nose measurement sensor width in X-axis direction		Tool nose measurement sensor dimensions are set. Example 1: RENISHAW touch sensor  NM211-00330
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
B62	Tool nose measurement sensor width in Z-axis direction		Example 2: MT pulsar  NM211-00331
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	

PARAMETER (MACHINE, MACHINE)

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B63	Tool nose measurement sensor mounting position, X-axis (diametral value)		Setting of sensor reference point coordinates The Z coordinate on the machine coordinate system and the X coordinate on the reference workpiece coordinate system are set for parameter B64 and B63 respectively. Tool nose measurement sensor reference point is positioned as shown below. Example: No. 1 spindle head side 
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
B64	Tool nose measurement sensor mounting position, Z-axis		Note: The tool nose measurement sensor reference point for No. 2 spindle head must be positioned above left of the sensor.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
B66	Workpiece measurement sensor diameter compensation data for outside diameter measurement and projection width measurement		Values set for these parameters are used to calculate measurement data. Outside diameter measurement $Ax = \left \frac{\#1 - \#2}{2} \right - 2R + \mathbf{B66}$ Projection width measurement $Az = \left \#1 - \#2 \right - 2R + \mathbf{B66}$ Inside diameter measurement $Ax = \left \frac{\#1 - \#2}{2} \right + 2R + \mathbf{B67}$ Groove width measurement $Az = \left \#1 - \#2 \right + 2R + \mathbf{B67}$
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
B67	Workpiece measurement sensor diameter compensation data for inside diameter measurement and groove width measurement		$Ax/Az : \text{Measurement data}$ $\#1/\#2 : \text{Sensor ON position}$ $R : \text{Touch sensor nose R}$ Notes: 1. When the parameter B66 is not set (or set to 0), the value of parameter B235 is used for projection width measurement (WID OUT and WID IN). 2. When the parameter B67 is not set (or set to 0), the value of parameter B236 is used for groove width measurement (GRV OUT and GRV IN).
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	


Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B68	Position of separating plate		The position of separating plate viewed from spindle nose is specified. No. 1 spindle side No. 2 spindle side 
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
B69	Chuck outside diameter of No. 2 spindle (for chuck barrier)		Setting of chuck outside diameter of No. 2 spindle  NM211-00312 Note: For MULTIPLEX and DUAL TURN specs., the same value as B33 for the No. 2 spindle is displayed. Do not change this setting value.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B70	Chuck width of No. 2 spindle (for chuck barrier)		Setting of chuck width of No. 2 spindle  NM211-00313 Note: For MULTIPLEX and DUAL TURN specs., the same value as B34 for the No. 2 spindle is displayed. Do not change this setting value.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B71	Chuck inside diameter of No. 2 spindle (for chuck barrier)		Setting of chuck inside diameter of No. 2 spindle  NM211-00314 Note: For MULTIPLEX and DUAL TURN specs., the same value as B35 for the No. 2 spindle is displayed. Do not change this setting value.
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	

Title of display **PARAMETER (MACHINE, MACHINE)**

Address	Meaning	Description
B72	Z-coordinate of tool post reference position with respect to No. 2 spindle edge	Setting of position when Z-axis is returned to machine origin point. <div style="text-align: center;">  <p style="text-align: right; margin-right: 20px;">NM211-00326</p> </div> <p>Note: The display value of B72 at the No. 1 spindle side is the same as that of B48 at the No. 2 spindle side. Do not change the value of B72 at the No. 1 spindle side, except for the MULTIPLEX or DUAL TURN specifications.</p>
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Power OFF → ON
	Applicable program	M, E
B73	X-coordinate of tool path start point on the TOOL PATH CHECK display	The start point of a tool path drawn on the TOOL PATH CHECK display is set by a coordinate value of machine coordinate system. <div style="text-align: center;">  <p style="text-align: right; margin-right: 20px;">NM211-00334</p> </div> <p>A: Tool path start point</p>
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	M, E
B74	Z-coordinate of tool path start point on the TOOL PATH CHECK display	Refer to B73 .
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	M, E





PARAMETER (MACHINE, MACHINE)

Address	Meaning	Description																					
B75 B76 B77	Spindle limit speed selection for spindle position control time constants B75 - Limit speed 1 B76 - Limit speed 2 B77 - Limit speed 3																						
	Unit	Revolution																					
	Effective condition	Power OFF → ON																					
	Applicable program	M, E																					
B78 B79 B80	Spindle position control time constants B78 - Time constant 1 B79 - Time constant 2 B80 - Time constant 3																						
	Unit	0.001 sec																					
	Effective condition	Power OFF → ON																					
	Applicable program	M, E																					
B81	EIA barrier activation																						
	Set the types of tailstock, tool holder and chuck for which the EIA barriers are to be activated.																						
	<table style="width: 100%; border: none;"> <tr> <td style="width: 60%;">Tailstock.....</td> <td style="width: 30%;">Off/On</td> <td style="width: 10%; text-align: right;">0/1</td> </tr> <tr> <td></td> <td>(see Note 1 below)</td> <td></td> </tr> <tr> <td>Tool holder.....</td> <td>Unset/Set</td> <td style="text-align: right;">0/2</td> </tr> <tr> <td>Main chuck.....</td> <td>Outer/Inner Jaw</td> <td style="text-align: right;">0/4</td> </tr> <tr> <td>Sub-chuck.....</td> <td>Outer/Inner Jaw</td> <td style="text-align: right;">0/8</td> </tr> <tr> <td>G22/G23.....</td> <td>Inside/Outside</td> <td style="text-align: right;">0/64</td> </tr> <tr> <td></td> <td>(see Note 2 below)</td> <td></td> </tr> </table>		Tailstock.....	Off/On	0/1		(see Note 1 below)		Tool holder.....	Unset/Set	0/2	Main chuck.....	Outer/Inner Jaw	0/4	Sub-chuck.....	Outer/Inner Jaw	0/8	G22/G23.....	Inside/Outside	0/64		(see Note 2 below)	
	Tailstock.....	Off/On	0/1																				
	(see Note 1 below)																						
Tool holder.....	Unset/Set	0/2																					
Main chuck.....	Outer/Inner Jaw	0/4																					
Sub-chuck.....	Outer/Inner Jaw	0/8																					
G22/G23.....	Inside/Outside	0/64																					
	(see Note 2 below)																						
For example, if Tailstock Off, Tool holder Set, Main chuck Inner jaw, and Sub-chuck Inner jaw are to be specified, then set 14 in B81 since the total value becomes (0+2+4+8=14).																							
Notes: 1. "Tailstock off" does not mean cancelling the tail barriers; it means that the tail will move away prior to machining. 2. Refer to the EIA/ISO Programming Manual for further details of G22/G23.																							
Unit	—																						
Effective condition	Instant																						
Applicable program	E																						




Title of display		PARAMETER (MACHINE, MACHINE)																						
Address	Meaning		Description																					
B82	M-code for spindle forward rotation during a fixed hole-drilling cycle		Set the M-code to be used to rotate the spindle in its forward direction during a fixed hole-drilling cycle. If 0 is set here, the M-code will be regarded as M03.																					
	Unit	—																						
	Effective condition	Power OFF → ON																						
	Applicable program	E																						
B83	M-code for spindle reverse rotation during a fixed hole-drilling cycle		Set the M-code to be used to rotate the spindle in its reverse direction during a fixed hole-drilling cycle. If 0 is set here, the M-code will be regarded as M04.																					
	Unit	—																						
	Effective condition	Power OFF → ON																						
	Applicable program	E																						
B84	Whether to activate T-command pre-reading, whether to display tailstock information, whether to activate stand-by M code pre-reading, whether to pre-read the block immediately succeeding the M00/M01 code, whether to make bar feeder schedule function valid/invalid, whether to make the NC powered tailstock valid, and selection of whether to display tail thrust in pounds (lbs)		Select whether T-command pre-reading is to be made valid and whether tailstock-related information is to be displayed on the SET UP display. <table border="0" style="width: 100%; margin-top: 10px;"> <tr> <td>T-command pre-reading</td> <td style="text-align: right;">Yes/No</td> <td style="text-align: right;">0/1</td> </tr> <tr> <td>Display of tailstock information</td> <td style="text-align: right;">No/Yes</td> <td style="text-align: right;">0/2</td> </tr> <tr> <td>Stand-by M code pre-reading</td> <td style="text-align: right;">No/Yes</td> <td style="text-align: right;">0/4</td> </tr> <tr> <td>Pre-reading the block immediately succeeding the M00/M01 code</td> <td style="text-align: right;">Yes/No</td> <td style="text-align: right;">0/8</td> </tr> <tr> <td>Bar feeder schedule function</td> <td style="text-align: right;">Invalid/Valid</td> <td style="text-align: right;">0/16</td> </tr> <tr> <td>NC powered tailstock function</td> <td style="text-align: right;">Invalid/Valid</td> <td style="text-align: right;">0/32</td> </tr> <tr> <td>Display of tail thrust also in pounds (lbs)</td> <td style="text-align: right;">No/Yes</td> <td style="text-align: right;">0/64</td> </tr> </table> <p>Example: If T-command pre-reading is not required and tailstock information is to be displayed, set 3 since the total value becomes (1 + 2 = 3).</p> <p>Notes:</p> <ol style="list-style-type: none"> 1. If the machine has ATC, set the value 1 for T-command pre-reading. 2. To make the NC powered tailstock function valid, also make the display of tailstock information valid. 	T-command pre-reading	Yes/No	0/1	Display of tailstock information	No/Yes	0/2	Stand-by M code pre-reading	No/Yes	0/4	Pre-reading the block immediately succeeding the M00/M01 code	Yes/No	0/8	Bar feeder schedule function	Invalid/Valid	0/16	NC powered tailstock function	Invalid/Valid	0/32	Display of tail thrust also in pounds (lbs)	No/Yes	0/64
	T-command pre-reading	Yes/No		0/1																				
	Display of tailstock information	No/Yes		0/2																				
	Stand-by M code pre-reading	No/Yes		0/4																				
Pre-reading the block immediately succeeding the M00/M01 code	Yes/No	0/8																						
Bar feeder schedule function	Invalid/Valid	0/16																						
NC powered tailstock function	Invalid/Valid	0/32																						
Display of tail thrust also in pounds (lbs)	No/Yes	0/64																						
Unit	—																							
Effective condition	Power OFF → ON																							
Applicable program	M, E																							


PARAMETER (MACHINE, MACHINE)

Address	Meaning	Description	
B85	Selection of the feed unit at block connections	Select this function if luster of about 1 mm (0.04 in.) luster on the as-cut surface becomes a problem at block connections, for example, for a linear-to-arc pattern change. B85 (bit 0) = 0 Under linear-to-arc cutting conditions (with no changes in speed), linear-to-linear cutting conditions (with changes in speed), and linear-to-arc cutting conditions (with changes in speed), the cutting speed may fluctuate in the linear blocks. B85 (bit 0) = 1 (no speed fluctuations in linear blocks) Under linear-to-arc cutting conditions (with no changes in speed), linear-to-linear cutting conditions (with changes in speed), and linear-to-arc cutting conditions (with changes in speed), the cutting speed does not fluctuate in the linear blocks. B85 bit 0 = 0  Luster may change in this section. B85 bit 0 = 1 	
		Unit	—
		Effective condition	Instant
		Applicable program	M, E
B86	Holder angle of angle tool holder	Set the holder angle of the angle tool holder. According to the value set in this parameter, the holder angle is set in HLD.TYPE on the TOOL DATA display. B86 = 45  HLD.TYPE: 45 (B86 = 45)  HLD.TYPE: 45 (180 - B86 = 135)	
		Unit	Degree
		Effective condition	Instant
		Applicable program	M, E

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B89	Selection of the solid-mode threading tool nose position		Specify the solid-mode threading tool nose position. P89 (bit 0) = 0 (Conventional method) The sharp section of the threading tool is recognized as its nose. P89 (bit 0) = 1 The tool-setting point is recognized as the tool nose.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M	
B107	Angle of pre-interpolation corner deceleration		Specify the angle of deceleration at corners. If 0 is entered, the angle will be handled as 5 degrees. If a value exceeding 90 degrees is entered, the angle will be handled as 30 degrees.
	Unit	Degree	
	Effective condition	Instant	
	Applicable program	M, E	
B108	Reference axis for polygonal machining		Specify the axis number of the spindle (workpiece axis) to be used as a reference axis for polygonal machining.
	Unit	Number of controlled axis	
	Effective condition	Power OFF → ON	
	Applicable program	E	
B109	Spindle number for milling-spindle synchronous tapping		Set the identification number of the spindle for milling-spindle synchronous tapping. B109 = 7 For spindle rotary switch 2 B109 = 0 For spindle rotary switch 6
	Unit	Number of controlled axis	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B110	Axis control flag for a machine having a high-speed turret		Set the axis control flag for a machine having both a high-speed turret and No. 2 spindle. B110 = 1 For machine having both a high-speed turret and No. 2 spindle B110 = 0 For other machines
	Unit	—	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B112	S-shaped acceleration/deceleration filtering		Specify the length for S-shaped acceleration/deceleration filtering of the shape correction function. 0: No filtering 1: 14.2 msec 2: 28.4 msec 4: 56.8 msec 8: 113.6 msec Note: If a value other than the above is entered, the filtering length will be regarded as 14.2 msec.
	Unit	—	
	Effective condition	Instant	
	Applicable program	M, E	
B145	Dwell time during the C-axis unclamping mode in a fixed hole-drilling cycle		Set the dwell time to be secured during the C-axis unclamping mode in a fixed hole-drilling cycle.
	Unit	msec	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B146	Pre-interpolation acceleration/deceleration: Time constant		Set the time constant as the time up to the arrival of the target pre-interpolation acceleration/deceleration speed specified in parameter B233 . 
	Unit	msec	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B147	Maximum cutting speed in shape correction mode		Set the maximum cutting speed in shape correction mode.
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M, E	
B148	Feedrate during measurement for automatic tool offsetting		Set the feedrate during measurement for automatic tool offsetting.
	Unit	mm/min	
	Effective condition	Instant	
	Applicable program	E	
B149 B150 B151	Rapid feed overriding data		Set the rapid feed overriding data: 100% ↓ ↑ 50% ↓ ↑ B149% ↓ ↑ B150% ↓ ↑ B151%
	Unit	%	
	Effective condition	Instant	
	Applicable program	M, E	
B152	Minimum index angle of the FLASH-tool		This parameter is used as the basis for judging whether the index angle entered in TOOL DATA display is acceptable. An alarm will be displayed if the entered value is judged to be unacceptable. (Specify "900" for 4-segment splitting.)
	Unit	0.1 degree	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B153 to B160	Maximum spindle speeds for each gear position during a synchronous tapping cycle		<p>Specify the maximum spindle speeds for each gear position during a synchronous tapping cycle.</p> <p>The following diagram represents the relationship to each synchronous tapping time constants:</p>  <p>B153: Maximum spindle speeds setting for each gear position [1] B154: Maximum spindle speeds setting for each gear position [2] B155: Maximum spindle speeds setting for each gear position [3] B156: Maximum spindle speeds setting for each gear position [4] B157: Maximum spindle speeds setting for each gear position [5] B158: Maximum spindle speeds setting for each gear position [6] B159: Maximum spindle speeds setting for each gear position [7] B160: Maximum spindle speeds setting for each gear position [8]</p>
	Unit	min ⁻¹ (rpm)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B161 to B168	Critical spindle speeds for each gear position during a synchronous tapping cycle		<p>Specify the critical spindle speeds for each gear position during a synchronous tapping cycle.</p> <p>B161: Critical spindle speeds setting for each gear position [1] B162: Critical spindle speeds setting for each gear position [2] B163: Critical spindle speeds setting for each gear position [3] B164: Critical spindle speeds setting for each gear position [4] B165: Critical spindle speeds setting for each gear position [5] B166: Critical spindle speeds setting for each gear position [6] B167: Critical spindle speeds setting for each gear position [7] B168: Critical spindle speeds setting for each gear position [8]</p>
	Unit	min ⁻¹ (rpm)	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B169	Maximum permissible speed of the rotational axis for polygonal/hobbing machining		<p>If the rotational speed of the tool rotational axis during polygonal machining exceeds the setting of this parameter, that rotational speed will be clamped at this setting.</p> <p>Also, if the rotational speed of the milling axis during hobbing exceeds the setting of this parameter, that rotational speed will be clamped at this setting.</p>
	Unit	min ⁻¹ (rpm)	
	Effective condition	Power OFF → ON	
	Applicable program	E	


Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B170	Acceleration/deceleration time constant for synchronous tapping		Set the acceleration/deceleration time constant for synchronous tapping. If 0 is set, the program will operate at a default of 1500 msec.
	Unit	msec	
	Effective condition	Power OFF → ON	
	Applicable program	M, E	
B171	Spindle 1/4h (1/2h) rated torque for L coils for auto-pecking of the cutting load detection type		Set the 1/4h (1/2h) rated torque for the L coils of the spindle motor. Note: Only the 1/2h rated torque, not the 1/4h rated torque, may be known for the particular motor. If that is the case, set the 1/2h rated torque.
	Unit	0.1 N·m	
	Effective condition	Instant	
	Applicable program	M	
B172	Spindle 1/4h (1/2h) rated torque for H coils for auto-pecking of the cutting load detection type		Set the 1/4h (1/2h) rated torque for the H coils of the spindle motor. Note: Only the 1/2h rated torque, not the 1/4h rated torque, may be known for the particular motor. If that is the case, set the 1/2h rated torque.
	Unit	0.1 N·m	
	Effective condition	Instant	
	Applicable program	M	
B173	Cutting force calculation filter for auto-pecking of the cutting load detection type		Set the filter for the data which has been sampled at 7.1-msec intervals. If the entered value is "0", the data actually used will be 4 × 7.1 (msec).
	Unit	7.1 msec	
	Effective condition	Instant	
	Applicable program	M	





Title of display		PARAMETER (MACHINE, MACHINE)													
Address	Meaning		Description												
B176	Linear acceleration/deceleration time constant for thread cutting		Set the special time constant for linear acceleration and deceleration during thread cutting (by G32). Setting range: 1 to 300 (msec) The normal time constant for linear acceleration and deceleration during linear interpolation (by G01) will be applied instead to thread cutting if the setting of this parameter is outside the above-mentioned range.												
	Unit	msec													
	Effective condition	Instant													
	Applicable program	M, E													
B177 to B181	Analog input/output offsets adjustment		This parameter adjusts the analog output offsets value of DIO cards. <table border="1"> <thead> <tr> <th>Parameter</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>B177</td> <td>Analog output channel 1</td> </tr> <tr> <td>B178</td> <td>Analog output channel 2</td> </tr> <tr> <td>B179</td> <td>Analog output channel 3</td> </tr> <tr> <td>B180</td> <td>Analog output channel 4</td> </tr> <tr> <td>B181</td> <td>Analog output channel 5</td> </tr> </tbody> </table> Setting for analog output $= \frac{-8191 \times \text{Measured voltage (V)}}{10.56 \text{ (V)}}$ No setting for No. 2 spindle head	Parameter	Description	B177	Analog output channel 1	B178	Analog output channel 2	B179	Analog output channel 3	B180	Analog output channel 4	B181	Analog output channel 5
	Parameter	Description													
	B177	Analog output channel 1													
	B178	Analog output channel 2													
B179	Analog output channel 3														
B180	Analog output channel 4														
B181	Analog output channel 5														
Unit	—														
Effective condition	Instant														
Applicable program	M, E														




Title of display	PARAMETER (MACHINE, MACHINE)
-------------------------	-------------------------------------

Address	Meaning	Description																		
B182 to B186	Analog output gain	<p>This parameter adjusts the analog output gain levels of DIO cards (such as DX539).</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <thead> <tr> <th>Parameter</th> <th>Description</th> <th>Corresponding card</th> </tr> </thead> <tbody> <tr> <td>B182</td> <td>Analog output channel 1</td> <td>First card</td> </tr> <tr> <td>B183</td> <td>Analog output channel 2</td> <td>Second card</td> </tr> <tr> <td>B184</td> <td>Analog output channel 3</td> <td>Third card</td> </tr> <tr> <td>B185</td> <td>Analog output channel 4</td> <td>Fourth card</td> </tr> <tr> <td>B186</td> <td>Analog output channel 5</td> <td>Fifth card</td> </tr> </tbody> </table> <p>Setting = $\frac{\text{Correct voltage (V)}}{\text{Measured voltage (V)}} \times 4096$</p> <p style="text-align: right;">No setting for No. 2 spindle head</p>	Parameter	Description	Corresponding card	B182	Analog output channel 1	First card	B183	Analog output channel 2	Second card	B184	Analog output channel 3	Third card	B185	Analog output channel 4	Fourth card	B186	Analog output channel 5	Fifth card
	Parameter	Description	Corresponding card																	
	B182	Analog output channel 1	First card																	
	B183	Analog output channel 2	Second card																	
B184	Analog output channel 3	Third card																		
B185	Analog output channel 4	Fourth card																		
B186	Analog output channel 5	Fifth card																		
Unit	—																			
Effective condition	Instant																			
Applicable program	M, E																			
B187 to B191	Analog input offsets adjustment	<p>This parameter adjusts the analog input offsets value of DIO card.</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <thead> <tr> <th>Parameter</th> <th>Description</th> <th>Corresponding card</th> </tr> </thead> <tbody> <tr> <td>B187</td> <td>Analog input channel 1</td> <td>First card</td> </tr> <tr> <td>B188</td> <td>Analog input channel 2</td> <td>Second card</td> </tr> <tr> <td>B189</td> <td>Analog input channel 3</td> <td>Third card</td> </tr> <tr> <td>B190</td> <td>Analog input channel 4</td> <td>Fourth card</td> </tr> <tr> <td>B191</td> <td>Analog input channel 5</td> <td>Fifth card</td> </tr> </tbody> </table> <p>Setting value of analog input = offsetting value</p> <p style="text-align: right;">No setting for No. 2 spindle head</p>	Parameter	Description	Corresponding card	B187	Analog input channel 1	First card	B188	Analog input channel 2	Second card	B189	Analog input channel 3	Third card	B190	Analog input channel 4	Fourth card	B191	Analog input channel 5	Fifth card
	Parameter	Description	Corresponding card																	
	B187	Analog input channel 1	First card																	
	B188	Analog input channel 2	Second card																	
B189	Analog input channel 3	Third card																		
B190	Analog input channel 4	Fourth card																		
B191	Analog input channel 5	Fifth card																		
Unit	—																			
Effective condition	Instant																			
Applicable program	M, E																			



PARAMETER (MACHINE, MACHINE)

Address	Meaning	Description	
B200 B201	Correction value for tool-setting data auto-setting functions (for ↓ tool)	Deviations of actual machine from its theoretical data are corrected during tool-setting data auto-setting. Tool-setting X for the tool = Tool-setting X for reference tool + B200 / A Tool-setting Z for the tool = [Parameter B234 × (-1) × 2 / A] – (Tool-setting Z for reference tool + B201 / A) A = 1000 (mm) or 10000 (in.) B200 : Correction value X, B201 : Correction value Z Note: These parameters are valid only in automatic tool-setting data setting mode for ↓ tools, and they are invalid in other modes.	
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M
B202 B203	Correction value for tool-setting data auto-setting functions (for ← tool)	Deviations of actual machine from its theoretical data are corrected during tool-setting data auto-setting. Tool-setting X for the tool = Tool-setting X for reference tool + B202 / A Tool-setting Z for the tool = [Parameter B234 × (-1) × 2 / A] – (Tool-setting Z for reference tool + B203 / A) A = 1000 (mm) or 10000 (in.) B202 : Correction value X, B203 : Correction value Z Note: These parameters are valid only in automatic tool-setting data setting mode for ← tools, and they are invalid in other modes.	
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M
B204	Turret rotational runout correction value	This parameter corrects the X-axial offset between the axis of the milling spindle and the rotational center of the turret. This parameter is used when executing the automatic TOOL SET data setting function for the B-axis angle index turning function. (Entry of diametral value)  Note: This parameter is valid only when the automatic TOOL SET data setting function for the B-axis angle index turning function is executed, and is not valid in any other case.	
	Unit		0.001 mm or 0.0001 inches
	Effective condition		Instant
	Applicable program		M, E

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B209	Radius of the rear turret (Dual-turret specs. only)		Set the radius of the rear turret.  Reference center position of the turret Turret B209 NM211-00323
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
B210	Width of the rear turret (Dual-turret specs. only)		Set the width of the rear turret.  Turret B210 NM211-00324
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
B211	Rear turret reference position – X-coordinate (Dual-turret specs. only)		Set the distance from the position of the rear turret existing at the machine origin position of the X-axis to the corresponding X-coordinate  B211/2 Workpiece reference point NM211-00325
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
B212	Rear turret reference position – Z-coordinate (Dual-turret specs. only)		Set the distance from the position of the rear turret existing at the machine origin position of the Z-axis to the corresponding Z-coordinate.  B212 Spindle edge NM211-00326
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning	Description	
B213 B216 B219 B222	Mounting position of the tool holder (Dual-turret specs. only) B213 – Type 1 B216 – Type 2 B219 – Type 3 B222 – Type 4	Set the mounting position of the tool holder for the rear turret. If this value is plus, the holder will face sideways. If the value is minus, the holder will face downward. Example: Type 1 	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
B214 B217 B220 B223	X-axial width of the tool holder for the rear turret (Dual-turret specs. only) B214 – Type 1 B217 – Type 2 B220 – Type 3 B223 – Type 4	Set the X-axial width of the tool holder for the rear turret. Example: Type 1 	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
B215 B218 B221 B224	Z-axial width of the tool holder for the rear turret (Dual-turret specs. only) B215 – Type 1 B218 – Type 2 B221 – Type 3 B224 – Type 4	Set the Z-axial width of the tool holder for the rear turret. Example: Type 1 	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	

Title of display **PARAMETER (MACHINE, MACHINE)**



Address	Meaning	Description
B229	Distance between the turrets for opposed-turret mirror image	<p>Set the radial distance from the reference tool position of a reference turret to that of the opposed turret. This parameter becomes invalid if the distance to the opposed turret is designated in the program. Refer to "Opposed-turret mirror image" of the EIA/ISO Programming Manual for further details.</p> 
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	E
		*: The setting unit when the EIA decimal digit adding function is valid
B230 B231 B232	Dimensions of the virtual Y-axis, real X-axis and real Y-axis for inclined Y-axis offsetting	<p>Set the lengths of the sides of a triangle formed according to the particular angle of inclination.</p>  <p>B230: Inclined Y-axis offsetting, virtual Y-axis B231: Inclined Y-axis offsetting, Real X-axis B232: Inclined Y-axis offsetting, Real Y-axis</p>
	Unit	0.001 mm or 0.0001 inches
	Effective condition	Power OFF → ON
	Applicable program	M, E

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning		Description
B233	Pre-interpolation acceleration/deceleration: Target speed		Set the target speed for pre-interpolation acceleration/deceleration.
	Unit	mm/min or 0.1 inches/min	
	Effective condition	Instant	
	Applicable program	M, E	
B234	Distance from reference workpiece zero point to center of milling spindle rotation (absolute value)		B234 = Milling spindle edge rotation radius + Tool setting value of milling spindle edge (absolute value)
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M	
B235	Correction value relating to the workpiece measuring sensor diameter for protrusion width measurement		This value is used for measured value calculation. $Az = #1 - #2 - 2R + \mathbf{B235}$ Az: Measured value #1/#2: Sensor ON positions R: Radius of curvature of the touch sensor nose When WID-OUT and WID-IN are measured, if this parameter is not set (or set to 0), the value of the B66 parameter will be used. *: The setting unit when the EIA decimal digit adding function is valid.
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	
	Effective condition	Instant	
	Applicable program	M	




Title of display **PARAMETER (MACHINE, MACHINE)**

Address	Meaning	Description
B236	Correction value relating to the workpiece measuring sensor diameter for groove width measurement	<p>This value is used for measured value calculation.</p> $Az = \#1 - \#2 + 2R + \mathbf{B236}$ <p>Az: Measured value #1/#2: Sensor ON positions R: Radius of curvature of the touch sensor nose</p> <p>When GRV-OUT and GRV-IN are measured, if this parameter is not set (or set to 0), the value of the B67 parameter will be used.</p> <p>*: The setting unit when the EIA decimal digit adding function is valid.</p>
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	M
B237 to B240	Measurement area for automatic tool offsetting	<div style="text-align: center;"> <p style="text-align: right;">FR: Rapid feed FP: Feedrate set by parameter</p> </div> <p>B237: Measurement area setting for automatic tool offsetting, X-axial direction B238: Measurement area setting for automatic tool offsetting, Z-axial direction B239: Deceleration area setting for automatic tool offsetting, X-axial direction B240: Deceleration area setting for automatic tool offsetting, Z-axial direction</p> <p>*: The setting unit when the EIA decimal digit adding function is valid.</p>
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	E




PARAMETER (MACHINE, MACHINE)

Address	Meaning	Description
B241 to B245	EIA chuck barrier Jaw shape dimensions	<p>Set the jaw shape data for forming chuck barriers using an EIA/ISO program.</p>  <p>B241: EIA chuck barrier, Jaw shape dimension A B242: EIA chuck barrier, Jaw shape dimension B B243: EIA chuck barrier, Jaw shape dimension C B244: EIA chuck barrier, Jaw shape dimension D B245: EIA chuck barrier, Jaw shape dimension E</p>
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	E
B246 to B248	EIA tool barrier Holder dimensions	<p>Set the holder shape data for forming tool barriers using an EIA/ISO program.</p> <p><Holder-under type> Input B246 with a minus sign.</p> <p><Holder-side type> Input B246 with a plus sign.</p>  <p>B246: EIA tool barrier, Holder mounting position B247: EIA tool barrier, X-axial width of the holder B248: EIA tool barrier, Z-axial width of the holder</p>
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	E



Title of display **PARAMETER (MACHINE, MACHINE)**

Address	Meaning	Description	
B249 B250	EIA tool barrier Tool nose position	<p>Set the tool nose position data for forming tool barriers using an EIA/ISO program. The EIA tool barriers become valid at the nose position of the tool. They do not become valid for the tool shape.</p> <p style="text-align: center;"> <Holder-under type> <Holder-side type> Input B249 with a minus sign. Input B250 with a minus sign. </p> <div style="display: flex; justify-content: space-around; align-items: center;">   </div> <p>B249: EIA tool barrier, Z-axial nose position of the tool B250: EIA tool barrier, X-axial nose position of the tool</p>	
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	*: The setting unit when the EIA decimal digit adding function is valid
	Effective condition	Instant	
	Applicable program	E	
B251	EIA chuck barrier Sub-chuck mounting position	<div style="text-align: center;">  <p style="margin-left: 100px;">Machine origin position</p> </div> <p>B251: EIA chuck barrier, Sub-chuck mounting position</p>	
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)	*: The setting unit when the EIA decimal digit adding function is valid
	Effective condition	Instant	
	Applicable program	E	



PARAMETER (MACHINE, MACHINE)

Address	Meaning	Description
B252 to B254	EIA tail barrier Tail dimensions	<p>Set the dimensional data for forming tail barriers using an EIA/ISO program.</p> <p><During tail operation></p>  <p><During tail reversing></p>  <p>B252: EIA tail barrier, Tail extruding length B253: EIA tail barrier, Workpiece length B254: EIA tail barrier, Distance from the machine origin position to the leading edge position during tail reversing</p> <p>*: The setting unit when the EIA decimal digit adding function is valid</p>
	Unit	0.001 mm or 0.0001 in. (* 0.0001 mm or 0.00001 in.)
	Effective condition	Instant
	Applicable program	E
B255	Spindle viscous friction coefficient "cms" for auto-pecking of the cutting load detection type	<p>If the "fms" value depends on revolutions, specify the gradient.</p> <p>Example: If "fms" is 90000 for a "S" value of 5000 If "fms" is 140000 for a "S" value of 10000</p>  <p>Since "cms" = (140000 - 90000) / (10000 - 5000) = 10, set "10" in B255 in the above example.</p>
	Unit	-
	Effective condition	Instant
	Applicable program	M

PARAMETER (MACHINE, MACHINE)



Address	Meaning	Description
<p>B256</p>	<p>Spindle coulombic friction coefficient "fms" for auto-pecking of the cutting load detection type</p>	<p>Set the value where the width of the flat section in the current feedback data matches estimated data.</p> <p>Example: If "fms" is 90000 for a "S" value of 5000 or if "fms" is 140000 for "S" value of 10000, set "C" in B256</p>  <p>Calculate "c" from the linear equation "y = (b/a)x + c". Since "c" = 90000 - (10 × 5000) = 40000, set "40000" in B256 in the above example.</p>
	<p>Unit</p>	<p>—</p>
	<p>Effective condition</p>	<p>Instant</p>
	<p>Applicable program</p>	<p>M</p>
<p>B257 B258</p>	<p>Tool reference position (For INTEGREX machines, this parameter related to ↓ turning tool)</p>	<p>Set the dimensions shown in the diagram below.</p>  <p>B257: X-axial tool reference position (For INTEGREX machines, ↓ turning tool)</p> <p>B258: Z-axial tool reference position (For INTEGREX machines, ↓ turning tool)</p>
	<p>Unit</p>	<p>0.001 mm or 0.0001 inches</p>
	<p>Effective condition</p>	<p>Instant</p>
	<p>Applicable program</p>	<p>M, E</p>

PARAMETER (MACHINE, MACHINE)

Title of display		PARAMETER (MACHINE, MACHINE)		
Address	Meaning	Description		
B259 B260	Tool reference position (For ← turning) Only for INTEGREX machines	Set the dimensions shown in the diagram below.  <p> B259: X-axial tool reference position (← turning tool) B260: Z-axial tool reference position (← turning tool) </p> <p>No setting for No. 2 spindle head.</p>		
		Unit	0.001 mm or 0.0001 inches	
		Effective condition	Instant	
		Applicable program	M, E	
B261 B262	Tool reference position (For ↓ milling) Only for INTEGREX machines	Set the dimensions shown in the diagram below.  <p> B261: X-axial tool reference position (↓ milling tool) B262: Z-axial tool reference position (↓ milling tool) </p> <p>No setting for No. 2 spindle head.</p>		
		Unit	0.001 mm or 0.0001 inches	
		Effective condition	Instant	
		Applicable program	M, E	

Title of display **PARAMETER (MACHINE, MACHINE)**

Address	Meaning	Description	
B263 B264	Tool reference position (For ← milling) Only for INTEGREX machines		
	<p>B263: X-axial tool reference position (← milling tool) B264: Z-axial tool reference position (← milling tool)</p> <p style="text-align: right;">No setting for No. 2 spindle head.</p>		
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
B265 B266	Number of jaws to be used for displaying solids		
	Set the number of jaws of the main spindle or sub-spindle to be used to display solids. B265: Jaws of the No. 1 spindle B266: Jaws of the No. 2 spindle		
	Unit	—	
		Effective condition	Instant
	Applicable program	M	
B267 B268	Jaws offsets for displaying solids		
	Set the jaw offsets for displaying solids. B267: Jaws of the No. 1 spindle B268: Jaws of the No. 2 spindle		
	Unit	0.1 deg	
		Effective condition	Instant
	Applicable program	M	

Title of display		PARAMETER (MACHINE, MACHINE)	
Address	Meaning	Description	
B269 B270	Tool reference position (For → turning tool) Only for INTEGRGX machines	Set the dimensions shown in the diagram below.  <p>The diagram shows a turning tool cutting a cylindrical workpiece. A vertical dashed line represents the workpiece axis, and a horizontal dashed line represents the tool's cutting plane. The 'Reference workpiece origin' is marked at the intersection. The 'Tool reference position' is marked on the tool's cutting edge. Dimension B270 is the distance from the workpiece axis to the tool reference position. Dimension B269 is the distance from the tool reference position to the cutting plane.</p> <p>B269: X-axial tool reference position (For → turning tool) B270: Z-axial tool reference position (For → turning tool)</p>	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	
B271 B272	Tool reference position (For → milling tool) Only for INTEGRGX machines	Set the dimensions shown in the diagram below.  <p>The diagram shows a milling tool cutting a workpiece. A vertical dashed line represents the workpiece axis, and a horizontal dashed line represents the tool's cutting plane. The 'Reference workpiece origin' is marked at the intersection. The 'Tool reference position' is marked on the tool's cutting edge. Dimension B272 is the distance from the workpiece axis to the tool reference position. Dimension B271 is the distance from the tool reference position to the cutting plane.</p> <p>B271: X-axial tool reference position (For → milling tool) B272: Z-axial tool reference position (For → milling tool)</p>	
	Unit	0.001 mm or 0.0001 inches	
	Effective condition	Instant	
	Applicable program	M, E	

3-9 DATA I/O CMT PARAM.

CMT parameter

Parameter setting


The screenshot shows a dialog box titled "PARAM." with three dropdown menus and two buttons. The first dropdown is labeled "1. BAUDRATE:" and is set to "19200". The second dropdown is labeled "2. SAME WNo.:" and is set to "ALARM". The third dropdown is labeled "3. PORT:" and is set to "COM1". At the bottom, there are "OK" and "CANCEL" buttons.

D735S0004E

Classification	DATA I/O	Title of display	CMT PARAM.
----------------	----------	------------------	------------

Meaning		Description								
Baudrate		Baudrate for RS-232C interface Setting <table border="1" style="margin-left: 40px;"> <tr><td>110</td><td>4800</td></tr> <tr><td>300</td><td>9600</td></tr> <tr><td>1200</td><td>19200</td></tr> <tr><td>2400</td><td></td></tr> </table>	110	4800	300	9600	1200	19200	2400	
110	4800									
300	9600									
1200	19200									
2400										
Unit	—									
Effective condition	I/O start									
Applicable program	M, E									
Acceptance of same work number		Set condition for machining program load of same work number Setting Upon acceptance of same work number, alarm will be caused Upon acceptance of same work number, it will be altered.								
Unit	—									
Effective condition	I/O start									
Applicable program	M, E									
Selection of port		Select CMT port Setting <table border="1" style="margin-left: 40px;"> <tr><td>COM1</td><td>CF22 serial channel 3</td></tr> <tr><td>COM2</td><td>CF22 serial channel 4</td></tr> <tr><td>COM3</td><td>CF21 serial channel 1</td></tr> </table>	COM1	CF22 serial channel 3	COM2	CF22 serial channel 4	COM3	CF21 serial channel 1		
COM1	CF22 serial channel 3									
COM2	CF22 serial channel 4									
COM3	CF21 serial channel 1									
Unit	—									
Effective condition	I/O start									
Applicable program	M, E									

Detailed parameter setting



D735S0005E

Classification	DATA I/O	Title of display	CMT PARAM.
Address	Meaning	Description	
CMT25	Selection between whether or not to load for CMT and DNC I/O operation tool data or tool offset data	<div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">7</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">6</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">5</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">4</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">3</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">2</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">1</div> <div style="border: 1px solid black; padding: 2px;">0</div> </div> <ul style="list-style-type: none"> ↖ Selection of loading tool data or tool offset data 0: Alarm 1: Always loaded ↖ Selection of saving program with set up data 0: Saved 1: Not saved ↖ Selection of loading tool data number and suffix 0: Loaded 1: Not loaded ↖ Selection of loading pitch error compensation of machine parameter 0: Loaded 1: Not loaded ↖ Selection of loading jow data 0: Alarm 1: Always loaded 	
	Unit	—	
	Effective condition	I/O start	
	Applicable program	M, E	

3-10 DATA I/O PARAM.

Tape Parameter (TAP)

Parameter setting

The screenshot shows a dialog box titled "PARAM" with the following settings:

- 1. BAUDRATE: 19200
- 2. DATA BIT: 8
- 3. PARITY: NONE
- 4. STOP BIT: 2
- 5. HAND SHAKE: DC CONTROL
- 6. WAIT TIME: 5.0 sec
- 7. FORMAT: ISO
- 8. SAME WNo.: ALARM
- 9. PORT: COM1

Buttons for "OK" and "CANCEL" are visible at the bottom.

D735S0006E

Classification	DATA I/O	Title of display	TAPE PARAM.
-----------------------	-----------------	-------------------------	--------------------

Meaning		Description									
Baudrate		Display baudrate for RS-232C interface Setting <table border="1" style="margin-left: 20px;"> <tr><td>110</td><td>4800</td></tr> <tr><td>300</td><td>9600</td></tr> <tr><td>1200</td><td>19200</td></tr> <tr><td>2400</td><td></td></tr> </table>	110	4800	300	9600	1200	19200	2400		
110	4800										
300	9600										
1200	19200										
2400											
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										
Data bit digits		Display data bit digits of initial setting parameter for RS-232C interface Setting <table border="1" style="margin-left: 20px;"> <tr><td>5</td></tr> <tr><td>6</td></tr> <tr><td>7</td></tr> <tr><td>8</td></tr> </table>	5	6	7	8					
5											
6											
7											
8											
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										


3 PARAMETER

Classification	DATA I/O	Title of display	TAPE PARAM.								
Meaning		Description									
Parity bit		Display parity check of initial setting parameter for RS-232C interface Setting <table border="1" style="margin-left: 20px;"> <tr><td>NONE</td></tr> <tr><td>ODD</td></tr> <tr><td>EVEN</td></tr> </table>		NONE	ODD	EVEN					
NONE											
ODD											
EVEN											
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										
Stop bit digits		Display stop bit digits of initial setting parameter for RS-232C interface Setting <table border="1" style="margin-left: 20px;"> <tr><td>1</td></tr> <tr><td>1.5</td></tr> <tr><td>2</td></tr> </table>		1	1.5	2					
1											
1.5											
2											
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										
Selection of handshaking method		Parameter for selecting handshaking method to control data transfer between NC equipment and I/O units <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>Setting</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>RTS/CTS</td> <td>RTS/CTS for unit connection</td> </tr> <tr> <td>—</td> <td>No control (free transfer)</td> </tr> <tr> <td>DC CONTROL</td> <td>Control codes DC 1 to 4</td> </tr> </tbody> </table>		Setting	Description	RTS/CTS	RTS/CTS for unit connection	—	No control (free transfer)	DC CONTROL	Control codes DC 1 to 4
Setting	Description										
RTS/CTS	RTS/CTS for unit connection										
—	No control (free transfer)										
DC CONTROL	Control codes DC 1 to 4										
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										
Wait time		Waiting time (sec) for response from I/O units set. When the set time has passed after the last response, alarm will be caused.									
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										

Classification	DATA I/O	Title of display	TAPE PARAM.
----------------	----------	------------------	-------------

Meaning		Description									
Output format		Change the output selection of punching on paper tape. Setting <table border="1" style="margin-left: 40px;"> <tr> <td style="text-align: center;">ISO</td> <td>Punch on paper tape by ISO code</td> </tr> <tr> <td style="text-align: center;">EIA</td> <td>Punch on paper tape by EIA code</td> </tr> <tr> <td style="text-align: center;">ASCII</td> <td>Punch on paper tape by ASCII code</td> </tr> </table>		ISO	Punch on paper tape by ISO code	EIA	Punch on paper tape by EIA code	ASCII	Punch on paper tape by ASCII code		
ISO	Punch on paper tape by ISO code										
EIA	Punch on paper tape by EIA code										
ASCII	Punch on paper tape by ASCII code										
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										
Acceptance of same work number		Set the condition on machining program load of same work number. Setting Upon acceptance of same work number, alarm will be caused Upon acceptance of same work number, it will be altered.									
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										
Selection of port		Select tape port Setting <table border="1" style="margin-left: 40px;"> <tr> <td style="text-align: center;">COM1</td> <td>CF22 serial channel 3</td> </tr> <tr> <td style="text-align: center;">COM2</td> <td>CF22 serial channel 4</td> </tr> <tr> <td style="text-align: center;">COM3</td> <td style="text-align: center;">—</td> </tr> <tr> <td style="text-align: center;">COM4</td> <td style="text-align: center;">—</td> </tr> </table>		COM1	CF22 serial channel 3	COM2	CF22 serial channel 4	COM3	—	COM4	—
COM1	CF22 serial channel 3										
COM2	CF22 serial channel 4										
COM3	—										
COM4	—										
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										

Detailed parameter setting








D735S0007E

Classification	DATA I/O	Title of display	TAPE PARAM.
----------------	----------	------------------	-------------

Address	Meaning	Description														
TAP1	Terminator type	<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: center;">Setting</th> <th style="text-align: center;">Terminator</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td>No terminator</td> </tr> <tr> <td style="text-align: center;">1</td> <td>EOB or EOR</td> </tr> <tr> <td style="text-align: center;">2</td> <td>EOB only</td> </tr> <tr> <td style="text-align: center;">3</td> <td>EOR only</td> </tr> <tr> <td style="text-align: center;">4</td> <td>Any one character (character specified by TAP2)</td> </tr> <tr> <td style="text-align: center;">5</td> <td>Two characters of your choice (First Character specified by TAP2, second character fixed to 0)</td> </tr> </tbody> </table>	Setting	Terminator	0	No terminator	1	EOB or EOR	2	EOB only	3	EOR only	4	Any one character (character specified by TAP2)	5	Two characters of your choice (First Character specified by TAP2 , second character fixed to 0)
	Setting		Terminator													
	0		No terminator													
	1		EOB or EOR													
2	EOB only															
3	EOR only															
4	Any one character (character specified by TAP2)															
5	Two characters of your choice (First Character specified by TAP2 , second character fixed to 0)															
Unit	—															
Effective condition	I/O start															
Applicable program	M, E															
TAP2	Terminator code 1	<p>This parameter can be used only when the terminator type (I10) is set to 4 or 5 only. The terminator type, however, must be set to 1 to allow paper tape processing. 0 must be used for this parameter in such cases.</p>														
	Unit		—													
	Effective condition		I/O start													
	Applicable program		M, E													

Classification	DATA I/O	Title of display	TAPE PARAM.
----------------	----------	------------------	-------------

Address	Meaning	Description																																												
TAP4	CR code output to paper tape punch	Selection between whether or not CR code should be added before LF (the end of block) 0: CR code not added 1: CR code added																																												
	Unit	—																																												
	Effective condition	I/O start																																												
	Applicable program	M, E																																												
TAP5	Selection of DC code parity	Parameter for selection between whether or not parity should be added for DC code output <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>Setting</th> <th></th> <th colspan="10">Hole position patterns of DC 3 code</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>NO</td> <td></td><td></td><td></td><td></td><td></td><td></td><td>●</td><td>•</td><td></td><td></td><td></td><td></td><td>●</td><td>●</td> </tr> <tr> <td>1</td> <td>YES</td> <td>●</td><td></td><td></td><td></td><td>●</td><td>•</td><td></td><td></td><td></td><td></td><td></td><td></td><td>●</td><td>●</td> </tr> </tbody> </table>	Setting		Hole position patterns of DC 3 code										0	NO							●	•					●	●	1	YES	●				●	•							●	●
	Setting		Hole position patterns of DC 3 code																																											
	0	NO							●	•					●	●																														
	1	YES	●				●	•							●	●																														
Unit	—	Note: This parameter is used only when handshaking method is set to "DEC control".																																												
Effective condition	I/O start																																													
Applicable program	M, E																																													
TAP6	DC code output on feed control	Select between whether or not DC 2 and DC4 code outputs should be made to feed section where paper tape punch (PTP) start and end are commanded Example: 																																												
	Unit	—																																												
	Effective condition	I/O start																																												
	Applicable program	M, E																																												
		<table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>Setting</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>No output of DC2 or DC4</td> </tr> <tr> <td>1</td> <td>Output of DC2 only</td> </tr> <tr> <td>2</td> <td>Output of DC4 only</td> </tr> <tr> <td>3</td> <td>Output of both DC2 and DC4</td> </tr> </tbody> </table>	Setting	Description	0	No output of DC2 or DC4	1	Output of DC2 only	2	Output of DC4 only	3	Output of both DC2 and DC4																																		
Setting	Description																																													
0	No output of DC2 or DC4																																													
1	Output of DC2 only																																													
2	Output of DC4 only																																													
3	Output of both DC2 and DC4																																													
		Note: This parameter is valid only when handshaking method is set to "DC control".																																												

Classification		DATA I/O	Title of display	TAPE PARAM.
Address	Meaning		Description	
	TAP9	Perforation pattern for "[" code on paper tape reader/puncher for EIA		<p>Specifying perforation pattern for loading or punching "[" by EIA code on paper tape reader/punch.</p> <p>Count hole position by 8 units of binary digits, and convert the binary number into a decimal number.</p> <p>Example:</p>  <p>Setting value ↓ $(0 \times 2^7) + (1 \times 2^6) + (0 \times 2^5) + (0 \times 2^4) + (1 \times 2^3) + (1 \times 2^2) + (0 \times 2^1) + (0 \times 2^0) = 76$ MPL068</p>
		Unit	—	
		Effective condition	I/O start	
Applicable program		M, E		
TAP10	Perforation pattern for "]" code on paper tape reader/puncher for EIA		<p>Specifying perforation pattern for loading or punching "]" by EIA code on paper tape reader/punch.</p> <p>Count hole positions by 8 units of binary digits (1/10), and convert the binary number into a decimal number.</p> <p>Example:</p>  <p>Setting value ↓ $(0 \times 2^7) + (0 \times 2^6) + (0 \times 2^5) + (0 \times 2^4) + (1 \times 2^3) + (1 \times 2^2) + (0 \times 2^1) + (1 \times 2^0) = 13$ MPL069</p>	
	Unit	—		
	Effective condition	I/O start		
	Applicable program	M, E		
TAP11	Perforation pattern for "#" code on paper tape reader/puncher for EIA		<p>Specifying perforation pattern for loading or punching "#" by EIA code on paper tape reader/punch.</p> <p>Count hole positions by 8 units of binary digits, and convert the binary number into a decimal number.</p> <p>Example:</p>  <p>Setting value ↓ $(0 \times 2^7) + (1 \times 2^6) + (1 \times 2^5) + (0 \times 2^4) + (1 \times 2^3) + (1 \times 2^2) + (0 \times 2^1) + (1 \times 2^0) = 109$ MPL070</p>	
	Unit	—		
	Effective condition	I/O start		
	Applicable program	M, E		
TAP12	Perforation pattern for "*" code on paper reader/puncher for EIA		<p>Specifying perforation pattern for loading or punching "*" by EIA code on paper tape reader/punch.</p> <p>Count hole positions by 8 units of binary digits (1/0), and convert the binary number into a decimal number.</p> <p>Example:</p>  <p>Setting value ↓ $(0 \times 2^7) + (1 \times 2^6) + (1 \times 2^5) + (1 \times 2^4) + (1 \times 2^3) + (0 \times 2^2) + (1 \times 2^1) + (0 \times 2^0) = 122$ MPL071</p>	
	Unit	—		
	Effective condition	I/O start		
	Applicable program	M, E		



Classification	DATA I/O	Title of display	TAPE PARAM.
-----------------------	-----------------	-------------------------	--------------------

Address	Meaning	Description
TAP13	Perforation pattern for "=" code on paper reader/puncher for EIA	Specifying perforation pattern for loading or punching "=" by EIA code on paper tape reader/punch Count hole positions by 8 units of binary digits (1/0), and convert the binary number into a decimal number. Example: $(0 \times 2^7) + (1 \times 2^6) + (0 \times 2^5) + (1 \times 2^4) + (1 \times 2^3) + (0 \times 2^2) + (1 \times 2^1) + (1 \times 2^0) = 91$ MPL072
	Unit	—
	Effective condition	I/O start
	Applicable program	M, E
TAP14	Perforation pattern for ":" code on paper tape reader/puncher for EIA	Specifying perforation pattern for loading or punching ":" by EIA code on paper tape reader/punch Count hole positions by 8 units of binary digits (1/0), and convert the binary number into a decimal number. Example: $(0 \times 2^7) + (1 \times 2^6) + (0 \times 2^5) + (0 \times 2^4) + (0 \times 2^3) + (1 \times 2^2) + (1 \times 2^1) + (0 \times 2^0) = 70$ MPL073
	Unit	—
	Effective condition	I/O start
	Applicable program	M, E
TAP25	Selection of parity V check	<div style="border: 1px solid black; padding: 2px; display: inline-block;">7 6 5 4 3 2 1 0</div> Specifies whether a parity V check is to be conducted during paper tape reading. 0: No 1: Yes
	Unit	—
	Effective condition	I/O start
	Applicable program	M, E

Classification	DATA I/O	Title of display	TAPE PARAM.
----------------	----------	------------------	-------------

Address	Meaning	Description	
TAP26	Selection of program name tape input/output Selection of setup information punching Selection of RTS/CTS control when "DC control" is selected	<p>Specifies whether the program name input/output function is to be made valid during tape reading or punching. 0: Invalid 1: Valid</p> <p>Specifies whether to punch the setup information in the TAPE mode. 0: Valid 1: Invalid</p> <p>Specifies whether RTS/CTS control is to be conducted when "DC control" is selected in the TAPE hand-shaking scheme. 0: Yes (Conducting both DC control and RTS/CTS control) 1: No (Conducting only DC control)</p> <p>Note: For connection to a microdisk unit, set up "0" at bit 7.</p>	
		Unit	—
		Effective condition	I/O start
		Applicable program	M, E
TAP27	Selection of PTP program end code	<p>(0: YES 1: NO)</p> <p>Selection between whether or not O or : code of next program should be used as program end for loading a number of programs</p> <p>M199 } M198 } When these codes are loaded, M99 } select whether or not use them as M30 } PTP program M02 }</p> <p>Character conversion input/output using an extension tape 0 : In the case where the character data* is in ASCII codes. The character data will be input/output as it is 1 : In the case where the character data* is not in ASCII codes (special code, etc.). The character data will be converted into character codes prior to input/output.</p> <p>* Denotes workpiece materials, tool materials, tool names and jaw names.</p>	
		Unit	—
		Effective condition	I/O start
		Applicable program	M, E

Classification	DATA I/O	Title of display	TAPE PARAM.
----------------	----------	------------------	-------------

Address	Meaning	Description								
TAP28	Protocol B function selection	<div style="display: flex; align-items: flex-start;"> <div style="margin-right: 10px;"> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td></tr> </table> </div> <div> <ul style="list-style-type: none"> ↑ { Start code <li style="margin-left: 20px;">0: DC1 <li style="margin-left: 20px;">1: BEL ↑ { DC3 output on completion <li style="margin-left: 20px;">0: No output <li style="margin-left: 20px;">1: Output ↑ { DC1 output after NAK or SYN <li style="margin-left: 20px;">0: No output <li style="margin-left: 20px;">1: Output ↑ { NC alarm (NAK) output <li style="margin-left: 20px;">0: No output <li style="margin-left: 20px;">1: Output ↑ { NC reset (SYN) output <li style="margin-left: 20px;">0: No output <li style="margin-left: 20px;">1: Output ↑ { Data code <li style="margin-left: 20px;">0: ASCII <li style="margin-left: 20px;">1: ISO <p style="margin-left: 40px;">(normal setting: 00111010)</p> </div> </div>	7	6	5	4	3	2	1	0
	7	6	5	4	3	2	1	0		
	Unit	—								
	Effective condition	I/O start								
Applicable program	E									
TAP29	Number of space characters (SP) between work No. and program on paper tape puncher	<p>Specifying number of space characters (SP) between O number and program head in punching the program on paper tape</p> <div style="text-align: center;">  <p>TAP29 (Number of characters) MPL079</p> </div>								
	Unit	—								
	Effective condition	I/O start								
	Applicable program	M, E								
TAP30	Number of space characters (SP) between programs on paper tape puncher	<p>Specifying number of space characters (SP) between different programs in punching programs on paper tape</p> <div style="text-align: center;">  <p>Program ← TAP30 (Number of characters) → Program</p> </div>								
	Unit	—								
	Effective condition	I/O start								
	Applicable program	M, E								

Classification	DATA I/O	Title of display	TAPE PARAM.
----------------	----------	------------------	-------------

Address	Meaning	Description
TAP31	Number of leading and trailing feed characters of paper tape puncher	<p>Specifying number of NULL (feed) characters punched on leading and trailing portions of paper tape.</p> <div style="text-align: center;"> </div>
	Unit	—
	Effective condition	I/O start
	Applicable program	M, E

MPL078

3-11 DATA I/O DNC PARAM.

DNC Parameter (DNC)

Parameter setting

PARAM. dialog box showing the following settings:

- 1. BAUDRATE: 19200
- 2. DATA BIT: 8
- 3. PARITY: NONE
- 4. STOP BIT: 2
- 5. WAIT TIME: 5.0 sec
- 6. SAME WNo.: ALARM
- 7. PORT: COM1

Buttons: OK, CANCEL

D735S0008E

Classification	DATA I/O	Title of display	DNC PARAM.
-----------------------	-----------------	-------------------------	-------------------

Meaning		Description									
Baudrate		Baudrate for RS-232C interface Setting <table border="1" style="margin-left: 40px;"> <tr><td>110</td><td>4800</td></tr> <tr><td>300</td><td>9600</td></tr> <tr><td>1200</td><td>19200</td></tr> <tr><td>2400</td><td></td></tr> </table>		110	4800	300	9600	1200	19200	2400	
110	4800										
300	9600										
1200	19200										
2400											
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										
Data bit digits		Display data bit digits of initial setting parameter for RS-232C interface Setting <table border="1" style="margin-left: 40px;"> <tr><td>5</td></tr> <tr><td>6</td></tr> <tr><td>7</td></tr> <tr><td>8</td></tr> </table>		5	6	7	8				
5											
6											
7											
8											
Unit	—										
Effective condition	I/O start										
Applicable program	M, E										


3 PARAMETER

Classification	DATA I/O	Title of display	DNC PARAM.			
Meaning		Description				
Parity bit		Display parity check of initial setting parameter for RS-232C interface Setting <table border="1" style="margin-left: 20px;"> <tr><td>NONE</td></tr> <tr><td>ODD</td></tr> <tr><td>EVEN</td></tr> </table>		NONE	ODD	EVEN
NONE						
ODD						
EVEN						
Unit	—					
Effective condition	I/O start					
Applicable program	M, E					
Stop bit digits		Display stop bit digits of initial setting parameter for RS-232C interface Setting <table border="1" style="margin-left: 20px;"> <tr><td>1</td></tr> <tr><td>1.5</td></tr> <tr><td>2</td></tr> </table>		1	1.5	2
1						
1.5						
2						
Unit	—					
Effective condition	I/O start					
Applicable program	M, E					
Wait time		Waiting time (sec) for response from I/O units set. When the set time has passed after the last response, alarm will be caused.				
Unit	—					
Effective condition	I/O start					
Applicable program	M, E					
Acceptance of same work number		Set the condition on machining program load of same work number. Setting Upon acceptance of same work number, alarm will be caused Upon acceptance of same work number, it will be altered.				
Unit	—					
Effective condition	I/O start					
Applicable program	M, E					

Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------

Meaning		Description	
Selection of port		Select DNC port	
		Setting	
		COM1	CF22 serial channel 3
		COM2	CF22 serial channel 4
COM3	CF21 serial channel 1		
Unit	—		
Effective condition	I/O start		
Applicable program	M, E		

Detailed parameter setting





D735S0009E



Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------

Address	Meaning	Description
DNC9	Transmission retry frequency for DNC file transfer	<p>Setting how often transmission to be repeated after * or TEXT has been transferred without @ signaled back from HOST within waiting time set for parameter "wait time duration"</p> <p style="text-align: right;">Transmission repeated until @ signaled back.</p> <p style="text-align: right;">MPL081</p>
	Unit	Times
	Effective condition	I/O start
	Applicable program	M, E
DNC10	Transmission retry frequency for DNC command message transfer	<p>Setting how often return to initial status to be repeated after @ has been transferred without TEXT or EOT signaled back from HOST within waiting time set for parameter "wait time duration"</p> <p style="text-align: right;">Return to initial status repeated until TEXT or EOT signaled back.</p> <p style="text-align: right;">MPL082</p>
	Unit	Times
	Effective condition	I/O start
	Applicable program	M, E
		After repetition as often as the set number of times alarm will be caused.

Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------

Address	Meaning	Description	
DNC11	Transmission retry frequency for DNC command message transfer	Setting how often to be repeated when command message has not been correctly transferred. It is almost same as the case of parameters DNC9 and DNC10 , there is however, a difference in what are transferred, that is command message for DNC11 while file for DNC9 and DNC10 .	
	Unit		Times
	Effective condition		I/O start
	Applicable program		M, E
DNC12	@ waiting time for DNC transfer	Setting of waiting time until NC equipment receives @ signaled from HOST after transmission of * or TEXT  <p style="text-align: right; margin-right: 20px;">MPL083</p>	
	Unit		0.1 sec
	Effective condition		I/O start
	Applicable program		M, E
DNC13	TEXT, * waiting time for DNC transfer	Setting waiting time until NC equipment receives TEXT or * signaled from HOST after transmission of @ or reception of EOT  <p style="text-align: right; margin-right: 20px;">MPL084</p>	
	Unit		0.1 sec
	Effective condition		I/O start
	Applicable program		M, E

Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------



Address	Meaning		Description
DNC14	EOT waiting time for DNC transfer		Setting of waiting time until NC equipment receives EOT signaled from HOST after transmission of @  <p style="text-align: right;">MPL085</p>
	Unit	0.1 sec	
	Effective condition	I/O start	
	Applicable program	M, E	
			Note: Refer to parameter DNC10
DNC15	Stop time after acceptance of ! for DNC transfer		Setting of stop time until NC equipment transmits * after reception of ! from HOST  <p style="text-align: right;">MPL086</p>
	Unit	0.1 sec	
	Effective condition	I/O start	
	Applicable program	M, E	
			* will be transferred of the end of duration DNC15 after reception of "1" from HOST.
DNC16	Reset time after digital out for DNC transfer		Setting of time until internal resetting of NC equipment after reception of digital out command
	Unit	0.1 sec	
	Effective condition	I/O start	
	Applicable program	M, E	

Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------

Address	Meaning	Description
DNC17	Acceptance → stop time for DNC transfer	<p>Setting of time data below</p> <div style="display: flex; justify-content: space-around;"> <div style="width: 45%;"> <p><NC equipment signaling> NC equipment stop time after reception of @ from HOST until transmission of TEXT or EOT</p> </div> <div style="width: 45%;"> <p><NC equipment receiving> NC equipment stop time after reception of * or TEXT until transmission of @</p> </div> </div> <p style="text-align: right;">MPL087</p>
	Unit	0.01 sec
	Effective condition	I/O start
	Applicable program	M, E
DNC18	Command response message waiting time for DNC transfer	<p>Setting of waiting time until NC equipment receives * of command response message signaled from HOST after transmission of EOT of command message</p> <p style="text-align: right;">MPL088</p>
	Unit	0.1 sec
	Effective condition	I/O start
	Applicable program	M, E

3 PARAMETER

Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------

Address	Meaning	Description	
DNC19	Machine No. for DNC transfer	Each machine is given its own No. for DNC operation wherein, tool data and parameters are controlled on the HOST side by these data.	
	Unit		
	Effective condition		I/O start
	Applicable program		M, E
DNC21	Stop time between EOT acceptance and * transmission for DNC transfer (duration after acceptance upto signaling)	Setting of stop time until NC equipment signals * of next message after reception of EOT from HOST  <p style="text-align: right;">MPL089</p>	
	Unit		0.01 sec
	Effective condition		I/O start
	Applicable program		M, E
DNC22	Stop time between EOT transmission and * transmission for DNC transfer	Setting of stop time until NC equipment signals * of next message after transmission of EOT  <p style="text-align: right;">MPL090</p>	
	Unit		0.01 sec
	Effective condition		I/O start
	Applicable program		M, E

Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------

Address	Meaning	Description
DNC25	Selection between whether or not to load for DNC I/O operation tool data or tool offset data	
		Selection between whether or not to load for DNC I/O operation tool data or tool offset data
		Selection between whether or not to load for DNC I/O operation tool data number and suffix
		Selection of loading pitch error compensation of machine parameter
Unit	—	
Effective condition	I/O start	
Applicable program	M, E	
DNC26	Selection of functions for DNC I/O	
		Selection between whether or not to work No. search for the program should be executed
		Selection between whether or not alarm caused in DNC should be indicated
		Selection between whether or not loading programs of stored work No. on NC equipment should be inhibited
Unit	—	
Effective condition	I/O start	
Applicable program	M, E	

3 PARAMETER

Classification	DATA I/O	Title of display	DNC PARAM.
----------------	----------	------------------	------------

Address	Meaning	Description	
DNC29	DNC physical error detection repeat times	<p>Set the number of times that detection of physical errors during waiting for the first message (ENQ) from the host is to be repeated to identify whether the particular error is due to host power off/on actions or hardware errors.</p> <p>After physical errors have occurred, if redetection within the setting of this parameter succeeds, those errors will be regarded as not being due to hardware errors and DNC communication will continue. A DNC alarm will result if redetection within the setting of the parameter does not succeed.</p> <p>DNC29 = 0 Default (5 times)</p> <p>DNC29 = 1 bis 255 Number of times of repetition after the occurrence of physical errors</p>	
	Unit		Times
	Effective condition		I/O start
	Applicable program		M, E

3-12 DATA I/O EXTENDED PARAMETER

Extended parameter

Detailed parameter setting

PARAM.

DPR1	<input type="text" value="0"/>	DPR9	<input type="text" value="0"/>	IDD1	<input type="text" value="0"/>	IDD9	<input type="text" value="0"/>
DPR2	<input type="text" value="0"/>	DPR10	<input type="text" value="0"/>	IDD2	<input type="text" value="0"/>	IDD10	<input type="text" value="0"/>
DPR3	<input type="text" value="0"/>	DPR11	<input type="text" value="0"/>	IDD3	<input type="text" value="0"/>	IDD11	<input type="text" value="0"/>
DPR4	<input type="text" value="0"/>	DPR12	<input type="text" value="0"/>	IDD4	<input type="text" value="0"/>	IDD12	<input type="text" value="0"/>
DPR5	<input type="text" value="0"/>	DPR13	<input type="text" value="0"/>	IDD5	<input type="text" value="0"/>	IDD13	<input type="text" value="0"/>
DPR6	<input type="text" value="0"/>	DPR14	<input type="text" value="0"/>	IDD6	<input type="text" value="0"/>	IDD14	<input type="text" value="0"/>
DPR7	<input type="text" value="0"/>	DPR15	<input type="text" value="0"/>	IDD7	<input type="text" value="0"/>	IDD15	<input type="text" value="0"/>
DPR8	<input type="text" value="0"/>	DPR16	<input type="text" value="0"/>	IDD8	<input type="text" value="0"/>	IDD16	<input type="text" value="0"/>

DATA:

D735S0051E

Classification	DATA I/O	Title of display	EXTENDED PARAMETER
-----------------------	-----------------	-------------------------	---------------------------

Address	Meaning	Description																				
DPR1	Baud rate	Baud rate for RS-232C interface <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Setting</th> <th>Baud rate</th> <th>Set values</th> <th>Baud rate</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>110</td> <td>4</td> <td>4800</td> </tr> <tr> <td>1</td> <td>300</td> <td>5</td> <td>9600</td> </tr> <tr> <td>2</td> <td>1200</td> <td>6</td> <td>19200</td> </tr> <tr> <td>3</td> <td>2400</td> <td></td> <td></td> </tr> </tbody> </table>	Setting	Baud rate	Set values	Baud rate	0	110	4	4800	1	300	5	9600	2	1200	6	19200	3	2400		
	Setting		Baud rate	Set values	Baud rate																	
	0		110	4	4800																	
	1		300	5	9600																	
2	1200	6	19200																			
3	2400																					
<table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 50%; text-align: center;">110</td><td style="width: 50%; text-align: center;">4800</td></tr><tr><td style="text-align: center;">300</td><td style="text-align: center;">9600</td></tr><tr><td style="text-align: center;">1200</td><td style="text-align: center;">19200</td></tr><tr><td style="text-align: center;">2400</td><td></td></tr></table>	110	4800	300	9600	1200	19200	2400															
110	4800																					
300	9600																					
1200	19200																					
2400																						
Unit	—																					
Effective condition	I/O start																					
Applicable program	M, E																					
DPR2	Stop bit	Number of stop bits (parameter for RS-232C interface initialization) <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Setting</th> <th>Stop bit</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1</td> </tr> <tr> <td>1</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>2</td> </tr> </tbody> </table>	Setting	Stop bit	0	1	1	1.5	2	2												
	Setting		Stop bit																			
	0		1																			
	1		1.5																			
2	2																					
<table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 50%; text-align: center;">1</td><td style="width: 50%;"></td></tr><tr><td style="text-align: center;">1.5</td><td></td></tr><tr><td style="text-align: center;">2</td><td></td></tr></table>	1		1.5		2																	
1																						
1.5																						
2																						
Unit	—																					
Effective condition	I/O start																					
Applicable program	M, E																					

Classification	DATA I/O	Title of display	EXTENDED PARAMETER
----------------	----------	------------------	--------------------

Address	Meaning	Description												
DPR3	Parity bit	Parity check (parameter for RS-232C interface initialization) <table border="1" style="margin: 10px auto;"> <thead> <tr> <th>Setting</th> <th>Paity bit</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>None</td> </tr> <tr> <td>1</td> <td>Odd</td> </tr> <tr> <td>2</td> <td>Even</td> </tr> </tbody> </table>	Setting	Paity bit	0	None	1	Odd	2	Even				
	Setting		Paity bit											
	0		None											
	1		Odd											
2	Even													
Unit	—													
Effective condition	I/O Start													
Applicable program	M, E													
DPR4	Data bit	Number of data bits (parameter for RS-232C interface initialization) <table border="1" style="margin: 10px auto;"> <thead> <tr> <th>Setting</th> <th>Data bit</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>8</td> </tr> <tr> <td>1</td> <td>7</td> </tr> </tbody> </table>	Setting	Data bit	0	8	1	7						
	Setting		Data bit											
	0		8											
	1		7											
Unit	—													
Effective condition	I/O Start													
Applicable program	M, E													
DPR5 to DPR8	—	Not used												
	Unit		—											
	Effective condition		—											
	Applicable program		—											
DPR9	Method of handshaking	This parameter is used to select the method of handshaking to control the state of data transfer between the NC system and connected instrument. <table border="1" style="margin: 10px auto;"> <thead> <tr> <th>Setting</th> <th>Method</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>None</td> <td>No control</td> </tr> <tr> <td>1</td> <td>DC control</td> <td>Complies with control code DC1 through DC4</td> </tr> <tr> <td>2</td> <td>RTS/CTS</td> <td>Complies with device connection RTS/CTS.</td> </tr> </tbody> </table>	Setting	Method	Description	0	None	No control	1	DC control	Complies with control code DC1 through DC4	2	RTS/CTS	Complies with device connection RTS/CTS.
	Setting		Method	Description										
	0		None	No control										
	1		DC control	Complies with control code DC1 through DC4										
2	RTS/CTS	Complies with device connection RTS/CTS.												
Unit	—													
Effective condition	I/O start													
Applicable program	M, E													

Classification	DATA I/O	Title of display	EXTENDED PARAMETER
----------------	----------	------------------	--------------------

Address	Meaning	Description									
DPR13	Output format	Selection of output code <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>Setting</th> <th>Format</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">ISO</td> <td>Output in ISO code</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">EIA</td> <td>Output in EIA code</td> </tr> </tbody> </table>	Setting	Format	Description	0	ISO	Output in ISO code	1	EIA	Output in EIA code
	Setting	Format	Description								
	0	ISO	Output in ISO code								
	1	EIA	Output in EIA code								
Unit	—										
Effective condition	I/O Start										
Applicable program	M, E										
DPR14	Port selection	Port selection <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>Setting</th> <th>Port</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">COM1</td> <td>CF22 serial ch3</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">COM2</td> <td>CF22 serial ch4</td> </tr> </tbody> </table>	Setting	Port	Description	0	COM1	CF22 serial ch3	1	COM2	CF22 serial ch4
	Setting	Port	Description								
	0	COM1	CF22 serial ch3								
	1	COM2	CF22 serial ch4								
Unit	—										
Effective condition	I/O Start										
Applicable program	M, E										
DPR15	Number of characters in feed section	Number of characters in NULL (feed) Example: <div style="display: flex; justify-content: center; align-items: center; gap: 10px;"> <div style="text-align: center;"> DPR15 characters <table border="1" style="border-collapse: collapse;"> <tr><td style="width: 20px; height: 15px;"></td></tr> </table> </div> <div style="text-align: center;"> DPR15 characters <table border="1" style="border-collapse: collapse;"> <tr><td style="width: 20px; height: 15px;"></td></tr> </table> </div> </div> <div style="display: flex; justify-content: center; align-items: center; gap: 5px; margin-top: 5px;"> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr><td style="width: 30px; height: 20px;">Feed</td></tr> </table> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr><td style="width: 30px; height: 20px;">EOR</td></tr> </table> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr><td style="width: 60px; height: 20px;">(Significant information)</td></tr> </table> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr><td style="width: 30px; height: 20px;">EOR</td></tr> </table> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr><td style="width: 30px; height: 20px;">Feed</td></tr> </table> </div>			Feed	EOR	(Significant information)	EOR	Feed		
	Feed										
EOR											
(Significant information)											
EOR											
Feed											
Unit	—										
Effective condition	1 character										
Applicable program	M, E										
DPR16	—	Not used									
	Unit	—									
	Effective condition	—									
	Applicable program	—									